

ASS. RES. BY:

REF:

21012334/kgyb

C

ASSIGNMENT

From: _____ Date: _____

Estimated Cost: _____

CO/RES/TP/RES/CO/RES/EVA/INV/INV

To inspect Vehicle No: _____

at Workshop no: Cheng Hoe

Insured: _____

Policy No: _____

Claims No: 266420

Sum Insured: _____

Excess: _____

(Client's Record)

Make of Veh: _____

(Policy Condition)

Remark: The veh had commenced its repair at the time of inspection.



Est. or Market Value: \$63k

IDAC Accident Report Consistent?: Yes or No

GIA / PR Seen: Consistent?: Yes or No

Est. Repairs: 04 days Res.: Yes or No

Lum Sum: 1-B1/1% 3 Val.: Yes or No

CA / REV / REP. / 24 HRS

Vehicle: IN / OUT

Date: _____ Person Contacted: _____

Veh No: SLL 2695B Yr Regn: 02, 17

Type: M/Car / M/Cycle / Bus / Van / Lorry / Taxi / Prime Mover /

Truck / Trailer or Wagon

Make: Mazda 5 cc: 1998

Colour: M. Gray A/C: Insured / Std / NI / NA

Sp. Reading: 75125 T/Radio: Insured / Std / NI / NA

Eng No: _____

C No: _____

Gen. Cond: Good / Fair / Poor / Burnt

Steering: Inoper / Jammed / Leaked / Burnt or

Brake: Inoper / Jammed / Leaked / Burnt or

Mod: NII / S/Rlm / STD / Rlm or

Tyre Size: F: 205/55R16

R: _____

BS / DUN / EXNOVA / GY / FS / LIZA / MIC / OHTSU / PIR / SUMI /

TOYO / YOKO or

Front

Rear

R/Sal: 8 mm

R/Sal: 8 mm

L/Sal: 8 mm

L/Sal: 8 mm

D.O.A. 4/12/21

D.O.I. 6/12/2021

Survey held at

4-50pm

Des. of Damages: Frt / Rear / QS / NS / UIC / Rooftop or

The UIC / Chassis frame / Body Structure affected due to collision.

Date / Time Action / Instruction

Wksp said I.B.I. no 2nd parts available

09/12/21 @ 3.48pm revised to Christina Wong via Merimen.

815 @ 4003-04 Cash Cred to 612, 13%

Date/Time, File Pass to?

: Prell. Report

Days Of Repair: 4

1)

: Final Report

Resurvey No. of Trip: 2

Date/Time, File Return to?

Survey Fee:

2)

Add Fee: : Site Insp (\$ _____)

Transportation:

: Interview (\$ _____)

Fuel

: Tech Invs (\$ _____)

Others

: Weekend (\$ _____)

TOTAL

Report Format: MER-TP

Lump Sum / I.B.I. (\$ 4003.04)

Cheng Hoe Motor Pte Ltd

Blk 1019, Yishun Industrial Park A #01-374/382, Singapore 768761
 TEL: 67556142 (YIS) FAX: 67557719 (YIS) Email: chmotor@singnet.com.sg
 GST:201001158E RCB NO:201001158E

SLL2695B
TP/MSIG

M/S : MSIG INSURANCE (S) PTE LTD (SGX)
 16 RAFFLES QUAY
 #24-01 HONG LEONG BUILDING
 SINGAPORE 048581

TEL: 68277660 **FAX:** 62257402
ATTN: Motor Claim Department *Not Authorised*

WS Ref: TP/MSIG *Phony B9 pain*
Claim Type: Third Party
Accident Date: 04/12/2021 *4 days*
TP Veh Reg No: SMS8221Y

Estimate No: ES2191170/YISHUN
Date: 06 Dec 2021
Policy No: 5112357057-02
Veh Reg No: SLL2695B
Make/Model: MAZDA MAZDA 5 5-DOOR WAGON 2.0L
Chassis No: JM6CW1071G0124782
Engine No: PE10404277
Reg. Date: 20/02/2017

Estimate Repair Cost to Vehicle No :SLL2695B

PAGE:1/1

Description	U/Price	Quantity	List Price S\$	Amount S\$
List Price				
1 REAR BUMPER	981.00	1 PC	<i>Bu</i> 981.00	✓
2 REAR BUMPER CLIPS	5.90	6 PCS	<i>na</i> 35.40	
3 REAR TAILGATE	1,637.00	1 PC	<i>By</i> 1,637.00	
4 TAILGATE EMBLEM (5)	38.00	1 PC	<i>na</i> 38.00	
5 TAILGATE EMBLEM (MAZDA)	38.60	1 PC	<i>na</i> 38.60	
6 TAILGATE EMBLEM (SKYACTIV)	53.30	1 PC	<i>na</i> 53.30	
7 TAILGATE INNER LOCK	265.00	1 PC	<i>R</i> 265.00	✓
			3,048.30	
		Less 20%	609.66	2,438.64
Cost Plus				
8 REMOVE AND REFIX REAR WINDSCREEN GLASS	120.00	1 LA	120.00	✓
			120.00	120.00
Special Net				
9 REVERSE SENSOR	200.00	1 SET	<i>Shat</i> 200.00	✓
10 REAR BUMPER BODY PROTECTOR	90.00	1 PC	<i>na</i> 90.00	✓
11 REAR WINDSCREEN GLASS GUM	40.00	1 PC	<i>na</i> 40.00	
			330.00	330.00
Labour				
12 REMOVE & REFIX REAR BUMPER ASSY, TAILGATE, REAR TOP SPOILER, LOCK ASSY, REFLECTORS, TO KNOCK & REPAIR REAR END PANEL AND REALIGN THE SAME	600.00	1 LA	600.00	450
13 PUTTY & RESPRAY ON REAR END PANEL, TAILGATE, REAR BUMPER	700.00	1 LA	700.00	450
14 REMOVE & REFIX REVERSE CAMERA AND RESET SYSTEM	30.00	1 LA	30.00	✓
15 RUSTPROOFING	30.00	1 LA	30.00	✓
			1,360.00	1,360.00
			Total	S\$ 4,248.64
			Add GST @ 7%	297.40
			Total Amount Payable	S\$ 4,546.04

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer
 Signature:
 Date:

For Cheng Hoe Motor Pte Ltd

[Signature]
 AUTHORISED SIGNATURE

Att: Kenneth
Cheng Hoe Motor Pte Ltd

Blk 1019, Yishun Industrial Park A #01-374/382, Singapore 768761
 TEL: 67556142 (YIS) FAX: 67557719 (YIS) Email: chmotor@singnet.com.sg
 GST:201001158E RCB NO:201001158E

SLL2695B
 TP/MSIG

M/S : MSIG INSURANCE (S) PTE LTD (SGX)
 16 RAFFLES QUAY
 #24-01 HONG LEONG BUILDING
 SINGAPORE 048581

TEL: 68277660 FAX: 62257402
 ATTN: Motor Claim Department

Estimate No: **ES2191170/YISHUN**
 Date: 06 Dec 2021
 Policy No: 5112357057-02
 Veh Reg No: **SLL2695B**
 Make/Model: MAZDA MAZDA 5 5-DOOR WAGON 2.0L
 Chassis No: JM6CW1071G0124782
 Engine No: PE10404277
 Reg. Date: 20/02/2017

WS Ref: TP/MSIG
 Claim Type: Third Party
 Accident Date: 04/12/2021
 TP Veh Reg No: SMS8221Y

Not Notified
Repair by pain
4 days

Estimate Repair Cost to Vehicle No :SLL2695B

PAGE:1/1

Description	U/Price	Quantity	List Price	Amount
			SS	SS
List Price				
1 REAR BUMPER	981.00	1 PC	981.00	✓
2 REAR BUMPER CLIPS	5.90	6 PCS	35.40	✓
3 REAR TAILGATE	1,637.00	1 PC	1,637.00	✓
4 TAILGATE EMBLEM (S)	38.00	1 PC	38.00	✓
5 TAILGATE EMBLEM (MAZDA)	38.60	1 PC	38.60	✓
6 TAILGATE EMBLEM (SKYACTIV)	53.30	1 PC	53.30	✓
7 TAILGATE INNER LOCK	265.00	1 PC	265.00	7 X
			3,048.30	
		Less 20%	609.66	2,438.64
Cost Plus				
8 REMOVE AND REFIX REAR WINDSCREEN GLASS	120.00	1 LA	120.00	✓
			120.00	120.00
Special Net				
9 REVERSE SENSOR	200.00	1 SET	200.00	2 ✓
10 REAR BUMPER BODY PROTECTOR	90.00	1 PC	90.00	✓
11 REAR WINDSCREEN GLASS GUM	40.00	1 PC	40.00	✓
			330.00	330.00
Labour				
12 REMOVE & REFIX REAR BUMPER ASSY, TAILGATE, REAR TOP SPOILER, LOCK ASSY, REFLECTORS, TO KNOCK & REPAIR REAR END PANEL AND REALIGN THE SAME	600.00	1 LA	600.00	450
13 PUTTY & RESPRAY ON REAR END PANEL, TAILGATE, REAR BUMPER	700.00	1 LA	700.00	450
14 REMOVE & REFIX REVERSE CAMERA AND RESET SYSTEM	30.00	1 LA	30.00	✓
15 RUSTPROOFING	30.00	1 LA	30.00	✓
			1,360.00	1,360.00
		Total	SS 4,248.64	
		Add GST @ 7%	297.40	
		Total Amount Payable	SS 4,546.04	

Supp. 1pc tail gate outer garnish \$458
20% 91.60
\$366.40

Parts \$2783.30
Add supp \$458
\$3241.30
20% 648.26
\$2593.04
330.00
1080
\$4003.04

For Cheng Hoe Motor Pte Ltd

[Signature]
 AUTHORISED SIGNATURE

4615.04

Cheng Hoe Motor Pte Ltd

Blk 1019, Yishun Industrial Park A #01-374/382, Singapore 768761
TEL: 67556142 (YIS) FAX: 67557719 (YIS) Email: chmotor@singnet.com.sg
GST:201001158E RCB NO:201001158E

Suppl

M/S : MSIG INSURANCE (S) PTE LTD (SGX)
16 RAFFLES QUAY
#24-01 HONG LEONG BUILDING
SINGAPORE 048581
TEL: 68277660 FAX: 62257402
ATTN: Motor Claim Department

Estimate No: ES2191170/YISHUN
Date: 08 Dec 2021
Policy No: 5112357057-02
Veh Reg No: SLL2695B
Make/Model: MAZDA MAZDA 5 5-
DOOR WAGON 2.0L
Chassis No: JM6CW1071G0124782
Engine No: PE10404277
Reg. Date: 20/02/2017

WS Ref: TP/MSIG
Claim Type: Third Party
Accident Date: 04/12/2021
TP Veh Reg No: SMS8221Y

Estimate Repair Cost to Vehicle No :SLL2695B

Description	U/Price	Quantity	List Price	Amount
			<u>S\$</u>	<u>S\$</u>
Supplementary 1				
List Price				
1 TAILGATE OUTER GARNISH	458.00	1 PC	458.00 ✓	
			458.00	
	Less 20%		91.60	366.40
			Total	S\$ 366.40
			GST Amount	S\$ 25.65
			Total Amount Payable	S\$ 392.05

For Cheng Hoe Motor Pte Ltd


AUTHORISED SIGNATURE