



CYCLE & CARRIAGE

CYCLE & CARRIAGE AUTOMOTIVE PTE LIMITED
PANDAN GARDENS CUSTOMER SERVICE CENTRE
209 Pandan Gardens Singapore 609339 Tel: 65684555 Fax: 65691056



Co Reg No : 1977014696

ESTIMATE

GST Reg No : MR-8500111-X

Invoice Name & Address	Owner Name & Vehicle Info
AIG Asia Pacific Insurance Pte. Ltd. MOTOR CLAIM DEPT 78 SHENTON WAY #09-16 AIG BUILDING SINGAPORE 079120 Contact No 6419 1892	Cust No/Name KCV11519/HOE SIN KONG PAUL (HE XINGGUANG) Reg No/Reg Date SJQ8783M / 21/06/201 Date In/Mileage / 0 Chassis No JMAXTGK1WJZ004746 Engine No 4B40GB4565 Make/Model MIT/ECLIPSE CROSS 1.5 T/C SPORTS SU Colour/Trim P26 ORIENT RED / BK BLACK

Account No	Terms	Date/Time Printed	CSE	Operator	WIP No
KAX00008	Credit	06/12/2021/ 14:00	TLE	261 / Edwin Caina	18286
Description of Goods / Services		Qty	Unit Price	Disc%	Amount
E PNT88000	RENEW FR BUMPER, RHF FENDER & FR SUPPORT PNL REPAIR BONNET & RHF DOOR	1 1/2 x 480			675 2250.00
E PNT98000	RSPRAY FR BUMPER, RHF FENDER, FR SUPPORT PNL BONNET & RHF DOOR	4 x 350			1400 2400.00
E PNT88000	REMOVE & REFIT AC COND & RADIATOR				9 100.00 X
M SUNDRY	TOP UP AC GAS				9 80.00 X
A 54900099	CHECK WIRING ELECTRICAL SYSTEM & ADJUST HEADLAMP AIM				30.00
A 10028901	TO CARRY OUT DIAGNOSTIC CHECK ON ELECTRONIC CONTROL SYSTEM				120.00
M SUNDRY	SUPPLY FR NUMBER PLATE WITH CASING				50.00
E PNT88000	REMOVE & REFIT FR PARKING SENSOR				80.00
M SUNDRY	APPLY ANTI CORROSION ON AFFECTED AREAS				40.00
M SUNDRY	SUPPLY BODY PNL SEALANT				40 60.00
M SUNDRY	Sundries				20.00
M HEADLAMP ASSY, RH	BR	1.00	1986.00	23.00	1529.22
M FACE, FR BUMPER	BR	1.00	718.00	23.00	552.86
M COVER, FR BUMPER	BR (Black)	1.00	382.00	23.00	294.14
M EXTENSION, FR BUMPER	CUT (Silver)	1.00	318.00	23.00	244.86
M BRKT, F/BMPR T/SIG LAMP, RH	? X nn	1.00	17.00	23.00	13.09
M GARNISH, FR BUMPER SIDE	BR (RH chane)	1.00	214.00	23.00	164.78
M GARNISH, FR BUMPER SIDE	? X nn	1.00	77.00	23.00	59.29
M BAR, FR BUMPER GUARD	? X nn	1.00	100.00	23.00	77.00
M REINFORCEMENT, FR BUMPER	? X nn	1.00	555.00	23.00	427.35

Confirm & accepted by

Authorized signatory and company stamp

Validity of this estimate is 14 days from date of quote. This is a computer generated document, no signature is required. Estimated costs quoted are excluding GST. We would mention that the above estimate is based on our initial inspection and does not include any additional parts or labour which may be required after repair work has commenced. Occasionally worn or damaged parts are discovered after work has started and needed for repairs or replacement. However, should this occur, we would advise you. Please be informed that a deposit of 50% of the above estimate is payable before commencement of the work. Payment for this may be made in cash, credit card or cheque. You must also agree to pay full amount for renewal of the windscreen in the event of inadvertent breakage in the course of renewing the rubber seal or other repair requiring the removal of the windscreen.



CYCLE & CARRIAGE

CYCLE & CARRIAGE AUTOMOTIVE PTE LIMITED
PANDAN GARDENS CUSTOMER SERVICE CENTRE

209 Pandan Gardens Singapore 609339 Tel: 65684555 Fax: 65691056



Co Reg No : 197701469G

ESTIMATE

GST Reg No : MR-8500111-X

Invoice Name & Address	Owner Name & Vehicle Info
AIG Asia Pacific Insurance Pte. Ltd. MOTOR CLAIM DEPT 78 SHENTON WAY #09-16 AIG BUILDING SINGAPORE 079120 Contact No 6419 1892	Cust No/Name KCV11519/HOE SIN KONG PAUL (HE XINGGUANG) Reg No/Reg Date SJQ8783M / 21/06/201 Date In/Mileage / 0 Chassis No JMAXTGK1WJZ004746 Engine No 4B40GB4565 Make/Model MIT/ECLIPSE CROSS 1.5 T/C SPORTS SU Colour/Trim P26 ORIENT RED / BK BLACK

Account No	Terms	Date/Time Printed	CSE	Operator	WIP No
KAX00008	Credit	06/12/2021/ 14:00	TLE	261 / Edwin Caina	18286
Description of Goods / Services		Qty	Unit Price	Disc%	Amount
M REINF,FR BUMPER SIDE,RH	BT	1.00	35.00	23.00	26.95
M REINFORCEMENT,FR BUMPER	BT	1.00	236.00	23.00	181.72
M BRACKET,FR BUMPER SIDE,RH	X NO	1.00	18.00	23.00	13.86
M STAY,FR BUMPER	X NO	2.00	9.00	23.00	13.86
M COVER,HEADLAMP WASHER HOLE	MIS	1.00	53.00	23.00	40.81
M ACTUATOR,HEADLAMP WASHER,R	BR	1.00	113.00	23.00	87.01
M HOSE ASSY,HEADLAMP WASHER	X NO	1.00	185.00	23.00	142.45
M FENDER,FR RH	NO	1.00	541.00	23.00	416.57
M MOULDING,FR WHEEL ARCH,RH	X NO	1.00	151.00	23.00	116.27
M GRILLE ASSY,RADIATOR	CRA	1.00	486.00	23.00	374.22
M COVER,FR BUMPER GRILLE	X NO	1.00	302.00	23.00	232.54
M PANEL,AIR GUIDE	X NO	1.00	32.00	23.00	24.64
M PANEL,AIR GUIDE SIDE,RH	X NO	1.00	82.00	23.00	63.14
M PNL,HEADLAMP SUPT,UPR RH	X NO	1.00	59.00	23.00	45.43
M PANEL,HEADLAMP SUPPORT,UPR	BT	1.00	172.00	23.00	132.44
M LLC 4L	X NO	1.00	26.00	23.00	20.02

SURVEYOR NAME: Steve (LKK)SURVEYOR SIGNATURE: 6/12/21, 2.30pmDATE: 06-12-21REMARKS: Excess - 1P/PMy Ref sy
5 days

LKK Auto Consultants hence notify

- Confirm & accepted by
- To resurvey before/after spray painting
 - To display damaged part(s) during resurvey
 - Parts prices are subject to confirmation
 - Third party survey is on a "Without Prejudice" basis
 - No illegal modification(s) is allowed
 - Supplementary item(s) must be resurveyed and

Authorized signatory and company stamp

7% GST on **Nett** 10,524.52
10524.52 736.72
Total Payable 11,261.24

Validity of this estimate is 14 days from date of quote. This is a computer generated document, no signature is required. Estimated costs quoted are excluding GST. We would mention that the above estimate is based on our initial inspection and does not include any additional parts or labour which may be required after repair work has commenced. Occasionally worn or damaged parts are discovered after work has started and needed for repairs or replacement. However, should this occur, we would advise you. Please be informed that a deposit of 50% of the above estimate is payable before commencement of the work. Payment for this may be made in cash, credit card or cheque. You must also agree to pay full amount for renewal of the windscreen in the event of inadvertent breakage in the course of renewing the rubber seal or other repair requiring the removal of the windscreen.