



Exceptional Journeys

Surveyor : STEVE LKK
Claim : AIG OD
DOA : 05.12.2021
Emailed : 22.12.2021, 9.55am
Date survey : 06.12.2021

VEHICLE NO : SJQ 8783 M
MODEL : MIT ECLIPSE CROSS 1.5 SPORTS SUNROO
WIP : 18286

Material	:	\$	4,083.31
Labour	:	\$	3,255.00
Sub-Total	:	\$	7,338.31
	:		-
Less Excess	:	\$	400.00
Total	:	\$	6,938.31
GST 7%	:	\$	485.68
Grand Total	:	\$	7,423.99
Finalise By/Date	:	LOI / 22/12/2021	

☒ REVERT BACK WITHIN 7 DAYS,
OTHERWISE WILL PROCEED WITH INVOICING

☐ SURVEYOR'S REPORT REQUIRED

☐ REPAIR TOOK 0 WORKING DAYS + 0 Days (0) Weekends
+ 0 Days (0) Public holiday
TOTAL DAYS REPAIR TOOK = 0

☐ TP claim _____

☐ Claim GIA / LTA fee _____

☐ Claim Loss of ☐ Use / ☐ Rental

☐ Claim Medical Fee / Others _____

☐ Third Party Report - _____



CYCLE & CARRIAGE

CYCLE & CARRIAGE AUTOMOTIVE PTE LIMITED

PANDAN GARDENS CUSTOMER SERVICE CENTRE

209 Pandan Gardens Singapore 609339 Tel: 65684555 Fax: 65691056



PRO-FORMA INVOICE

Co Reg No : 197701469G

THIS IS NOT AN OFFICIAL TAX INVOICE

GST Reg No : MR-8500111-X

Invoice Name & Address	Owner Name & Vehicle Info	
AIG Asia Pacific Insurance Pte. Ltd. MOTOR CLAIM DEPT 78 SHENTON WAY #09-16 AIG BUILDING SINGAPORE 079120 Contact No 6419 1892 08/12/2021	Cust No/Name	KCV11519/HOE SIN KONG PAUL (HE XINGGUANG)
	Reg No/Reg Date	SJQ8783M / 21/06/2019
	Date In/Mileage	08/12/2021/ 33708
	Chassis/Package	JMAXTGK1WJZ004746
	Engine No	4B40GB4565
	Make/Model	MIT/ECLIPSE CROSS 1.5 T/C SPORTS SUNROOF
	Colour/Trim	P26 ORIENT RED / BK BLACK

Account No	Terms	Date/Time Printed	CSE	Operator	WIP No			
KAX00008	Credit	21/12/2021/ 16:58	BLE	260 / AiTing	18286			
Description of Goods / Services					Qty	Unit Price	Disc%	Amount
E PNT88000 REPLACE DAMAGED PARTS, REPLACE FRONT BUMPER, RH FRONT FENDER, REPAIR RH FRONT DOOR, AND ALL OTHER AFFECTED AREAS, ADJUST AND ALIGN BODY GAPS ALIGNMENT TO THE SAME								✓ 675.00
E PNT98000 RESPRAY ON FRONT BUMPER, RH FRONT FENDER, RH FRONT DOOR, AND ALL OTHER AFFECTED AREAS TO THE SAME								✓ 1400.00
A 54900099 CHECK WIRING & ELECTRICAL SYSTEM & ADJUST HEADLAMP AIM								✓ 30.00
A 10028901 CONDUCT DIAGNOSTIC CHECK USING MUT TESTER AND CLEAR TROUBLE CODE								✓ 120.00
E PNT88000 REMOVE & REINSTALL FRONT PARKING SENSOR TO FACILITATE REPAIR								✓ 80.00
M SUNDRY APPLY ANTI CORROSION ON AFFECTED AREAS								✓ 40.00
M SUNDRY SUPPLY BODY PANEL SEALANT								✓ 40.00
M SUNDRY SUNDRIES								✓ 20.00
S SPECIALISTJOB SUPPLY & REPLACE FRONT LICENSE PLATE WITH FRAME								✓ 50.00
E PNT88000 REPLACE FRONT RE-INFORCEMENT & FRONT SUPPORT UPPER PANEL → Supp.								450.00
E PNT98000 REPLACE FRONT RE-INFORCEMENT & FRONT SUPPORT UPPER PANEL → Supp.								350.00
X EXC EXCESS								-400.00
X	HEADLAMP ASSY,RH				1.00	✓ 1986.00	23.00	1529.22
X	FACE,FR BUMPER				1.00	✓ 718.00	23.00	552.86
X	COVER,FR BUMPER				1.00	✓ 382.00	23.00	294.14
X	EXTENSION,FR BUMPER				1.00	✓ 318.00	23.00	244.86
X	GARNISH,FR BUMPER SIDE				1.00	✓ 214.00	23.00	164.78
X	REINF,FR BUMPER SIDE,RH				1.00	✓ 35.00	23.00	26.95

This is not an official tax invoice.
 This is a computer generated document, no signature is required.



CYCLE & CARRIAGE

CYCLE & CARRIAGE AUTOMOTIVE PTE LIMITED
PANDAN GARDENS CUSTOMER SERVICE CENTRE

209 Pandan Gardens Singapore 609339 Tel: 65684555 Fax: 65691056

**PRO-FORMA INVOICE**

Co Reg No : 197701469G

THIS IS NOT AN OFFICIAL TAX INVOICE

GST Reg No : MR-8500111-X

Invoice Name & Address	Owner Name & Vehicle Info														
AIG Asia Pacific Insurance Pte. Ltd. MOTOR CLAIM DEPT 78 SHENTON WAY #09-16 AIG BUILDING SINGAPORE 079120 Contact No 6419 1892 08/12/2021	<table> <tr> <td>Cust No/Name</td><td>KCV11519/HOE SIN KONG PAUL (HE XINGGUANG)</td></tr> <tr> <td>Reg No/Reg Date</td><td>SJQ8783M / 21/06/2019</td></tr> <tr> <td>Date In/Mileage</td><td>08/12/2021/ 33708</td></tr> <tr> <td>Chassis/Package</td><td>JMAXTGK1WJZ004746</td></tr> <tr> <td>Engine No</td><td>4B40GB4565</td></tr> <tr> <td>Make/Model</td><td>MIT/ECLIPSE CROSS 1.5 T/C SPORTS SUNROOF</td></tr> <tr> <td>Colour/Trim</td><td>P26 ORIENT RED / BK BLACK</td></tr> </table>	Cust No/Name	KCV11519/HOE SIN KONG PAUL (HE XINGGUANG)	Reg No/Reg Date	SJQ8783M / 21/06/2019	Date In/Mileage	08/12/2021/ 33708	Chassis/Package	JMAXTGK1WJZ004746	Engine No	4B40GB4565	Make/Model	MIT/ECLIPSE CROSS 1.5 T/C SPORTS SUNROOF	Colour/Trim	P26 ORIENT RED / BK BLACK
Cust No/Name	KCV11519/HOE SIN KONG PAUL (HE XINGGUANG)														
Reg No/Reg Date	SJQ8783M / 21/06/2019														
Date In/Mileage	08/12/2021/ 33708														
Chassis/Package	JMAXTGK1WJZ004746														
Engine No	4B40GB4565														
Make/Model	MIT/ECLIPSE CROSS 1.5 T/C SPORTS SUNROOF														
Colour/Trim	P26 ORIENT RED / BK BLACK														

Account No	Terms	Date/Time Printed	CSE	Operator	WIP No
KAX00008	Credit	21/12/2021/ 16:58	BLE	260 / AiTing	18286

Description of Goods / Services	Qty	Unit Price	Disc%	Amount
X REINFORCEMENT,FR BUMPER	1.00	236.00	23.00	181.72
X COVER,HEADLAMP WASHER HOLE	1.00	53.00	23.00	40.81
X ACTUATOR,HEADLAMP WASHER,R	1.00	113.00	23.00	87.01
X FENDER,FR RH	1.00	541.00	23.00	416.57
X GRILLE ASSY,RADIATOR	1.00	486.00	23.00	374.22
X PANEL,HEADLAMP SUPPORT,UPR	1.00	172.00	23.00	132.44
X REINF,FR BUMPER SIDE,LH	1.00	35.00	23.00	26.95
X GROMMET,FR BUMPER	1.00	4.00	23.00	3.08
X CLIP,ENG ROOM COVER	5.00	2.00	23.00	7.70

Z TEXT

AIG OD CLAIM

DOA : 05.12.21

SURVEYOR STEVE LKK 06.12.21

POLICY NO : 1900111250-01 REPAIR 05 DAYS

Pro Forma

Guarantee Your Warranty, Maintain with Cycle & Carriage!

Parts	4,083.31	Nett	6,938.31
Labour	3,105.00	7% GST on	485.68
Standard Menu	0.00		
Specialist Job	50.00	Total Payable	7,423.99
Diagnostics Job	0.00		
Sundry/Others	-300.00		
Total(w/o GST)	6,938.31		

This is not an official tax invoice.
This is a computer generated document, no signature is required.



Exceptional Journeys

INSURANCE CO. : AIG

Supplementary Parts For Registration No.: SJQ 8783 M

<u>Materials</u>		<u>Cost (\$)</u>
1	Reinf, Fr bumper side, LH	35.00 - BT
2	Grommet	4.00 - nec
3	Clips (x5)	10.00 - nlc
Total		49.00
Less 23%		11.27
Total Materials		37.73
<u>Labour</u>		<u>Cost (\$)</u>
1	Replace front re-inforcement & front support upper panel	450.00 -
2	Replace front re-inforcement & front support upper panel spray	350.00 -
Total Labour		800.00
Taxable Amount		837.73
7% GST		58.64
Grand total		<u><u>896.37</u></u>

Thank You.

Yours faithfully
CYCLE & CARRIAGE AUTOMOTIVE PTE LTD

LOI AI TING
SENIOR OFFICER - ADMIN
TEL: 6568 4556 / 6568 4501
FAX : 6567 5258 / 6565 1240

WIP: 18286

(ADDITIONAL PARTS CHANGE)

	DATE	TAKEN BY
PHOTO BEFORE PAINT		
PHOTO AFTER PAINT		
PHOTO OF MOUNT TO CELLETTE BENCH		
REMOVE AND INSTALL ENGINE		
REMOVE AND INSTALL DASHBAORD		
REMOVE & INSTALL FUEL TANK		
PHOTO UNDERCARRIAGE PARTS		

MODEL: ECLIPSE

SURVEYOR: STEVE

Ref No: SJG87837

After using MOT-3x not work to Base oil

by Base oil

Job Done by G.C. Test drive

All DTCs

2021.12.17

Setting	
Item	Information
M.U.T.-3 Version	SEW21091-00
V.C.I. Version	B179
Vehicle Information	GK1W 2018MY

All DTCs

	</								