



## LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Affiliated to Federation Internationale Des Experts En Automobile			
LONPAC INSURANCE BHD 300 BEACH ROAD #17-04/07 THE CONCOURSESINGAPORE 199555		Ref: CS3/LPC21010946/Uvf3e2-1 Date: 13/12/2021 Code: LPC2	
<b>1. Policy Particulars :- THIRD PARTY CLAIM</b>			
Insured Veh.	XE 1745S	Veh. Inspected	SDZ 1010E
Policy No.		Coverage (\$)	0.00
Claim No.	21/21/21/VC00/025080	Excess (\$)	0.00
Assign From	KENNY LIM	Assign Date	07/12/2021
<b>2. Vehicle Particulars &amp; Condition</b>			
Make & Model	TOYOTA HARRIER ELEGANCE (A)	c.c	1986
Engine No.	HIDDEN	Year of Reg.	2016
Chassis No.	ZSU600080726	Colour	WHITE
Odometer	244095 KM	Steering	IN ORDER
Brakes	IN ORDER	Modification	SPORTS RIM
General	GOOD		
<b>3. Conditions of Tyres</b>			
	Size	Make	Balance
R/H Front Tyre	245/45Z R19	DUNLOP	7 mm
L/H Front Tyre	245/45Z R19	DUNLOP	7 mm
R/H Rear Tyre	245/45Z R19	DUNLOP	7 mm
L/H Rear Tyre	245/45Z R19	DUNLOP	7 mm
<b>4. Description of Damages</b>			
THE VEHICLE SUSTAINED DAMAGES AT THE O/S FRONT AND O/S REAR PORTION. DAMAGES SEE DETAILS.			
<b>5. General Information</b>			
Accident Date	22/10/2021	Inspection Date	27/10/2021
Survey held at	BLUWEL AUTOMOTIVE SERVICE PL BLK 1 KAKI BUKIT AVE 6 #01-28/53/55/56 (MAIN OFFICE) SINGAPORE 417883		
<b>5a. Remarks</b>			
A)THE INSPECTION WAS CONDUCTED ON A"WITHOUT PREJUDICE" BASIS. B)IN ACCORDANCE TO YOUR INSTRUCTIONS, WE HAVE NOT AUTHORISED REPAIRS.			
<b>5b. Estimate Days of Repair</b>			
ESTIMATED NORMAL PERIOD FOR REPAIR:		10 Working Days	