

ASS REC. BY: Marcus

REF: CC4/2PC 21012357/Uea3

ASSIGNMENT

From: _____ Date: _____
 Estimated Cost: _____
OD / TP / WS / TP RES / OD RES / EVA / INV / MV
 To Inspect Vehicle No: GP 1199L
 at Workshop m/s Auto Union
 of _____
 Insured: YN 8022P
 Policy No. _____
 Claims No. _____
 Sum Insured: _____ Excess: _____
 (Client's Record)
 Make of Veh: _____

(Policy Condition)

Remark: The veh had commenced its
 repair at the time of inspection.



Bal. or Market Value: \$31k.
 IDAC Accident Report: Consistent? : Yes or No
 GIA / PR Seen: Consistent? : Yes or No
 Est. Repairs: 6 days Res.: Yes or No
 Lum Sum: 1.31 % 3 Val.: Yes or No

CA / REV / REP. / 24 HRS

Vehicle: IN / OUT

Date: _____ Person Contacted: LTA 18192

Veh No: GP 1199L Yr Regn: 28/10/15
 Type: M.Car / M.Cycle / Bus / Van / Lorry / Taxi / Prime Mover /
Truck / Trailer or CM /
 Make: NISSAN NV350 c.c. 2488
 Colour: Silver A/C: Insured / Std / NI / NA
 Sp.Reading: 134252 T/Radio: Insured / Std / NI / NA
 Eng/No: _____
 C/No: JN1MC2E2680025245
 Gen. Cond: Good / Fair / Poor / Burnt
 Steering: Order / Jammed / Leaked / Burnt or
 Brake: Order / Jammed / Leaked / Burnt or
 Modi: NH / S/Rim / STD A/Rim or

Tyre Size: F: 195 R15
 R: _____

BS / DUN / EXNOVA / GY / FS / LIZA / MIC / OHTSU / PIR / SUMI /
 TOYO / YOKO

Front Rear
 R/Bal. 7 mm R/Bal. 7 mm
 L/Bal. 7 mm L/Bal. 7 mm
 D.O.A. 6/11/21 D.O.I. 7/11/21
 Survey held at _____

Des. of Damages: Frt / Rear / O/S / N/S / U/C / Rooftop or
Rear & Rear w/steer
 The U/C / Chassis frame / Body Structure affected due to collision.

Date / Time Action / Instruction Rep 8500Shattered

28/11/21 P/P \$6386.49 informed Elmer
All parts is s/n item

Date/Time, File Pass to?

☐

Preli. Report

Days Of Repair:

1)

☐

Final Report

Resurvey No. of Trip:

Date/Time, File Return to?

2)

Add Fee: ☐ Site Insp (\$)

Survey Fee:

Transportation:

Report Format :

Lump Sum / I.B.I. (\$))

☐ Interview (\$)☐ Tech. Invs (\$)☐ Weekend (\$)

) \$ + RS \$

) Photos

) Others

TOTAL

AUTOLUTION INDUSTRIAL PTE LTD
19 UBI ROAD 4
SINGAPORE 408623
TEL: 6490 9866 FAX: 68467483

AUTOLUTION INDUSTRIAL PTE. LTD.

ESTIMATE : ACCIDENT/BODY REPAIRS

REFERENCE : INS/1C/EA/0420/21
DATE : 06-DEC-2021

LONPAC INSURANCE BHD
300 BEACH RD
#17-04/07 THE CONOURSE
S(199555)
TEL : 62507388
FAX : 62962706
MOTOR CLAIMS DEPT

OWNER'S NAME : COMMAND - AIR PTE LTD
ADDRESS : 237 UBI AVE 4
INTREPID WAREHOUSE COMPLEX
S(408820)
TELEPHONE NO : 94783076

TYPE OF CLAIM : DIRECT SETTLEMENT / THIRD PARTY CLAIM
POLICY NO : D21MTPCVD002493
VEHICLE NO : GP1199L
MODEL CODE : MVL2R0RE26KW3GBR-D
MODEL/YEAR : NISSAN NV350 PANEL VAN MT EURO 5
ENGINE NO : YD25382579A
CHASSIS NO : JN1MC2E26Z0005245
MILEAGE : 134252 KM
DATE IN : 06/12/2021
LIABILITY : 0.00
EXCESS CLAUSE : 0.00
ESTIMATE BY : ELMER
ACCIDENT DATE : 06/12/2021

Not Authorized
Allen Marcus
7/1/21
take photo & security.
6 days.
p/p \$ 6386.49

-9645 0084 elmer@tanchoy.com

KKK Auto Consultants hence notify
the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and
is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date:

ESTIMATED LABOUR CHARGES FOR ACCIDENT VEHICLE REGN NO GP1199L

S/NO JOB CODE	NATURE OF JOB	ESTIMATED CHARGES	SURVEYOR'S RECOMMENDATION
1 ZZ/001	LABOR CHARGES TO REPAIR TRUNKFLOOR, INNER END PANEL BOTH INNER PANEL RR FENDER, RENEW OUTER END PANEL	2730.00	4500 1520
2 ZZ/002	RR BUMPER AND TAIL GATE		
3 ZZ/003	CHARGES TO SPRAY PAINTING TRUNKFLOOR, INNER/OUTER END PANEL, BOTH RR FENDER INNER EXTENSION, RR BUMPER	2000.00	1100
4 ZZ/004	AND TAIL GATE		
5 ZZ/005	REMOVE AND INSTALL TAILGATE MECHANISM	80.00	✓
6 ZZ/006	RENEW REAR WINDSCREEN GLASS	240.00	✓ 180
7 ZZ/007	RENEW REAR WINDSCREEN GLASS SOLAR FILM	150.00	X
8 ZZ/008	RENEW REVERSE SENSOR	110.00	55
9 ZZ/009	RENEW BOTH RR COMB LAMP AND CHECK WIRING SYSTEM RR	48.00	✓
10 ZZ/011	COMPUTER CHECK DIAGNOSIS	120.00	✓
11 ZZ/10	SUPPLY REAR LICENSE PLATE		
	TOTAL LABOUR CHARGES	5478.00	

3102

MATERIAL LIST FOR ACCIDENT VEHICLE REGN NO GP1199L

		DAMAGED PARTS & PRICES			S/NETT REMARKS
S/NO	PARTS DESCRIPTION	PARTS NUMBER	NETT	LIST	
1	CENTER TOP 3RD BRAKE LAMP	26590-3XA0A	11	237.50	X
2	RR WINDOW WIPER ARM COVER	28782-1FC0A	11	13.10	X
3	RR WINDOW WIPER BLADE	28790-3XA0A	11	26.90	X
4	RR WINDOW WIPER ARM	28781-3XA0A	11	75.20	X
5	REAR WIPER MOTOR	28710-3XA0A	11	242.00	X
6	REAR TOP UNDER MIRROR	96340-3XA0A	11	112.00	X
7	LH RR COMB LAMP	26555-3XA0B	SEA	224.80	X
8	RH RR COMB LAMP	26550-3XA0B	CN	224.80	136
9	SUNDRIES	NPN	11	100.00	X
10	EMBLEM-BACK DOOR URVAN	90892-3XY0A	11	64.90	39.27
11	EMBLEM-BACK DOOR NV350	90890-3XY0A	11	110.00	66.55
12	EMBLEM-REAR NISSAN	90890-0X00A	11	64.90	39.27
13	INNER CENTER BRACKET RR BUMPER	85040-VZ00A	R	171.90	X
14	CLIP RR BUMPER @ SGD \$1.30 EACH	01553-05323	11	13.00	7.90
15	REAR BUMPER	85022-3XA0A	2-3	667.20	403.66
16	REAR LICENCE PLATE	RLP	11	60.00	X
17	70KM/H STICKER	70KM/H	11	15.00	✓
18	TAILGATE LOCK	90500-3XA0A	2-3	287.10	173.70
19	STRIKER-TAIL GATE	90570-VW000	11	34.80	X
20	SENSOR-REVERSE	SENSOR	11	250.00	70.00
21	WEATHER STRIP TAILGATE	90830-3XA0A	11	134.30	X
22	REAR W/SCREEN SEALANT	SEALANT - 4	11	80.00	✓
23	LH STAY TAILGATE	90451-3XA0B	11	215.90	X
24	RH STAY TAILGATE	90450-3XA0B	11	215.90	X
25	INNER SCREEN TAIL GATE	90860-3XA0A	11	16.20	X

MATERIAL LIST FOR ACCIDENT VEHICLE REGN NO GP1199L

DAMAGED PARTS & PRICES					
S/NO	PARTS DESCRIPTION	PARTS NUMBER	NETT	LIST	S/NETT REMARKS
26	TAIL GATE	K010M-3KBAA	1998.30	✓	1208.98
27	CHROME TAILGATE FINISHER	90810-3KU1A	535.70	✓	324.10
28	GLASS-TAIL GATE	90300-3XA0A	891.00	✓	539.06
SUB TOTAL			5982.70	0.00	1099.70
LESS DISCOUNT (NETT-20.00%, LIST-30.00%, S/NETT-.00%)			1196.54	0.00	0.00
GRAND TOTAL			4786.16	0.00	1099.70
OVERALL TOTAL			5885.86		

LEGEND: REMARKS(OK) = APPROVED, REMARKS(X) = NOT APPROVED

SUMMARY OF ESTIMATE FOR VEHICLE REGN NO GP1199L

TOTAL LABOUR CHARGES	5478.00
TOTAL SPARE PARTS CHARGES	5885.86

GRAND TOTAL	11363.86 *

* All charges do2 not include GST.

SURVEYOR'S PARTICULARS

NAME	:	
SURVEYED DATE	:	
AUTHORIZED DATE	:	
EXCESS CLAUSE	:	0.00
LIABILITY	:	0.00
REMARKS	:	

PLS NOTE : This estimate is based on visual inspection of the affected vehicle. Should we require further labour charges & spare parts in the process of repairs, we shall inform you accordingly.