

AUTOLUTION INDUSTRIAL PTE LTD
19 UBI ROAD 4
SINGAPORE 408623
TEL: 6490 9666 FAX: 68467483

AUTOLUTION INDUSTRIAL PTE. LTD.

ESTIMATE : ACCIDENT/BODY REPAIRS

REFERENCE : INS/IC/EA/0420/21
DATE : 06-DEC-2021

LONPAC INSURANCE BHD
300 BEACH RD
#17-04/07 THE CONCOURSE
S(199555)
TEL : 62507388
FAX : 62962706
MOTOR CLAIMS DEPT

OWNER'S NAME : COMMAND - AIR PTE LTD
ADDRESS : 237 UBI AVE 4
INTREPID WAREHOUSE COMPLEX
S(408820)
TELEPHONE NO : 94783076

TYPE OF CLAIM : DIRECT SETTLEMENT / THIRD PARTY CLAIM
POLICY NO : D21MTPCVE002493
VEHICLE NO : GP1199L
MODEL CODE : MVL2RDRE26KW3GBR-D
MODEL/YEAR : NISSAN NV350 PANEL VAN MT EURO 5
ENGINE NO : YD25382579A
CHASSIS NO : JN1MC2E26Z0005245
MILEAGE : 134252 KM
DATE IN : 06/12/2021
LIABILITY : 0.00
EXCESS CLAUSE : 0.00
ESTIMATE BY : ELMER
ACCIDENT DATE : 06/12/2021

-9645 0084 elmer@tanchoy.com

ESTIMATED LABOUR CHARGES FOR ACCIDENT VEHICLE REGN NO GP1199L

S/NO	JOB CODE	NATURE OF JOB	ESTIMATED CHARGES	SURVEYOR'S RECOMMENDATION
1	ZZ/001	LABOR CHARGES TO REPAIR TRUNKFLOOR, INNER END PANEL BOTH INNER PANEL RR FENDER, RENEW OUTER END PANEL	2730.00	
2	ZZ/002	RR BUMPER AND TAIL GATE		
3	ZZ/003	CHARGES TO SPRAY PAINTING TRUNKFLOOR, INNER/OUTER END PANEL, BOTH RR FENDER INNER EXTENSION, RR BUMPR	2000.00	
4	ZZ/004	AND TAIL GATE		
5	ZZ/005	REMOVE AND INSTALL TAILGATE MECHANISM	80.00	
6	ZZ/006	RENEW REAR WINDSCREEN GLASS	240.00	
7	ZZ/007	RENEW REAR WINDSCREEN GLASS SOLAR FILM	150.00	
8	ZZ/008	RENEW REVERSE SENSOR	110.00	
9	ZZ/009	RENEW BOTH RR COMB LAMP AND CHECK WIRING SYSTEM RR	48.00	
10	ZZ/011	COMPUTER CHECK DIAGNOSIS	120.00	
11	ZZ/10	SUPPLY REAR LICENSE PLATE		
TOTAL LABOUR CHARGES			5478.00	

MATERIAL LIST FOR ACCIDENT VEHICLE REGN NO GP1199L

S/NO	PARTS DESCRIPTION	PARTS NUMBER	DAMAGED PARTS & PRICES		
			NETT	LIST	S/NETT REMARKS
1	CENTER TOP 3RD BRAKE LAMP	26590-3XA0A			237.50
2	RR WINDOW WIPER ARM COVER	28782-1FC0A			13.10
3	RR WINDOW WIPER BLADE	28790-3XA0A			26.90
4	RR WINDOW WIPER ARM	28781-3XA0A			75.20
5	REAR WIPER MOTOR	28710-3XA0A			242.00
6	REAR TOP UNDER MIRROR	96340-3XA0A	112.00		
7	LH RR COMB LAMP	26555-3XA0B	224.80		
8	RH RR COMB LAMP	26550-3XA0B	224.80		
9	SUNDRIES	NPN			100.00
10	EMBLEM-BACK DOOR URVAN	90892-3XY0A	64.90		
11	EMBLEM-BACK DOOR NV350	90890-3XY0A	110.00		
12	EMBLEM-REAR NISSAN	90890-JX00A	64.90		
13	INNER CENTER BRACKET RR BUMPER	85040-VZ00A	171.90		
14	CLIP RR BUMPER @ SGD \$1.30 EACH	01553-05323	13.00		
15	REAR BUMPER	85022-3XA0A	667.20		
16	REAR LICENCE PLATE	RLP			60.00
17	70KM/H STICKER	70KM/H			15.00
18	TAILGATE LOCK	90500-3XA0A	287.10		
19	STRIKER-TAIL GATE	90570-VW000	34.80		
20	SENSOR-REVERSE	SENSOR			250.00
21	WEATHER STRIP TAILGATE	90830-3XA0A	134.30		
22	REAR W/SCREEN SEALANT	SEALANT - 4			80.00
23	LH STAY TAILGATE	90451-3XA0B	215.90		
24	RH STAY TAILGATE	90450-3XA0B	215.90		
25	INNER SCREEN TAIL GATE	90860-3XA0A	16.20		

MATERIAL LIST FOR ACCIDENT VEHICLE REGN NO GP1199L

		DAMAGED PARTS & PRICES			
S/NO	PARTS DESCRIPTION	PARTS NUMBER	NETT	LIST	S/NETT REMARKS
26	TAIL GATE	K010M-3XBAA	1998.30		
27	CHROME TAILGATE FINISHER	90810-3XU1A	535.70		
28	GLASS-TAIL GATE	90300-3XA0A	891.00		
SUB TOTAL			5982.70	0.00	1099.70
LESS DISCOUNT (NETT-20.00%, LIST-30.00%, S/NETT-.00%)			1196.54	0.00	0.00
GRAND TOTAL			4786.16	0.00	1099.70
OVERALL TOTAL			5885.86		

LEGEND: REMARKS(OK) = APPROVED, REMARKS(X) = NOT APPROVED

SUMMARY OF ESTIMATE FOR VEHICLE REGN NO GP1199L

TOTAL LABOUR CHARGES 5478.00
TOTAL SPARE PARTS CHARGES 5885.86

GRAND TOTAL 11363.86 *

* All charges do2 not include GST.

SURVEYOR'S PARTICULARS

NAME :
SURVEYED DATE :
AUTHORIZED DATE :
EXCESS CLAUSE : 0.00
LIABILITY : 0.00
REMARKS :

PLS NOTE : This estimate is based on visual inspection of the
 affected vehicle. Should we require further labour
 charges & spare parts in the process of repairs, we
 shall inform you accordingly.