

PAIR DETAILS

Reference

Part Source: MRM-SG
 Parts: M1-MPV Version: 1.0 (Last Synchronised: 07 Dec 2021)
 Labour: Repairer's TOYOTA WISH 1.8 (A) (Catalogue:Merimen Singapore 1.0)
 Print Code: (Unsubmitted, no print-code for SGL3735Y)
 Validity: These estimates are valid only if they contain the print code (above) on all estimate pages, running page numbers with the END OF ESTIMATES marker on the last estimate page
 Further Info: Items/values not in reference catalogue are prefixed with an asterisk *.

SGL3735Y
 TP/china

Estimates on Parts

No.	Qty	Part No.	Particulars	%Disc	%Depr	Amount
1	1		*1 PC FRT RH DOOR	0.00	0.00	Rm *480.00 F ✓
2	1		*1 PC RH SIDE SKIRT	0.00	0.00	Redline *290.00 F ✓
3	1		*1 PC FRT RH DOOR SIDE MIRROR	0.00	0.00	Sm *310.00 F X
Total Parts (S\$)						1,080.00

F=Franchise part.

Report was unsubmitted during this print-out.
 Generated using Merimen e-Claims IEAS

Estimates on Miscellaneous Items

There are no new miscellaneous items selected.

Estimates on Labour

No	Particulars	Lab.Type	Amount
Labour Items			
1	REMOVE & REFIX FRT RH DOOR, TRANSFER DOOR ATTACHMENT, SIDE SKIRT, TO KNOCK & REPAIR RH ROCKER PANEL AND REALIGN THE SAME	New	600.00 Rod
2	PUTTY & RESPRAY ON FRT RH DOOR, RH ROCKER PANEL, RH SIDE SKIRT	New	600.00 Seal
3	REMOVE & REFIX FRT RH DOOR GLASS	New	60.00 ✓
4	RUSTPROOFING	New	30.00 ✓
Gross Labour Cost (S\$)			1,290.00

Report was unsubmitted during this print-out.
 Generated using Merimen e-Claims IEAS

< END OF ESTIMATES >

81750/-

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date:

REPAIR DETAILS

Reference

Part Source: MRM-SG

Parts: M1-MPV

Labour: Repairer's

Print Code: **Cheng Hoe Motor Pte Ltd/SGL3735Y/09/12/2021 09:21**

Validity: These estimates are valid only if they contain the print code (above) on all estimate pages, running page numbers with the END OF ESTIMATES marker on the last estimate page

Further Info: Items/values not in reference catalogue are prefixed with an asterisk *.

Version: 1.0 (Last Synchronised: 09 Dec 2021)

TOYOTA WISH 1.8 (A) (Catalogue:Merimen Singapore 1.0)

(Price-denominated Standard List)

SGL3735Y

SUPP

Estimates on Parts

There are no new parts selected.

Cheng Hoe Motor Pte Ltd/SGL3735Y/09/12/2021 09:21. Not valid without Reference section.
Generated using Merimen e-Claims IEAS

Estimates on Miscellaneous Items

There are no new miscellaneous items selected.

Estimates on Labour

No Particulars

Labour Items		Lab.Type	Amount
1	TO REMOVE & REFIX FRT RH DOOR ALARM SYSTEM AND RESET SYSTEM	New	60.00
2	TO SUPPLY 2 PCS FRT RH DOOR SOUND PROTECTION SEAL AND REFIX	New	100.00
Gross Labour Cost (S\$)			260.00

Cheng Hoe Motor Pte Ltd/SGL3735Y/09/12/2021 09:21. Not valid without Reference section.
Generated using Merimen e-Claims IEAS

< END OF ESTIMATES >