



A Subsidiary Of Autobacs Seven Co Ltd. Japan

8 Kaki Bukit Ave 4 #08-40/45/46 Premier@Kaki Bukit S(415875)

Tel : 6702 1555 Fax : 6702 1444 (Co Reg. No. 201500047H)

Email : tohguan@skauto.com.sg

TO	: CHINA TAIPING (SCV32G)	DATE	: 6-Dec-21
ATTENTION	: MOTOR CLAIMS DEPARTMENT	JOB TYPE	: T/P CLAIMS
OWNER PARTICULAR			
OWNER ID	: SXXXX794H		
VEHICLE DETAILS			
VEHICLE NO.	: SMJ6589Y	Veron.	
MODEL / MAKE	: HONDA FIT		
CHASSIS NO.	: GP5-1335477		
ACCIDENT DETAIL			
DATE	: 4-Dec-21		
TIME	: 03:30HRS	CONTACT PERSON	: MR. WINSON 91866680

QUOTATION SUMMARY

PAGE 01

CLAIMS DETAIL : PARTS LIST

S/N	DESCRIPTION	QTY	UNIT LIST PRICE	TOTAL LIST PRICE
1	FRONT HEADLAMP RH <i>Veron</i>	1	\$ 936.00	\$ 936.00
2	FRONT HEADLAMP LOWER BRACKET RH <i>new</i>	1	\$ 42.90	\$ 42.90
3	FRONT GRILLE <i>cracked</i>	1	\$ 321.80	\$ 321.80
4	FRONT GRILLE LOGO EMBLEM <i>new</i>	1	\$ 25.30	\$ 25.30
5	FRONT GRILLE CHROME GARNISH UPPER <i>new</i>	1	\$ 224.30	\$ 224.30
6	FRONT GRILLE CHROME MOLDING LOWER <i>lt.</i>	1	\$ 341.30	\$ 341.30
7	FRONT BUMPER <i>Defend</i>	1	\$ 872.20	\$ 872.20
8	FRONT BUMPER TOW HOOK COVER <i>new</i>	1	\$ 29.30	\$ 29.30
9	FRONT BUMPER LOWER CENTER GRILLE <i>cracked</i>	1	\$ 243.80	\$ 243.80
10	FRONT BUMPER LOWER CENTER GRILLE SIDE GARNISH LH/RH <i>new</i>	1	\$ 19.50	\$ 19.50
11	FRONT BUMPER FOG LAMP COVER RH <i>cracked</i>	1	\$ 68.30	\$ 68.30
12	FRONT BUMPER SIDE RETAINER LH/RH <i>new</i>	2	\$ 19.50	\$ 39.00
13	FRONT BUMPER REINFORCEMENT <i>new</i>	1	\$ 321.80	\$ 321.80
14	FRONT BUMPER LOWER UNDER COVER <i>new</i>	1	\$ 273.00	\$ 273.00
15	AIRCON CONDENSER AIR GUIDE RH <i>#</i>			
	<i>torn</i>			
			TOTAL PRICE	\$ 3,778.00
			LESS -20%	\$ (755.60)
			SUB TOTAL PRICE	\$ 3,022.40

CLAIMS DETAIL : PARTS LIST

S/N	DESCRIPTION	QTY	UNIT S/NETT	TOTAL S/NETT
1	FRONT GRILLE CLIPS SET <i>new</i>	1	\$ 50.00	\$ 50.00
2	FRONT BUMPER NUMBER PLATE WITH CASING SET <i>cracked</i>	1	\$ 85.00	\$ 85.00
3	FRONT BUMPER CLIPS SET <i>new</i>	1	\$ 80.00	\$ 80.00

TOTAL

\$ 215.00

QUOTATION SUMMARY

PAGE 02

CLAIMS DETAIL : LABOUR CHARGES AND SPRAY PAINTING

TO DISMANTLE & REPLACED WITH PANEL BEATING ALL THE ACCIDENT PORTION	\$ 600.00	200	
TO SPRAY PAINTING ALL THE ACCIDENT PORTION & POLISHING AFFECTED AREA	\$ 600.00	200	
TO APPLY ANTI-RUST & TUFF KOTE	\$ 75.00	X	
TO PERFORM LIGHTING & WIRING CHECK	\$ 80.00	30	

TOTAL \$ 1,355.00

430

Adrian Lij
P/P 07/12/21.
02 Days

ESTIMATE REPORT

TOTAL PARTS COST : \$ 3,237.40
TOTAL LABOUR COST : \$ 1,355.00
TOTAL REPAIR COST : \$ 4,592.40

4608.00

APPROVED DETAILS

NO. OF REPAIR DAYS : DAYS
REPAIR UNDER : PART BY PART OR LUMPSUM
DATE / TIME OF SURVEY :
SURVEYED BY / FROM :
CONTACT NUMBER :
EMAIL ADDRESS :
DATE / TIME OF RE-SURVEY :
EXCESS :

total: 1951.60 ✓
(P/P)

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date: