



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Affiliated to Federation Internationale Des Experts En Automobile				
STRIDES AUTOMOTIVE SERVICES PTE LTD 60 WOODLANDS INDUSTRIAL PARK E4SINGAPORE 757705			Ref: CS/SMR21012368/Utf3n2	
			Date: 29/12/2021	
			Code: SMR	
1. Policy Particulars :- THIRD PARTY CLAIM				
Insured Veh.	SHB 5812K	Veh. Inspected	SLH 8733G	
Policy No.		Coverage (\$)	0.00	
Claim No.	TAX/12/21/2007	Excess (\$)	0.00	
Assign From	HUA YEN	Assign Date	07/12/2021	
2. Vehicle Particulars & Condition				
Make & Model	SUBARU FORESTER (A)	c.c	1995	
Engine No.	HIDDEN	Year of Reg.	2016	
Chassis No.	JF1SJ5KC5GG079770	Colour	SILVER	
Odometer	71861 KM	Steering	IN ORDER	
Brakes	IN ORDER	Modification	SPORTS RIM	
General	GOOD			
3. Conditions of Tyres				
	Size	Make	Balance	
R/H Front Tyre	225/60 R17	YOKOHAMA	6 mm	
L/H Front Tyre	225/60 R17	YOKOHAMA	6 mm	
R/H Rear Tyre	225/60 R17	GOODYEAR	6 mm	
L/H Rear Tyre	225/60 R17	GOODYEAR	6 mm	
4. Description of Damages				
THE VEHICLE SUSTAINED DAMAGES AT THE REAR PORTION. DAMAGES SEE DETAILS.				
5. General Information				
Accident Date	03/12/2021	Inspection Date	07/12/2021	
Survey held at	BLK 15 KAKI BUKIT ROAD 4, BARTLEY BIZ, #01-53			
Repairer	ZOOM AUTOWERKS PTE LTD			
5a. Remarks				
A)THE INSPECTION WAS CONDUCTED ON A"WITHOUT PREJUDICE" BASIS. B)IN ACCORDANCE TO YOUR INSTRUCTIONS, WE HAVE NOT AUTHORISED REPAIRS.				
5b. Estimate Days of Repair				
ESTIMATED NORMAL PERIOD FOR REPAIR:			9 Working Days	