



# LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Affiliated to Federation Internationale Des Experts En Automobile				
INDIA INTERNATIONAL INSURANCE PL 64 CECIL STREET #05-02 IOB BUILDING SINGAPORE 049711			Ref: CS3/III20012509/Dqf3e2-1	
			Date: 04/02/2022	
			Code: III2	
<b>1. Policy Particulars :- THIRD PARTY CLAIM</b>				
Insured Veh.	SHD 3211Y	Veh. Inspected	SMH 9726J	
Policy No.	MCOM0015	Coverage (\$)	0.00	
Claim No.	MCT20110205	Excess (\$)	0.00	
Assign From	CARINE KEK PHER SER	Assign Date	07/12/2021	
<b>2. Vehicle Particulars &amp; Condition</b>				
Make & Model	LAND ROVER DISCOVERY	c.c	1999	
Engine No.	HIDDEN	Year of Reg.	2017	
Chassis No.	SALCA2AN8HH720975	Colour	WHITE	
Odometer	63026 KM	Steering	IN ORDER	
Brakes	IN ORDER	Modification	STANDARD ALLOY RIM	
General	GOOD			
<b>3. Conditions of Tyres</b>				
	Size	Make	Balance	
R/H Front Tyre	235/60 R18	PIRELLI	6 mm	
L/H Front Tyre	235/60 R18	PIRELLI	6 mm	
R/H Rear Tyre	235/60 R18	PIRELLI	6 mm	
L/H Rear Tyre	235/60 R18	PIRELLI	6 mm	
<b>4. Description of Damages</b>				
THE VEHICLE SUSTAINED DAMAGES AT THE O/S BODY. THE UNDERCARRIAGE AFFECTED DUE TO COLLISION. DAMAGES SEE DETAILS.				
<b>5. General Information</b>				
Accident Date	12/11/2020	Inspection Date	13/11/2020	
Survey held at	HIAP LEK AUTOMOBILE TRADING BLK 14 #01-19 SECTOR B SIN MING INDUSTRIAL ESTATE . SINGAPORE 575658.			
<b>5a. Remarks</b>				
A)THE INSPECTION WAS CONDUCTED ON A"WITHOUT PREJUDICE" BASIS. B)IN ACCORDANCE TO YOUR INSTRUCTIONS, WE HAVE NOT AUTHORISED REPAIRS.				
<b>5b. Estimate Days of Repair</b>				
ESTIMATED NORMAL PERIOD FOR REPAIR:			7 Working Days	