

SAM YICK LIAN

1 KAKI BUKIT AVE 6

#01-70 AUTOBAY @ KAKI BUKIT

SINGAPORE 417883

TEL: 6744 1373 FAX: 6741 7138

REG NO: 01939300L

TPECICS.

Veron.

ESTIMATE

VEHICLE NO: SMS 8390 S

MODEL: HONDA SHUTTLE

LKK Auto Consultants hence notify
the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer

GK Signature: 2100947
Date:

NO.	DESCRIPTION	QTY	PRICE (\$)
PARTS			
1	REAR BOOTLID <i>Dented</i>	1	1,276.50 ✓ 1193
2	REAR BOOTLID UPPER LOCK <i>Dented</i>	1	168.20 ✓
3	REAR BOOTLID INNER BOARD <i>Dented</i>	1	439.30 ✓ 295
4	REAR BOOTLID INNER WEATHER STRIP <i>lit</i>	1	180.20 ✓
5	REAR BOOTLID CENTRE HANDLE <i>new</i>	1	185.00 +
6	REAR BOOTLID "H" EMBLEM <i>new</i>	1	100.00 +
7	REAR BOOTLID "SHUTTLE" EMBLEM <i>new</i>	1	80.00 ✓
8	REAR BUMPER <i>Dented</i>	1	1,230.00 ✓ 1050
9	REAR BUMPER CHROME MOULDING <i>new</i>	1	161.80 ✓
10	REAR BUMPER TOWING HOOK COVER <i>Dented</i>	1	18.10 ✓
11	REAR BUMPER REFLECTOR @ \$48.10 <i>new</i>	2	96.20 x
12	REAR BUMPER BRACKET @ \$26.70 <i>new</i>	2	53.40 x
13	REAR BUMPER SIDE BRACKET @ \$39.00 <i>new</i>	2	78.00 ✓
14	REAR BUMPER REINFORCEMENT <i>new</i>	1	450.00 x
15	REAR END PANEL <i>Dented</i>	1	643.60 ✓ 4501.76
16	REAR END PANEL TOP GARNISH <i>Dented</i>	1	166.30 ✓
17	REAR LAMP @ \$589.00 <i>lit</i>	2	1,178.00 ✓
18	REAR SPARE TYRE TOP BOARD <i>new</i>	1	380.00 +
19	REAR SPARE TYRE TOOL BOX <i>Dented</i>	1	604.60 ✓ 415
20	REAR BUMPER CENTRE CHROME	2	280.00
LESS 20%			1,497.84
TOTAL			5,991.36

SPECIAL NETT ITEMS

1	REAR WINDSCREEN SEALANT <i>new</i>	1	50.00 ✓
2	REAR TAILGATE LOCK SENSOR <i>new</i>	1	380.00 x 250
3	REVERSE SENSOR (1 SET) <i>Dented</i>	1	380.00 200
TOTAL			810.00

LABOUR COST

1	TO PROVIDE PANEL KNOCKING ON ACC PARTS	2070	1,500.00 800
2	TO PROVIDE SPRAY PAINTING		1,300.00 800
3	REMOVE & REFIX REAR WINDSCREEN		200.00 120
4	REMOVE & REPLACE REVERSE SENSOR		100.00 50
5	REMOVE & REFIX CAMERA		100.00 50
6	Remove and refix reverse sensor		
7	Remove and refix upholstery		
8	To buff coat affected panels		
9	To transfer tailgate fittings		
TOTAL			3,200.00
GRAND TOTAL			10,001.36
			10,551.36

total: 6821.76

A/S: 5450

06 days