

PROVI AUTOWORKS PTE LTD.

Blk 8 , Kaki Bukit Avenue 4 , #02-24

Premier @ Kaki Bukit Singapore 415875

Email: claims@PROVIAUTO.com

Tel: 6286 6060 Fax : 6286 7060

Office Use Only

Parts -25%	
SN	
Labour	
TOTAL	
LUMSUM	
ERV	16k

TO: AIG
Vehicle No : SLN 6623 Y
Make & Model : TOYOTA AXIO
DATE: : 3/12/2021

No.	DESCRIPTION - PARTS	QTY	UNIT PRICE	PRICE	
1	BOOTLID / <i>Blue</i>	1	\$ 954.00	\$ 954.00	895
2	BOOTLID LOGO /	1	\$ 85.00	\$ 85.00	✓
3	BOOTLID EMBLEM (COROLLA) / } <i>Blue</i>	1	\$ 87.60	\$ 87.60	45
4	BOOTLID EMBLEM (AXIO) /	1	\$ 126.00	\$ 126.00	60
5	BOOTLID OUTER CHROME MOULDING X	1	\$ 452.00	\$ 452.00	
6	BOOTLID CAR PLATE LAMP X } <i>NN</i>	2	\$ 58.00	\$ 116.00	
7	BOOTLID OPENER SWICTH X	1	\$ 211.70	\$ 211.70	
8	BOOTLID INNER LOCK / <i>BT</i>	1	\$ 317.50	\$ 317.50	✓
9	BOOTLID LOCK CATCH X <i>NN</i>	1	\$ 35.00	\$ 35.00	
10	BOOTLID WEATHERSTRIP / <i>twi</i>	1	\$ 215.00	\$ 215.00	175
11	BOOTLID INNER TRIM X <i>NN</i>	1	\$ 395.00	\$ 395.00	
12	BOOTLID HINGE X	2	\$ 212.00	\$ 424.00	
13	TAILLAMP / <i>Blue</i>	2	\$ 698.00	\$ 1,396.00	1170
14	TAILLAMP INNER GASKET Blue X <i>NN</i>	2	\$ 76.30	\$ 152.60	
15	TAILLAMP PANEL IPC <i>Blue</i>	2	\$ 252.00	\$ 504.00	150
16	TAILLAMP LOWER BRACKET IPC <i>BR</i>	2	\$ 76.00	\$ 152.00	✓
17	REAR BUMPER / <i>Re</i>	1	\$ 665.00	\$ 665.00	596.2
18	REAR BUMPER SIDE RETAINER <i>IPC</i> - <i>BR</i>	2	\$ 185.00	\$ 370.00	96
19	REAR BUMPER REFLECTOR <i>IPC</i> - <i>BR</i>	2	\$ 125.00	\$ 250.00	48.2
20	REAR BUMPER DAMPER IPC <i>BT</i>	2	\$ 166.40	\$ 332.80	65
21	REAR FENDER LH X <i>repair</i>	1	\$ 1,036.40	\$ 1,036.40	
22	REAR FENDER INNER TRIM / <i>IN</i> <i>IPC</i>	2	\$ 358.00	\$ 716.00	263.1
23	REAR FENDER INNER SHIELD <i>IPC</i> - <i>IN</i>	2	\$ 96.00	\$ 192.00	96
24	REAR FENDER AIR VENT X	1	\$ 55.00	\$ 55.00	
25	REAR WINDSCREEN MOULDING X } <i>NN</i>	1	\$ 154.00	\$ 154.00	
26	REAR END PANEL / <i>Blue</i>	1	\$ 696.30	\$ 696.30	608
27	REAR END PANEL TOP GARNISH / <i>Re</i>	1	\$ 280.00	\$ 280.00	227
28	REAR FLOOR PANEL X <i>repair</i>	1	\$ 785.00	\$ 785.00	
29	REAR FLOOR PANEL TOP BOARD / <i>BT</i>	1	\$ 542.00	\$ 542.00	✓
30	REAR FLOOR TOOL SPONGE / <i>Blue</i>	1	\$ 325.00	\$ 325.00	✓

31	REAR DOOR INNER LOCK LH X	} nn	1	\$ 452.00	\$ 452.00
32	REAR DOOR WEATHERSTRIP LH X		1	\$ 215.00	\$ 215.00
33	DRIVER SEAT BELT X		1	\$ 954.00	\$ 954.00
34	SRS AIRBAG CONTOR UNIT X		1	\$1,245.00	\$ 1,245.00

Antenna sensor / pm 379 144.7

Subtotal : \$ 14,888.90 6060.7

Less 25% \$ 3,722.23

Parts Total : \$ 11,166.68 4545.52

NO.	SPECIAL NETT	QTY	UNIT PRICE	PRICE
1	REAR BUMPER CLIP / MC.	1	\$ 50.00	\$ 50.00 30
2	BOOT LID INNER TRIM CLIP X	1	\$ 50.00	\$ 50.00
3	BOOT LID OUTER GARNISH CLIP X	1	\$ 40.00	\$ 40.00
4	TAIL LAMP CLIP /	1	\$ 30.00	\$ 30.00 10
5	TAIL LAMP PANEL SEALANT /	1	\$ 80.00	\$ 80.00 20
6	REAR WINDSCREEN SEALANT X	1	\$ 80.00	\$ 80.00
7	REAR WINDSCREEN INNER SEAL X	1	\$ 60.00	\$ 60.00
8	REAR FENDER SEALANT X	1	\$ 80.00	\$ 80.00
9	REAR FENDER INNER TRIM CLIPS /	1	\$ 60.00	\$ 60.00 30
10	REAR FENDER INNER SHIELD CLIP /	1	\$ 50.00	\$ 50.00 20
11	REAR END PANEL SEALANT /	1	\$ 80.00	\$ 80.00 40
12	REAR END PANEL TOP GARNISH CLIPS /	1	\$ 30.00	\$ 30.00 10
13	REAR FLOOR PANEL SEALANT X	1	\$ 80.00	\$ 80.00
14	REAR FLOOR PANEL INSULATION SEAL X	1	\$ 120.00	\$ 120.00
15	REVERSE SENSOR / pm	1	\$ 450.00	\$ 450.00 200
16	REAR WINDSCREEN SEALANT X	1	\$ 60.00	\$ 60.00
17	REAR WINDSCREEN INNER SEAL X	1	\$ 60.00	\$ 60.00
SPECIAL NETT				\$ 1,460.00 360

LABOUR		PRICE
PANEL BEATING, REMOVAL AND REPLACING PARTS	800 1000 800	\$ 2,000.00
TO SPRAY PAINT AFFECTED AREA	1000	\$ 1,800.00
TUFF COAT	60	\$ 200.00
WIRING CHECK	30	\$ 50.00
REMOVE AND REFIX CUSHION SEAT AND INTERIOR TO FACILITATE REPAIR	60	\$ 450.00
REMOVE AND REFIX REAR WINDSCREEN	any X	\$ 200.00
REMOVE AND INSTALL REAR EXHAUST	any X	\$ 350.00
TRANSFER BOOTLID MECHANISM	40	\$ 150.00
REMOVE AND REFIX REVERSE SENSOR AND DISTANCE SETTING	40	\$ 150.00
CONDUCT WATER LEAKAGE TEST	any X	\$ 100.00
RESET SRS AIRBAG SYSTEM	any X	\$ 550.00
LABOUR TOTAL		\$ 6,000.00 2230

	Total Parts Cost	\$ 12,626.68
	Total Labour Cost	\$ 6,000.00
	Total Repair Cost	\$ 18,626.68

APPROVED DETAILS
NO. OF WORKING DAYS
PART BY PART OR LUMP SUM
DATE & TIME OF SURVEY
SURVEYED BY
CONTACT NUMBER
FAX NUMBER

7 Days.
07/12/21
Cano Q'arp

6935.52
-20%: 5500

After repair photos.
45.

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer
Signature:
Date: