

TAN CHONG MOTOR SALES PTE. LTD.
911, BUKIT TIMAH ROAD
SINGAPORE 589623

ESTIMATE : ACCIDENT/BODY REPAIRS
WORKSHOP : BUKIT TIMAH
CONTACT NO : 4694091
REFERENCE : INS/IC/ZHR/0350/2021
DATE : 02-DEC-2021

INDIA INT'L INSURANCE PTE LTD
64 CECIL STREET
#04-05 IOB BUILDING
S(049711)
TEL : 63476100
FAX : 62244174
ATTN:MOTOR CLAIM MANAGER

OWNER'S NAME : CHUA LYE CHOON
ADDRESS : BLK 852 JURONG WEST ST 81
#02-315
S(640852)
TELEPHONE NO : 67934663/88895955

TYPE OF CLAIM : DIRECT SETTLEMENT / THIRD PARTY CLAIM
POLICY NO : TP-SLH8715J
VEHICLE NO : SLH2174J
MODEL CODE : FRLARBZJ11UEA--A--
MODEL/YEAR : NISSAN QASHQAI 1.2
ENGINE NO : HRA2301403A
CHASSIS NO : SJNFEAJ11U1775822
MILEAGE : 1 KM
DATE IN : 02/12/2021
LIABILITY : 0.00
EXCESS CLAUSE : 0.00
ESTIMATE BY : MUHAMMAD ZUHRI
ACCIDENT DATE : 01/12/2021

DIRECT SETTLEMENT

OWNER CLAIMING LOSS OF USE / RENTAL

CAR AT WORKSHOP / CAR NOT AT WORKSHOP

KINDLY REVERT TO ME ASAP

03.12.2021

EMAIL : zuhri@tanchong.com

OFFICE : 67038916 FAX : 64697472

TAN CHONG MOTOR SALES PTE. LTD.
BUKIT TIMAH W/SHOP
SERVICE DEPARTMENT

ESTIMATED LABOUR CHARGES FOR ACCIDENT VEHICLE REGN NO SLH2174J

S/NO JOB CODE	NATURE OF JOB	ESTIMATED CHARGES	SURVEYOR'S RECOMMENDATION
1 RPI	PERFORM RUST PROOFING & TREATMENT FOR AFFECTED PANEL	120.00	
2 RSI	REPLACE REVERSE SENSOR, NECESSARY ADJUSTMENT & FUNCTION TEST	110.00	
3 Zz/001	REPAIR RR END PANEL & RENEW RR BUMPER	975.00	
4 Zz/002	S/PAINT RR BUMPER(2 TONE) & RR END PANEL	750.00	
	TOTAL LABOUR CHARGES	----- 1955.00 -----	

TAN CHONG MOTOR SALES PTE. LTD.
 BUKIT TIMAH W/SHOP
 SERVICE DEPARTMENT

MATERIAL LIST FOR ACCIDENT VEHICLE REGN NO SLH2174J

S/NO PARTS DESCRIPTION	PARTS NUMBER	DAMAGED PARTS & PRICES			REMARKS
		NETT	LIST	S/NETT	
1 SUNDRIES	NPN			20.00	
2 SENSOR-REVERSE	SENSOR			250.00	
3 STAY LH,RR	H5211-4EAMA	141.00			
4 STAY RH,RR	H5210-4EAMA	141.00			
5 REINF-BUMPER RR	H5030-4EAMA	691.50			
6 ENERGY ABSORBER	85090-4EA0B	155.60			
7 BRACKET-BUMPER	85221-4EA0A	38.90			
8 CLIP(8X3)	85284-JD00A	24.00			
9 CANOE(7.1X2)	76882-0M000	14.20			
10 CLIP(10X1.3)	01553-05933	13.00			
11 FINISHER-REAR B	85071-4EA0A	18.80			
12 FASCIA-RR BUMP	85022-4EA0H	876.40			
SUB TOTAL		2114.40	0.00	270.00	
LESS DISCOUNT (NETT-20.00%, LIST-30.00%, S/NETT-.00%)		422.88	0.00	0.00	
GRAND TOTAL		1691.52	0.00	270.00	
OVERALL TOTAL		1961.52			

LEGEND: REMARKS(OK) = APPROVED, REMARKS(X) = NOT APPROVED

TAN CHONG MOTOR SALES PTE. LTD.
BUKIT TIMAH W/SHOP
SERVICE DEPARTMENT

SUMMARY OF ESTIMATE FOR VEHICLE REGN NO SLH2174J

TOTAL LABOUR CHARGES	1955.00
TOTAL SPARE PARTS CHARGES	1961.52

GRAND TOTAL	3916.52 *

* All charges do2 not include GST.

SURVEYOR'S PARTICULARS

NAME	:	
SURVEYED DATE	:	
AUTHORIZED DATE	:	
EXCESS CLAUSE	:	0.00
LIABILITY	:	0.00
REMARKS	:	

PLS NOTE : This estimate is based on visual inspection of the
affected vehicle. Should we require further labour
charges & spare parts in the process of repairs, we
shall inform you accordingly.