

TAN CHONG MOTOR SALES PTE. LTD.
911, BUKIT TIMAH ROAD
SINGAPORE 589623

ESTIMATE : ACCIDENT/BODY REPAIRS
WORKSHOP : BUKIT TIMAH
CONTACT NO : 4694091
REFERENCE : INS/IC/ZHR/0350/2021
DATE : 02-DEC-2021

INDIA INT'L INSURANCE PTE LTD
64 CECIL STREET
#04-05 IOB BUILDING
S(049711)
TEL : 63476100
FAX : 62244174
ATTN:MOTOR CLAIM MANAGER

OWNER'S NAME : CHUA LYE CHOON
ADDRESS : BLK 852 JURONG WEST ST 81
#02-315
S(640852)
TELEPHONE NO : 67934663/86895955

TYPE OF CLAIM : DIRECT SETTLEMENT / THIRD PARTY CLAIM
POLICY NO : TP-SLH8715J
VEHICLE NO : SLH2174J
MODEL CODE : FRLARBZJ11UEA--A--
MODEL/YEAR : NISSAN QASHQAI 1.2
ENGINE NO : HRA2301403A
CHASSIS NO : SJNFEAJ11U1775822
MILEAGE : 1 KM
DATE IN : 02/12/2021
LIABILITY : 0.00
EXCESS CLAUSE : 0.00
ESTIMATE BY : MUHAMMAD ZUHRI
ACCIDENT DATE : 01/12/2021

DIRECT SETTLEMENT

OWNER CLAIMING LOSS OF USE / RENTAL

CAR AT WORKSHOP / CAR NOT AT WORKSHOP

KINDLY REVERT TO ME ASAP

03.12.2021

EMAIL : zuhri@tanchong.com

OFFICE : 67038916 FAX : 64697472

TAN CHONG MOTOR SALES PTE. LTD.
 BUKIT TIMAH W/SHOP
 SERVICE DEPARTMENT

ESTIMATED LABOUR CHARGES FOR ACCIDENT VEHICLE REGN NO SLH2174J

S/NO JOB CODE	NATURE OF JOB	ESTIMATED CHARGES	SURVEYOR'S RECOMMENDATION
1 RPI	PERFORM RUST PROOFING & TREATMENT FOR AFFECTED PANEL	120.00	/
2 RSI	REPLACE REVERSE SENSOR, NECESSARY ADJUSTMENT & FUNCTION TEST	110.00	/
3 ZZ/001	REPAIR RR END PANEL & RENEW RR BUMPER ⁷ 340	975.00	390
4 ZZ/002	S/PAINT RR BUMPER(2 TONE) & RR END PANEL ⁷ 250 250+125 250	750.00	375
TOTAL LABOUR CHARGES		1955.00	

MATERIAL LIST FOR ACCIDENT VEHICLE REGN NO SLH2174J

S/NO PARTS DESCRIPTION	PARTS NUMBER	DAMAGED PARTS & PRICES		
		NETT	LIST	S/NETT REMARKS
1 SUNDRIES	NFN			20.00 ✓
2 SENSOR-REVERSE <i>OR</i>	SENSOR			250.00 ✓
3 STAY LH,RR	H5211-4EAMA	141.00	?	
4 STAY RH,RR	H5210-4EAMA	141.00	?	
5 REINF-BUMPER RR	H5030-4EAMA	691.50	?	
6 ENERGY ABSORBER	85090-4EA0B	155.60	?	
7 BRACKET-BUMPER	85221-4EA0A	38.90	✓ <i>BR</i>	
8 CLIP(8X3)	85284-JD00A	24.00	✓ <i>MC</i>	
9 CANOE(7.1X2)	76882-0M000	14.20	✓ <i>MC</i>	
10 CLIP(10X1.3)	01553-05933	13.00	✓ <i>MC</i>	
11 FINISHER-REAR B	85071-4EA0A	18.80	✓ <i>CRU</i>	
12 FASCIA-RR BUMP	85022-4EA0H	876.40	✓ <i>OO</i>	
SUB TOTAL		2114.40	0.00	270.00
LESS DISCOUNT (NETT-20.00%, LIST-30.00%, S/NETT-.00%)		422.88	0.00	0.00
GRAND TOTAL		1691.52	0.00	270.00
OVERALL TOTAL		1961.52		

LEGEND: REMARKS(OK) = APPROVED, REMARKS(X) = NOT APPROVED

TAN CHONG MOTOR SALES PTE. LTD.
 BUKIT TIMAH W/SHOP
 SERVICE DEPARTMENT

SUMMARY OF ESTIMATE FOR VEHICLE REGN NO SLH2174J

TOTAL LABOUR CHARGES	1955.00
TOTAL SPARE PARTS CHARGES	1961.52
GRAND TOTAL	3916.52 *

* All charges do2 not include GST.

SURVEYOR'S PARTICULARS

NAME :
 SURVEYED DATE :
 AUTHORIZED DATE :
 EXCESS CLAUSE : 0.00
 LIABILITY : 0.00
 REMARKS :

*Store (LKK)
 8/12/21, 2-3pm*

*W/L
 P/P
 2 by 2 by
 3 dgs*

PLS NOTE : This estimate is based on visual inspection of the affected vehicle. Should we require further labour charges & spare parts in the process of repairs, we shall inform you accordingly.

- LKK Auto Consultants hence notify the Repairer of the following:
- To resurvey before/after spray painting
 - To display damaged part(s) during resurvey
 - Parts prices are subject to confirmation
 - Third party survey is on a "Without Prejudice" basis
 - No illegal modification(s) is allowed
 - Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer
 Signature:
 Date: