

Trans-cab Auto Services Pte Ltd

No. 2 Ang Mo Kio Street 63 Singapore 569111

Tel No. : 6287 6666 Fax No. : 6257 1330

CO./GST Reg. No. 201019626G

SML8528A

LAD2111-

Not Authorised
Recovery B4 paint
\$1144.48

Vehicle No.:

Chassis No.:

Vehicle Make:

Vehicle Model:

Date of Accident :

Third Party Insurer :

Date of Registration :

06 DEC 2021**SML8528A**

JTDKB3FU403083512

TOYOTA

PRIUS

03/12/2021

AIG.

07/06/2019

PART

- 1 MIRROR ASSY, OUTER REAR VIEW, RH

LIST

	\$	<i>Bv</i> 1,339.30	<i>✓</i>
TOTAL	\$	1,339.30	
25%	\$	334.83	
	\$	1,004.48	

Special Nett**TOTAL**

\$	-
----	---

TOTAL PARTS	\$	1,004.48
--------------------	----	-----------------

LABOUR

To remove and refit interior fittings, trimings, garnish, fittings and other, to enable repair.

\$	<i>nn</i> 380.00	<i>X</i>
----	------------------	----------

Panel Beating, Knocking And Straightening The Necessary Portion, Remove And Renewal Of Parts, Adjust And Realign The Same

\$	1,400.00	<i>601</i>
----	----------	------------

Putty And Spray Painting Of The Affected Portion.

\$	1,400.00	<i>601</i>
----	----------	------------

To Check Electrical Lighting Concerned.

\$	170.00	<i>201</i>
----	--------	------------

TOTAL	\$	3,350.00
--------------	----	-----------------

Trans-cab Auto Services Pte Ltd

No. 2 Ang Mo Kio Street 63 Singapore 569111

Tel No. : 6287 6666 Fax No. : 6257 1330

CO./GST Reg. No. 201019626G

SML8528A

LAD2111-

Over All Total	\$	4,354.48
-----------------------	-----------	-----------------

(PART-BY-PART) Repair Days

~~20~~ days

1 day

LKK Auto Consultants hence notify
the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and
is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date: