



# LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Affiliated to Federation Internationale Des Experts En Automobile			
INDIA INTERNATIONAL INSURANCE PL 64 CECIL STREET #05-02 IOB BUILDING SINGAPORE 049711		Ref: CS3/GRB21007017/Bqf3e2-1 Date: 13/01/2022 Code: GRB	
<b>1. Policy Particulars :- THIRD PARTY CLAIM</b>			
<b>Insured Veh.</b>	SLS 5230C	<b>Veh. Inspected</b>	GBG 4166T
<b>Policy No.</b>	D21MFL0000447	<b>Coverage (\$)</b>	0.00
<b>Claim No.</b>	MFL2021D0002694	<b>Excess (\$)</b>	0.00
<b>Assign From</b>	CARINE KEK PHER SER	<b>Assign Date</b>	07/12/2021
<b>2. Vehicle Particulars &amp; Condition</b>			
<b>Make &amp; Model</b>	TOYOTA PROACE	<b>c.c</b>	1997
<b>Engine No.</b>	HIDDEN	<b>Year of Reg.</b>	2017
<b>Chassis No.</b>	YARVFAHKHGZ069481	<b>Colour</b>	WHITE
<b>Odometer</b>	44782 KM	<b>Steering</b>	IN ORDER
<b>Brakes</b>	IN ORDER	<b>Modification</b>	NIL
<b>General</b>	FAIR		
<b>3. Conditions of Tyres</b>			
	<b>Size</b>	<b>Make</b>	<b>Balance</b>
<b>R/H Front Tyre</b>	215/65 R16	GOODYEAR	5 mm
<b>L/H Front Tyre</b>	215/65 R16	GOODYEAR	5 mm
<b>R/H Rear Tyre</b>	215/65 R16	BRIDGESTONE	5 mm
<b>L/H Rear Tyre</b>	215/65 R16	BRIDGESTONE	5 mm
<b>4. Description of Damages</b>			
THE VEHICLE SUSTAINED DAMAGES AT THE O/S BODY. DAMAGES SEE DETAILS.			
<b>5. General Information</b>			
<b>Accident Date</b>	22/06/2021	<b>Inspection Date</b>	29/06/2021
<b>Survey held at</b>	SIN HENG LONG MOTOR WORK BLK 5032 ANG MO KIO INDUSTRIAL PARK 2 #01-287/305 SINGAPORE 569535		
<b>5a. Remarks</b>			
A)THE INSPECTION WAS CONDUCTED ON A"WITHOUT PREJUDICE" BASIS. B)IN ACCORDANCE TO YOUR INSTRUCTIONS, WE HAVE NOT AUTHORISED REPAIRS.			
<b>5b. Estimate Days of Repair</b>			
ESTIMATED NORMAL PERIOD FOR REPAIR:		<b>5 Working Days</b>	