

Note: This document has not been finalised.

LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com; assignments@lkkauto.com

To: MSIG Insurance (Singapore) Pte. Ltd.
4 Shenton Way
#21-01 SGX Centre 2
Singapore 068807

From: LKK Auto Consultants Pte Ltd
51 Ubi Ave 1 #01-25
Paya Ubi Industrial Park
Singapore 408933

Attn: Christina Wong

Date: 09 Dec 2021

Preliminary Advice

Insured : SLQ4011K
Vehicle No
TP Vehicle No : SLN6761G
Accident Date : 02/12/2021
Make : KIA CERATO K3
Assignment Date : 07/12/2021
Date of Inspection : 08/12/2021
Est. Duration of Repair : 3
Inspection At : YEW TEE AUTOMOBILE TECH PTE LTD (WOODLANDS)
39 WOODLANDS CLOSE #01-12, MEGA@WOODLANDS
SINGAPORE 737856

Point of Impact / General Description of Damages

Parts claimed are consistent to the accident.

Repairer's Estimate (Gross)	:S\$	9,318.96
Revised Amount	:S\$	1,867.76
Check Items (Estimated)	:S\$	1,384.96
Total	:S\$	3,252.72

Lump Sum Repair :S\$

Total Loss Consideration

New for Old Value	:S\$
Pre-Accident Value	:S\$
COE / PARF Rebate	:S\$

Salvage Value :S\$

Margin for Repair :S\$

Remarks

- () The vehicle is economical for repair
- () The vehicle is not economical for repair
- () Part-by-Part repair
- () Lump Sum repair

- (X) The above survey was conducted on a 'without prejudice' basis.
Please note that the preliminary advice amount (Revised & Check Items)
stated are subject to consistency check, part prices and labour cost.