



CYCLE & CARRIAGE

CYCLE & CARRIAGE KIA PTE LTD
PANDAN GARDENS CUSTOMER SERVICE CENTRE
209 Pandan Gardens Singapore 609339 Tel: 65684555 Fax: 65651240

KIA
Movement that inspires

Co Reg No : 199405410K

ESTIMATE

GST Reg No : MR-8500111-X

Invoice Name & Address	Owner Name & Vehicle Info
LIM AGNES	Cust No/Name /LIM AGNES
BLK 329 SERANGOON AVENUE 3	Reg No/Reg Date SMD5517T / 27/08/201
#12-364	Date In/Mileage / 0
SINGAPORE 550329	Chassis No KNAF3416MK5011273
Contact No Mobile: 90171693	Engine No G4FGJH702640
	Make/Model KIA/CERATO 1.6 A SX G335
	Colour/Trim ABT PLATINUM GRAPHI/ WK SATURN BLACK

Account No	Terms	Date/Time Printed	CSE	Operator	WIP No			
CSM00081	Cash	07/12/2021/ 15:41	BLC	442 / CocoLu	43684			
Description of Goods / Services					Qty	Unit Price	Disc%	Amount
E PNT88000								400.00
RENEW REAR LOWER BUMPER, REPAIR REAR BUMPER								
E PNT98000								350.00
SPRAY PAINT FOR REAR BUMPER								
E PNT88000								60.00
REMOVE & INSTALL PARKING SENSOR								
A 90000001								30.00
CHECK WIRING & ELECTRICAL SYSTEM								
A 10028901								120.00
TO CARRY OUT DIAGNOSTIC CHECK ON ELECTRONIC CONTROL SYSTEM								
M SUNDRY								20.00
Sundry								
M COVER-RR BUMPER / CRU					1.00	651.00	00.00	651.00
M COVER-RR BUMPER LWR / RR					1.00	241.00	00.00	241.00
M COVER-RR BUMPER FOG LAMP, LH					1.00	88.00	00.00	88.00
M LAMP ASSY-SIDE T/SIGNAL, LH					1.00	181.00	00.00	181.00
M BRACKET ASSY-RR BPR SIDE UPR, L					1.00	25.00	00.00	25.00
M BEAM-RR BUMPER					1.00	318.00	00.00	318.00
M STAY-RR BUMPER LH					1.00	65.00	00.00	65.00

Estimate

Steve CLKK) 8/12/21, 9:30am

90-111 AL

Excess - ?

P/P

17 B/L 17

3 days

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis

Estimate

Steve CLKK)

8/12/21, 9:30am

00-111 AL

Excess - ?

P/P

M Bul M
3 days

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No Right of Appeal is allowed

Confirm & accepted by

Supplementary items must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature

Date

7% GST on **2,549.00** **178.43**
Total Payable 2,727.43

Authorized signatory and company stamp

Validity of this estimate is 14 days from date of quote. This is a computer generated document, no signature is required. Estimated costs quoted are excluding GST. We would mention that the above estimate is based on our initial inspection and does not include any additional parts or labour which may be required after repair work has commenced. Occasionally worn or damaged parts are discovered after work has started and needed for repairs or replacement. However, should this occur, we would advise you. Please be informed that a deposit of 50% of the above estimate is payable before commencement of the work. Payment for this may be made in cash, credit card or cheque. You must also agree to pay full amount for renewal of the windscreen in the event of inadvertent breakage in the course of renewing the rubber seal or other repair requiring the removal of the windscreen.