

Your Ref : SNM21D206910/C01/TAYHP

Date: 22nd Dec 2021

Our Ref : CS/CTI21012389/Uty3e2

M/s China Taiping Insurance (S) Pte Ltd

3 Anson Road #16-00

Springleaf Tower

Singapore 079909

(The Motor Claims Department)

Dear Sirs/Madam,

**AUTOMOBILE INSPECTION REPORT OF ACCIDENT VEHICLE SMP 594P
ACCIDENT ON 28/11/2021**

Instruction was received to inspect the vehicle Reg. No. SMP 594P. The inspection was conducted on 08/12/2021 at the premises of M/s Car City Auto Centre Pte Ltd, Blk 9006 Tampines Street 93 #01-198, Singapore 528840.

The following vehicle information was recorded:

Registration Number	: SMP 594P
Make/Model	: Mercedes Benz A180 FL Style (R17 HLG)
Year of Registration	: 2016
Body Colour	: Purple
Chassis Number	: WDD1760422J437030
Engine Capacity	: 1595 cc

The vehicle sustained damages at the front portion. (Details see photographs enclosed)

In view of this, we are of the opinion that it would be **uneconomical** to proceed with the repairs due to extensive repair cost and recommend it to be written off as **“Total Loss”**.

Market Value	S\$ 66,000.00 (est)
Less: LTA Reimbursement Value (RV)	(S\$ 32,194.00
Nett Liability	<u>S\$ 33,806.00</u> =====

Vehicle Inspected By:



CHUA KANG SENG
Licensed Appraiser



K.K.LAU
*MSc(Eng M), B Eng(Hons), Peng(UK),
MASME(USA), B Bus(Aust), MBA(UK),
IEng(UK), MIIE(mech), MinstAEA, MFIEA,
MIRTE, MIMI, MSAE, MCIAd, AM, NIJAAR(USA),
AM CATARI(CAN), M.MATA(USA), M.MdATA(USA),
Licensed Appraiser*

DISCLAIMER OF LIABILITY TO THIRD PARTIES:- This Report is made solely for the use and benefit of the Client named on the front page of this Report. No liability or responsibility whatsoever, in contract or tort, is accepted to any third party who may rely on the Report wholly or in part. Any third party acting or relying on this Report, in whole or in part, does so at his or her own risk.