

LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com;assignments@lkkauto.com

VEHICLE DAMAGE INSPECTION REPORT**Our File No:** CS/CTI21012390/ETY3N2**Date:** 09/02/2022**REFERENCE**

Handling Insurer:	China Taiping Insurance (Singapore) Pte. Ltd.	Policy No:	DMCVSNW00094142101
Claimant Vehicle No :	SJY3444H	Insured Vehicle No :	GW6854J
Date of Loss:	02/12/2021	Nature of Claim:	TP
		Claim No:	SNM21D207004/C02

DESCRIPTION & IDENTIFICATION OF VEHICLE

Reg No:	SJY3444H	Engine No:	CZD866835
Make & Model:	VOLKSWAGEN TOURAN, 1.4 TSI (A)	Chassis No:	WVGZZZ1TZJW071572
Reg. Date:	28/03/2018 (Man. Year: 2018)	Odometer:	45151 km
Colour:	White		
Engine Capacity:	1395 cc		
Market Value/New Car Price:	N/A		
Sum Insured (\$\$):	Market Value/New Car Price		

CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition:	Steering (Serviceable):	Yes	Footbrake (Serviceable):	Yes
Handbrake (Serviceable):	Yes	Engine Modification:	No	Pre-accident Condition:

CONDITION OF TYRES

Front Tyre Size:	215/55R17	Rear Tyre Size:	215/55R17
Front Left Side:	Michelin 5 mm	Rear Left Side:	Michelin 5 mm
Front Right Side:	Michelin 5 mm	Rear Right Side:	Michelin 5 mm

The above values represent the remaining tyre treads depth

COST OF CLAIMS	Repairer's	Adjuster's	Difference	Diff %
Parts	8,782.95	5,500.49	3,282.46	37.37
Miscellaneous Items	0.00	0.00	0.00	
Labour	11,630.00	5,450.00	6,180.00	53.14
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
Gross Total (\$\$)	20,412.95	10,950.49	9,462.46	46.36
+ GST 7.00/7.00% (\$\$)	1,428.91	766.53	662.38	46.36
Nett Amount (\$\$)	21,841.86	11,717.02	10,124.84	46.36

INSPECTION

Date of Assignment:	07/12/2021		
Date Inspected:	15/12/2021	Inspected At:	Volkswagen Group Singapore Pte Ltd 247 ALEXANDRA ROAD Singapore 159934
Estimated Period of Repair:	5.0 days		

Adjuster: CHEN TSUE YEE**Manager:** DENISE TAY KWEE CHENG

NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.

REPAIR DETAILS

Reference

Part Source:	(Last Synchronised: 09 Feb 2022)	
Parts:	N/A	VOLKSWAGEN TOURAN 1.4 TSI (A) (Model not available in database)
Labour:	Repairer's	(Price-denominated Standard List)
Print Code:	(Unsubmitted, no print-code for SJY3444H)	
Validity:	These estimates are valid only if they contain the print code (above) on all estimate pages, running page numbers with the END OF ESTIMATES marker on the last estimate page	
Further Info:	Items/values not in reference catalogue are prefixed with an asterisk *.	

Recommended Parts

No.	Qty	Part No. Particulars	Condition	Repairer's	Amount
1	1	*COVER FOR BUMPER PRIMED (REAR BUMPER)	Dented	1,443.25 FS	*1,443.25 FS
2	1	*SPOILER SATIN BLACK (REAR BUMPER SPOILER)	Cut	332.69 FS	*332.69 FS
3	4	*RIVET	Necessary	4.76 FS	*4.76 FS
4	1	*BUMPER (REAR REINFO)	Not Necessary	552.19 FS	*- FS
5	1	*ATTACHMENT STRIP (REAR BUMPER TOP BRACKET)	Not Necessary	65.63 FS	*- FS
6	1	*GUIDE PIECE LHR BUMPER BRACKET (UPPER)	Not Necessary	42.63 FS	*- FS
7	1	*GUIDE PIECE LHS BUMPER BRACKET (SIDE)	Not Necessary	34.85 FS	*- FS
8	1	*GUIDE PIECE RHS BUMPER BRACKET (UPPER)	Not Necessary	42.63 FS	*- FS
9	1	*GUIDE PIECE RHS BUMPER BRACKET (SIDE)	Not Necessary	34.85 FS	*- FS
10	4	*SPEED NUT	Necessary	6.52 FS	*6.52 FS
11	1	*LID	Dented	2,360.83 FS	*2,360.83 FS
12	2	*1K WINDOW ADHESIVE	Necessary	102.60 FS	*102.60 FS
13	1	*ALL PURPOSE CLEANER	Necessary	97.65 FS	*97.65 FS
14	1	*PRIMER	Necessary	28.52 FS	*28.52 FS
15	2	*APPLICATOR	Necessary	20.94 FS	*20.94 FS
16	1	*ACTIVATOR FOR PRECOATED W	Necessary	26.23 FS	*26.23 FS
17	1	*PACKING ADHESIVE REAR NUMBER PLATE PACKING	Necessary	30.60 FS	*30.60 FS
18	2	*RIVETTED CAP NUT	Necessary	5.00 FS	*5.00 FS
19	1	*INSCRIPTION BRIGHT CHROME (TOURAN WORD)	Necessary	74.51 FS	*74.51 FS
20	1	*VW SIGN BLACK/BRIGHT CHRO (VW LOGO)	Necessary	108.68 FS	*108.68 FS
21	1	*SPOILER SATIN BLACK LHS RR W/SCREEN SIDE TRIM (BLACK)	Necessary	267.95 FS	*267.95 FS
22	1	*SPOILER SATIN BLACK RHS RR W/SCREEN SIDE TRIM (BLACK)	Necessary	280.34 FS	*280.34 FS
23	1	*ADDITIONAL BRAKE LIGHT WI 3RD BRAKE LIGHT	Necessary	229.42 FS	*229.42 FS
24	1	*WIPER MOTOR	Not Necessary	423.81 FS	*- FS
25	1	*PUSHBUTTON FOR ELECTRIC L	Not Necessary	1,510.61 FS	*- FS
26	1	*HOOD LATCH BOOT LID LOCK	Not Necessary	175.26 FS	*- FS
27	1	*REAR NUMBER PLATE SUPPLY OF REGISTRATION PLATE	Cut	80.00 FS	*80.00 FS
28	1	*REVERSE SENSOR	Not Necessary	400.00 FS	*- FS

F=Franchise part. S=SpcNett.

Total Parts (\$\$) **8,782.95** **5,500.49**

Report was unsubmitted during this print-out.

Recommended Miscellaneous Items

There are no new miscellaneous items selected.

Recommended Labour

No	Particulars	Lab.Type	Repairer's	Amount
Labour Items				
1	SPRAY PAINTING	New	4,000.00	1,600.00
2	R&R REAR WINDSCREEN	New	840.00	840.00
3	TRANSFER BOOT LID MECHANISM	New	840.00	420.00
4	REAR WATER LEAK TEST	New	150.00	150.00
5	LABOUR	New	5,040.00	1,680.00
6	B&P CHECK SHORT CIRCUIT/HARNESS REPAIR	New	280.00	280.00
7	B&P DIAGNOSIS AND PROGRAMMING	New	480.00	480.00
Gross Labour Cost (\$\$)			11,630.00	5,450.00

Report was unsubmitted during this print-out.

< END OF ESTIMATES >