



A Subsidiary Of Autobacs Seven Co Ltd. Japan
8 Kaki Bukit Ave 4 #08-40/45/46 Premier@Kaki Bukit S(415875)
Tel : 6702 1555 Fax : 6702 1444 (Co Reg. No. 201500047H)
Email : tohguan@skauto.com.sg

TO	: CHINA TAIPING (SNA8076H)	DATE	: 7-Dec-21
ATTENTION	: MOTOR CLAIMS DEPARTMENT	JOB TYPE	: T/P CLAIMS
OWNER PARTICULAR			
OWNER ID	: 5XXXXX067J		
VEHICLE DETAILS			
VEHICLE NO.	: SMV1753J		
MODEL / MAKE	: MERC BENZ C180		
CHASSIS NO.	: WDD2040452A499479		
ACCIDENT DETAIL			
DATE	: 6-Dec-21		
TIME	: 13:05HRS	CONTACT PERSON	: MR. WINSON 91866680

QUOTATION SUMMARY PAGE 01

CLAIMS DETAIL : PARTS LIST

S/N	DESCRIPTION	QTY	UNIT LIST PRICE	TOTAL LIST PRICE
1	REAR TAILLAMP LOWER BRACKET LH/RH	2	\$ 95.00	\$ 190.00
2	REAR FENDER TOP GARNISH LH/RH	2	\$ 45.00	\$ 90.00
3	REAR FENDER TOP GARNISH CLIPS LH/RH	10	\$ 18.00	\$ 180.00
4	REAR BUMPER	1	\$ 1,615.00	\$ 1,615.00
5	REAR BUMPER CHROME MOLDING CENTER	1	\$ 140.00	\$ 140.00
6	REAR BUMPER CHROME MOLDING LH/RH	2	\$ 135.00	\$ 270.00
7	REAR BUMPER SIDE RETAINER LH/RH	2	\$ 55.00	\$ 110.00

TOTAL PRICE \$ 2,595.00
LESS -10% \$ (259.50)
SUB TOTAL PRICE \$ 2,335.50

CLAIMS DETAIL : PARTS LIST

S/N	DESCRIPTION	QTY	UNIT S/NETT	TOTAL S/NETT
1	REAR BUMPER CLIPS SET	1	\$ 80.00	\$ 80.00
2	REAR BUMPER REVERSE SENSOR SET (4 EYES)	1	\$ 450.00	\$ 450.00

TOTAL \$ 530.00

QUOTATION SUMMARY

PAGE 02

CLAIMS DETAIL : LABOUR CHARGES AND SPRAY PAINTING

TO DISMANTLE & REPLACED WITH PANEL BEATING ALL THE ACCIDENT PORTION	\$	500.00	250	
TO SPRAY PAINTING ALL THE ACCIDENT PORTION & POLISHING AFFECTED AREA	\$	500.00	250	
TO PERFORM LIGHTING & WIRING CHECK	\$	80.00	30	
TO DISMANTLE & REPLACED REAR BUMPER REVERSE SENSOR WITH DISTANCE SETTING	\$	150.00	50	
TO PERFORM DIAGNOSTIC CHECK & RESET MEMORY FAULT CODE TO IDENTIFICATION STANDARD	\$	350.00	x	
TO DISMANTLE & REINSTALL INTERIOR CARPET WITH OTHER ATTACHMENT PARTS COMPONENT TO FACILITATE REPAIR	\$	280.00	x	
TO PERFORM CONDUCT WATER LEAKAGE TEST OF ACCIDENT PORTION	\$	80.00	x	

TOTAL \$ 1,940.00

580

Adrian Lj
L/s 02 pages

ESTIMATE REPORT

TOTAL PARTS COST	:	\$	2,865.50
TOTAL LABOUR COST	:	\$	1,940.00
TOTAL REPAIR COST	:	\$	<u>4,805.50</u>

total: 2432.50
L/s: 1. SIC ✓

APPROVED DETAILS

NO. OF REPAIR DAYS : DAYS

REPAIR UNDER : PART BY PART OR LUMP SUM

DATE / TIME OF SURVEY :

SURVEYED BY / FROM :

CONTACT NUMBER :

EMAIL ADDRESS :

DATE / TIME OF RE-SURVEY :

EXCESS :

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer
Signature: