

Our Job Ref No : 305497152
Date : 10/12/21

ENGINEERING
ComfortDelGro Engineering Pte Ltd
59 Loyang Drive Singapore 508969
Fax: 6546 8156

FINALIZATION FORM

To : LKK
Attn : THEVAN
Vehicle Reg No. : SHA4399Z

Fax :

07/12/21

The survey and estimates of the repairs of the above-mentioned vehicle are as follows:-


Z The repair job shall bill to: AIG SLT8302Z
2. The finalized amount shall be:
(a) Spare Parts after List discount _____
(b) Labour Charges _____
Total for Part-By-Part Repair Cost _____
(c.) Lumpsum Repair (if applicable)
Total for Lumpsum repair cost after Less: _____
Final Lumpsum Repair cost \$2,800.00


3. Estimated normal period for repairs: 3 working days.

4. **We shall treat the above amount as Correct and Confirmed if there is no reply from you within 7 working days**

5. Thank you for your assistance.

We confirm the estimates and finalized amount

Signature : 
Name : CHIANG
Tel : 62148314
Fax : 65468156

Signature : 
Name : Thevan
Date : 21/5/12/21

For Official Use Only

| Item | Amount | Document Attached Yes or No | Confirm By (Signature) | Remarks |
|--|---------------|-----------------------------|------------------------|---------|
| 1. Rental Rate P/Day | | YES | | |
| 2. Loss of Income Paid | - | N | | |
| 3. Survey Fees | - | - | | |
| 4. LTA Search Fee | \$7.49/\$2.00 | | | |
| 5. Medical Fees (on behalf of driver, if applicable) | | | | |
| 6. Overrun | | | | |

Remarks:

COMFORT DEL GRO
ENGINEERING

VEHICLE 1 SHA4399Z

AIG

305497152

TYPE OF C: TP

SURVEY BY: THEVAN /LKK

DATE : 07/12/21

SUPPLEMENTARY OF PARTS AND LABOUR COSTS

[illegible]

REPAIR ESTIMATE*VEHICLE NO **SHA4399Z**DATE **07/12/2021 10.30**MAKE **REG.30.04.2019**MODEL **: HYUNDAI IONIQ G2****CHIANG /AIG**

| Qty | Parts Description/ Labour | Type | Unit Price | Amount |
|--|---|------|------------|-------------------|
| 1 | FRONT BUMPER COVER | | | \$430.90 |
| 1 | FRONT BUMPER BRACKET LH | | | \$35.00 |
| 1 | HEADLAMP LH | | | \$1,993.60 |
| 1 | FRONT BUMPER MOULDING CENTRE UPPER E RH | | | \$368.50 |
| 1 | DAY LIGHT LH | | | \$642.50 |
| 1 | FRONT BUMPER GRILLE LH | | | \$186.90 |
| 1 | FRONT WHEEL HUB COVER LH | | | \$346.40 |
| | SUB TOTAL | | | \$4,003.80 |
| | 20.00% | | | \$800.76 |
| | DISCOUNTED TOTAL | | | \$3,203.04 |
| | Labour Charge | | | |
| | Panel Beating | | | \$520.00 |
| | Spray Paint | | | \$600.00 |
| | Reset front wheel alignment | | | \$60.00 |
| | Check lighting | | | \$60.00 |
| | TOTAL LABOUR | | | \$1,240.00 |
| | ESTIMATE TOTAL | | | \$4,443.04 |
| This is an initial estimate based on a visual inspection of the above vehicle. The final repair quantum will be prepared after the vehicle is surveyed by a motor Surveyor appointed by the insurance company. | | | | |

Thevan @Lkharto.com
 82235769
 7/12/21 1700
 L/S after repair photo
 3 days wp

- LKK Auto Consultants hence notify the Repairer of the following:
- To resurvey before/after spray painting
 - To display damaged part(s) during resurvey
 - Parts prices are subject to confirmation
 - Third party survey is on a "Without Prejudice" basis
 - No illegal modification(s) is allowed
 - Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date: