

PROVI AUTOWORKS PTE LTD.

Blk 8 , Kaki Bukit Avenue 4 , #02-24

Premier @ Kaki Bukit Singapore 415875

Email: claims@PROVIAUTO.com

Tel: 6286 6060 Fax : 6286 7060

Office Use Only

Parts -25%	
SN	
Labour	
TOTAL	
LUMSUM	
ERV	33k

TO: AIG

Vehicle No : SLT 1021 K

Make & Model : TOYOTA AXIO

DATE: : 3/12/2021

No.	DESCRIPTION - PARTS	QTY	UNIT PRICE	PRICE	
1	FRONT FENDER LH / <i>buc</i>	1	\$ 684.00	\$ 684.00	465.2
2	FRONT FENDER COWLING LH <i>X NN</i>	1	\$ 215.00	\$ 215.00	
3	FRONT DOOR LH / <i>buc</i>	1	\$ 1,260.00	\$ 1,260.00	1100
4	FRONT DOOR OUTER MOULDING LH <i>X NN</i>	1	\$ 210.00	\$ 210.00	
5	FRONT DOOR FRAME SIDE BLACK STICKER LH <i>-buc</i>	2	\$ 67.00	\$ 134.00	✓
6	FRONT DOOR FRAME TOP BLACK STICKER LH <i>-buc</i>	1	\$ 75.00	\$ 75.00	✓
7	FRONT DOOR SIDE MIRROR LH / <i>bis</i>	1	\$ 1,257.00	\$ 1,257.00	692
8	FRONT DOOR HINGE LH <i>X NN</i>	2	\$ 125.20	\$ 250.40	
9	FRONT DOOR CHECKER LH <i>X NN</i>	1	\$ 89.00	\$ 89.00	
10	FRONT DOOR INNER LOCK LH <i>X NN</i>	1	\$ 417.50	\$ 417.50	
11	FRONT DOOR LOCK CATCH LH <i>X NN</i>	1	\$ 36.00	\$ 36.00	
12	FRONT DOOR WEATHERSTRIP LH <i>X NN</i>	1	\$ 198.60	\$ 198.60	
13	FRONT DOOR FRAM RUBBER LH <i>X NN</i>	1	\$ 385.00	\$ 385.00	
14	FRONT DOOR CHANNEL LH <i>X</i>	1	\$ 98.20	\$ 98.20	
15	FRONT DOOR CHANNEL SEAL LH <i>X</i>	1	\$ 178.60	\$ 178.60	
16	FRONT DOOR REGULATOR MOTOR LH <i>X</i>	1	\$ 455.60	\$ 455.60	
17	FRONT DOOR REGULATOR GEAR LH <i>X NN</i>	1	\$ 316.70	\$ 316.70	
18	FRONT DOOR INNER TRIM LH <i>X NN</i>	1	\$ 659.90	\$ 659.90	
19	FRONT DOOR INNER STEP GARNISH LH <i>X NN</i>	1	\$ 215.00	\$ 215.00	
20	FRONT DOOR OUTER STEP GARNISH LH <i>X NN</i>	1	\$ 112.00	\$ 112.00	
21	CENTER PILLER OUTER LH <i>X Repair</i>	1	\$ 845.00	\$ 845.00	
22	CENTER PILLER INNER LH <i>X NN</i>	1	\$ 568.00	\$ 568.00	
23	CENTER PILLER INNER TRIM LH <i>X NN</i>	1	\$ 485.00	\$ 485.00	
24	ROCKER PANEL LH <i>X Repair</i>	1	\$ 845.00	\$ 845.00	
25	FRONT LOWER ARM LH <i>X</i>	1	\$ 452.00	\$ 452.00	
26	FRONT KUNCKER ARM LH <i>X NN</i>	1	\$ 548.00	\$ 548.00	
27	FRONT KUNCKER BEALRING LH <i>X NN</i>	1	\$ 258.00	\$ 258.00	
28	FRONT SHOCK ABSOBER LH <i>X</i>	1	\$ 385.00	\$ 385.00	
29	REAR DOOR LH <i>X Repair</i>	1	\$ 1,213.60	\$ 1,213.60	
30	REAR DOOR FRAME SIDE BLACK STICKER LH <i>X</i>	2	\$ 68.90	\$ 137.80	
31	REAR DOOR FRAME TOP BLACK STICKER LH <i>X</i>	1	\$ 78.30	\$ 78.30	
32	REAR DOOR OUTER MOULDING LH <i>X NN</i>	1	\$ 201.00	\$ 201.00	
33	REAR DOOR HINGE LH <i>X</i>	2	\$ 113.00	\$ 226.00	
34	REAR DOOR CHECKER LH <i>X</i>	1	\$ 96.70	\$ 96.70	
35	REAR DOOR INNER LOCK LH <i>X</i>	1	\$ 426.90	\$ 426.90	

REAR DOOR LOCK CATCH LH	X	1	\$	36.00	\$	36.00
7 REAR DOOR WEATHERSTRIP LH	X	1	\$	198.00	\$	198.00
38 DRIVER SEAT BELT	X	1	\$	958.00	\$	958.00
39 SRS AIRBAG CONTOR UNIT	X	1	\$	1,258.00	\$	1,258.00

Subtotal : \$ 16,463.80 2466.2

Less 25% \$ 4,115.95

Parts Total : \$ 12,347.85 1849.65

NO.	SPECIAL NETT	QTY	UNIT PRICE	PRICE
1	FRONT FENDER SEALANT X	1	\$ 60.00	\$ 60.00
2	FRONT FENDER INNER SHILED CLIP SET X	1	\$ 50.00	\$ 50.00
3	FRONT DOOR SEALANT LH X	1	\$ 60.00	\$ 60.00
4	FRONT DOOR INNER TRIM CLIP SET X	1	\$ 40.00	\$ 40.00
5	CENTER PILLER OUTER SEALANT LH X	1	\$ 60.00	\$ 60.00
6	CENTER PILLER INNER SEALANT LH X	1	\$ 60.00	\$ 60.00
7	CENTER PILLER INNER TRIM CLIPS X	1	\$ 60.00	\$ 60.00
8	ROCKER PANEL SEALANT LH X	1	\$ 60.00	\$ 60.00
9	WHEEL RIM X	1	\$ 800.00	\$ 800.00
10	WHEEL TYRE X	1	\$ 400.00	\$ 400.00
11	REAR DOOR SEALANT LH X	1	\$ 60.00	\$ 60.00

Pa \$ 1,710.00

LABOUR	PRICE
PANEL BEATING, REMOVAL AND REPLACING PARTS	\$ 1,400.00
TO SPRAY PAINT AFFECTED AREA	\$ 1,400.00
TO PERFORM LIGHTING & WIRING CHECK	\$ 250.00
TO APPLY ANTI-RUST & TUFF KOTE	\$ 200.00
REMOVE AND INSTALL FRONT DOOR PART	\$ 250.00
REMOVE AND INSTALL REAR DOOR PART	\$ 250.00
REMOVE AND INSTALL FRONT UNDERCARRIGE	\$ 500.00
4 WHEEL WHEEL ALIGNMENT	\$ 120.00

LABOUR TOTAL \$ 4,370.00

Total Parts Cost \$ 14,057.85

Total Labour Cost \$ 4,370.00

Total Repair Cost \$ 18,427.85

3569.65

-20%: 2850

APPROVED DETAILS
NO. OF WORKING DAYS
PART BY PART OR LUMP SUM
DATE & TIME OF SURVEY
SURVEYED BY
CONTACT NUMBER
FAX NUMBER

5 Dng.
4/5.
07/12/21
Gmo Qiamy
After repair photos

LKK Auto Consultants hence notify
the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date: