

哈 汽 車 貿 易 服 務

HUP MOTOR TRADING & SERVICE

Blk 9004 Tampines Street 93 #01-120 Singapore 528838 Tel: 6784 0039 Fax: 6784 0076 Email: hupmotor@gmail.com Reg. No. 378091/00W

Our Ref: TP 3049/12/21

Supplementary item(s) must be resurveyed and
Your Ref: approval from Insurance Company

Date: 7th DEC 2021

MR TAN AH KIAT
BLK 9, #11-03,
JALAN MEMBINA, S(169483)

Acknowledged by Repairer
Signature:

Not Affected
2/5#2950
w/ght. Affected
5 days.

Estimate cost of repair to TOYOTA VIOS E 1.5 (A) Saloon - SJL 6156 L

1 pc rear bumper	Turn	\$	451.90	
10 pcs rear bumper clips	nee	\$	39.00	
1 pc rear bumper n/s reflector	CR	\$	82.80	
2 pcs rear bumper o/s & n/s top screw nut	nee	\$	11.60	
2 pcs rear bumper o/s & n/s top retainer	nee	\$	70.40	
2 pcs rear bumper o/s & n/s side retainer	nee	\$	184.80	
1 pc rear bumper n/s stay bracket	11	\$	67.30	X
1 pc rear bumper lower spoiler	De/moped	\$	388.20	
8 pcs rear bumper lower spoiler clips	11	\$	36.00	X
1 pc rear bumper lower spoiler sealant	nee	\$	60.00	
1 pc boot lid	R	\$	685.70	X
1 pc boot lid 'E' emblem	nee	\$	37.30	
1 pc boot lid 'VIOS' emblem	nee	\$	44.20	
1 pc boot lid logo emblem	nee	\$	51.20	
1 pc boot lid weatherstrip	11	\$	175.40	X
1 pc boot lid lock cable	11	\$	65.90	X
1 pc n/s tail lamp assy	CR	\$	357.20	
2 pcs n/s tail lamp clips & stopper	11	\$	10.40	X
1 pc rear end panel	11	\$	571.90	
1 pc rear end panel top garnish	11	\$	200.80	X
5 pcs rear end panel top garnish clips	11	\$	24.00	X
1 pc n/s tail lamp panel	R	\$	105.20	X
1 pc boot lid top spoiler sealant	11	\$	60.00	X
6 pcs rear n/s fender inner garnish clips	11	\$	33.00	X
		\$	3,814.20	
	Less 25%	\$	953.55	
		\$	2,860.65	

1 set rear bumper reverse sensor	shall	200.00	S.N	✓
1 pc rear number plate	11	50.00	S.N	X
To wiring check up for affected wiring system.		60.00	20	
To remove & refix carpet, floor mat, garnish, floor board cover & necessary parts.		150.00	80	
To remove, refix & re-pump sealant for boot lid spoiler & rear bumper lower spoiler.	11	160.00	X	
To respray Tuff-Kote on all affected accident parts.		90.00	30	
Labour charge to remove & cut out damaged parts, to jack, straighten & knocking out rear end panel, rear n/s fender, rear floor board panel & necessary parts, to weld, renew & align above parts.		1,200.00	700	
To putty & respray painting on all affected accident parts.		1,500.00	900	

5x16

P-2350-5

252
1762.87
3692.87

HUP MOTOR TRADING & SERVICE

\$ 6,270.65
=====