



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Affiliated to Federation Internationale Des Experts En Automobile

ALLIED WORLD ASSURANCE COMPANY LTD
(SINGAPORE BRANCH)
60 ANSON ROAD #08-01 (8th FLOOR)
MAPLETREE ANSON
SINGAPORE 079914

Ref: CS3/AWA21000915/T1f3e2-1

Date: 24/12/2021

Code: AWA

1. Policy Particulars :- THIRD PARTY CLAIM

Insured Veh.	GBH 1345H	Veh. Inspected	SLX 1032H
Policy No.	AVCPSB0099402000	Coverage (\$)	0.00
Claim No.	NSV2100011/HLF	Excess (\$)	0.00
Assign From	HEW LEE FONG	Assign Date	08/12/2021

2. Vehicle Particulars & Condition

Make & Model	HONDA SHUTTLE HYBRID 1.5 AUTO	c.c	1496
Engine No.	HIDDEN	Year of Reg.	2018
Chassis No.	GP71109548	Colour	BLACK
Odometer	229831 KM	Steering	IN ORDER
Brakes	IN ORDER	Modification	SPORTS RIM
General	GOOD		

3. Conditions of Tyres

	Size	Make	Balance
R/H Front Tyre	195/55 R15	DUNLOP	6 mm
L/H Front Tyre	195/55 R15	DUNLOP	6 mm
R/H Rear Tyre	195/55 R15	DUNLOP	6 mm
L/H Rear Tyre	195/55 R15	DUNLOP	6 mm

4. Description of Damages

THE VEHICLE SUSTAINED DAMAGES AT THE N/S BODY.
DAMAGES SEE DETAILS.

5. General Information

Accident Date	16/01/2021	Inspection Date	19/01/2021
Survey held at	GARAGE 13 PTE LTD 8 KAKI BUKIT AVE 4 #03-46 PREMIER 415875 SINGAPORE.		

5a. Remarks

A)THE INSPECTION WAS CONDUCTED ON A"WITHOUT PREJUDICE" BASIS.
B)IN ACCORDANCE TO YOUR INSTRUCTIONS, WE HAVE NOT AUTHORISED REPAIRS.

5b. Estimate Days of Repair

ESTIMATED NORMAL PERIOD FOR REPAIR: **5 Working Days**