

SJX4608B.

Toyota Vios. 1497cc

TP III
Ceilia.

MROS3HY930S168279

Front Bumper Distorted 481.30 ✓

Front Bumper Clips new 30(SN) ✓

Front Bumper Side Holder RH. Dented 35.70 ✓

Front Bumper Reinforcement. Dented 361.50 ✓

Front Bumper Top Bracket. torn 258.80 ✓

Front Bumper Fog Lamp RH. M 245.90 +

Front Bumper Fog Lamp Cover RH. M 85.40 +

Front Bumper Logo. new 65.10 ✓

Front Grille 3 new 320.10 +

Front Grille Clips. 20(SN) +

Headlamp RH. cut 458 ✓

Front RH Fender Dented 561.30 ✓

SJX4608B.

Front RH Fender Inner Shield.	tom	128.50 ✓
Front RH Fender Inner Shield clips	Nec	30(SN) ✓
Front RH Fender Emblem.	rm	38.50 ✓
Wiper Washer Tank.	HE m	110.50 X
Front RH wheel rim.	lt	680(SN) 400(SN)
Front RH Tyre.	XHE m	250(SN) X
Front RH Lower Arm.	} XHE m	364.20 X
Front RH Shock Absorber		272.90 X
Front RH Knuckle Arm.		558.90 X
Front RH Wheel Hub clw Bearing.	Damaged	183.80 ✓

2572.50

1929.67

S.N: 460.

SJX 4608B.

Panel Beating.

Spray Painting.

Wiring.

To spray full coat.

To dismantle front undercarriage.

To perform wheel alignment.

~~800~~ 500

~~800~~ 400

~~50~~ 30

~~150~~ 40

~~300~~ 80

~~180~~ 80

total: 3519.67

L/S: 2-81c.

05 Pays.

LKK Auto Consultants hence notify
the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and
is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date: