

TPAYA.

Asher.

SBW1222A. 2014 July.

Volkswagen Golf. 1395cc

WVWZZZA4ZEW43655

Reer	Number Plate	Dented	30(SN) /
Reer	Number Plate Holder	Deformed	30(SN) /
Reer	Number Plate Lamp x 02	$\frac{48.7}{m}$	$48.7 \times 2 = 97.40$. X
Reer	Bumper	Deformed	1251.40 /
Reer	Bumper Side Holder x 02	$\frac{65}{m}$	$65 \times 2 = 130$. X
Reer	Bumper Reinforcement	$\frac{495}{m}$	495.20 X
Reer	Bumper lower Garish.	lit	388.90 /
Reer	Bumper Centre Guide	cracked	185.40 /
Reer	Bumper Tow Cover	new	27.10 X
Reverse	Sensor x 02	2nd. 1 piece	$260 \times 2 = 520$ /
Reer	End Panel	$\frac{688.20}{m}$	688.20. X
Reer	End Panel Sealant.		60(SN) X

SBW1222A.

Panel Beating

~~800~~ 150

Spray Painting.

~~800~~ 250

Wiring

~~50~~ 30

To remove reverse sensor

~~100~~ 50

To remove upholstery.

150 X

To spray tuff coat

150 X

hist: 234570

Lebut: 580

len 10%: 2111.13

blbl: 2751.13

S.N: 60

H/S: 2.2k.

02 Days.

2.2k

LKK Auto Consultants hence notify
the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and
is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date: