

FASTECH AUTO PTE LTD
1 Kaki Bukit Ave 6 #01-48 Autobay
Singapore 417883
Tel No: 67452063/ 67467158 Fax No: 67458520
Tax Reg No : 200006262D

Mike Asher

Not Allowed
Mike
8/11/21
1/5 @ 2600
3 days.

VEHICLE No: SGT 6261K

1PC	REAR FENDER N/S	<i>R</i>		\$1,666.21	X
1PC	REAR FENDER UNDER SHIELD N/S	<i>11</i>		\$288.00	X
1SET	REAR FENDER UNDER SHIELD CLIPS N/S	<i>nee</i>		\$35.00	/
1PC	REAR BUMPER	<i>deep cut / de</i>	<i>1575.00</i>	\$1,675.00	/
1PC	REAR BUMPER LOWER GARNISH	<i>twi</i>	<i>455.21</i>	\$488.21	/
1PC	REAR BUMPER BEAM	<i>11</i>		\$605.00	X
1PC	REAR BUMPER SIDE RETAINER N/S	<i>one</i>	<i>65.00</i>	\$105.00	/
1SET	REAR BUMPER SIDE RETAINER CLIPS N/S	<i>nee</i>		\$20.00	/
1SET	REAR BUMPER CLIPS	<i>nee</i>	<i>(52)</i>	\$50.00	/
1PC	REAR END PANEL	<i>R</i>		\$688.25	X
				\$5,620.67	
TO CHECK WIRING				\$50.00	<i>20</i>
TO DISMANTLE & REFIX REAR PDC SENSOR				\$80.00	<i>50</i>
TO DISMANTLE & REFIX CUSHION UPHOLSTERY				\$120.00	<i>80</i>
TO SPRAY RUST PROOFING				<i>11</i> \$50.00	X
TO RESET & REPROGRAMME SYSTEM				<i>11</i> \$100.00	X
LABOUR FOR PANEL BEATING & REPLACED PARTS				\$850.00	<i>420</i>
TO PUTTY & SPRAY PAINTING				\$800.00	<i>600</i>
TOTAL				\$7,670.67	

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature

P-2200.21
52
P-2090.19
L-1170
3260.19
202
2608