

(08/11/13) wef
ASS. REC. BY: Marcus

REF: CS/CT121012423/443

ASSIGNMENT

From: _____ Date: _____

Estimated Cost: _____

OD / TP / WS / TP RES / OD RES / EVA / INV / MV

To Inspect Vehicle No: SLC 2042M

at Workshop m/s: 2nd Stirling

of: G39901P

Insured: _____

Policy No. _____

Claims No. _____

Sum Insured: _____

Excess: _____

(Client's Record)

Make of Veh: _____

(Policy Condition)

Remark: The veh had commenced its
repair at the time of inspection.



Bal. or Market Value: \$49k.

IDAC Accident Report: _____

Consistent? Yes or No

G/A / PR Seen: 5

Consistent? Yes or No

Est. Repairs: 5 days

Res: Yes or No

Lum Sum: 20 %

3 Val: Yes or No

CA / REV / REP. / 24 HRS

Vehicle: IN / OUT

Date: _____ Person Contacted: L7A 27659

Date / Time

Action / Instruction

Rep 9800

23/11/13 \$5200 informed repair
red:5597.14 ; 51%)

Veh No: SLC 5042M

Yr Regn: 17/5/16

Type: M/Car / M/Cycle / Bus / Van / Lorry / Taxi / Prime Mover /

Truck / Trailer or

Make: Toyota Sienna

cc 1496

Colour: white

A/C: Insured / Std / NI / NA

Sp Reading: 62077

T/Radio: Insured / Std / NI / NA

Eng/No: _____

C/No: NSP1707018699

Gen. Cond: Good / Fair / Poor / Burnt

Steering: In order / Jammed / Leaked / Burnt or

Brake: In order / Jammed / Leaked / Burnt or

Modi: Nil / S/Rim / STD A/Rim or

Tyre Size: F: 175/60R15

R: _____

BS / DUN / EXNOVA / GY / FS / LIZA / MIC / OHTSU / PIR / SUMI /

TOYO / YOKO or

Front

Rear

R/Bal. 6 mm

R/Bal. 6 mm

L/Bal. 6 mm

L/Bal. 6 mm

D.O.A. 4/12/14

D.O.I. 8/12/14

Survey held at _____

Des. of Damages: Frt / Rear / O/S / NIS / U/C / Rooftop or

The U/C / Chassis frame / Body Structure affected due to collision.

Date/Time, File Pass to?

☐

Preli. Report

1)

☐

Final Report

Date/Time, File Return to?

2)

Days Of Repair: 5

Resurvey No. of Trip: _____

Add Fee:

☐

Site Insp (\$

☐

Interview (\$

☐

Tech. Invs (\$

☐

Weekend (\$

Survey Fee

Transportation

Photos

Others

Report Format :

Lump Sum / I.B.I. (\$))

TOTAL



ZERO GRAVITY

2 Kaki Bukit Avenue 2, #01-25 Kaki Bukit Autohub, Singapore 417921
 Tel: +65 67412845 Fax No: +65 67412170
 Email: zero_gravity@singnet.com.sg
 Reg.No.: 5288887X

not attend
 car
 8/1/21
 1/2 @ 5200
 5 days
 take place after reg

QUOTATION

No : QT-000266

CHINA TAIPING INSURANCE (SINGAPORE) PTE LTD

3 ANSON ROAD

#16-00 SPRINGLEAF TOWER

SINGAPORE 079909

Attention: Motor Claim Department

TEL : 63896111

FAX : 62221033

Your Ref. : GBJ9901P
 Vehicle No. : SLC5042M
 Make & Model : TOYOTA SIENTA
 Chasis No. : NSP1707018699
 Engine No. : 2NR8573572
 Accident Date : 04/12/2021
 Policy No. : 5109233726-02
 Date : 08/12/2021
 Page : 1 of 3

Thank you for your inquiry. We are pleased to submit our quote as follows:

Item	Description	Qty	U/ Price S\$	Amount S\$
1	REAR BOOT <i>DD 1125.10</i>	1.0	PCS 1,229.85	1,229.85 ✓
2	LOGO <i>neu</i>	1.0	PCS 53.82	53.82 ✓
3	WINDSCREEN MOULDING (REAR) <i>neu</i>	1.0	PCS 72.24	72.24 ✓
4	REAR BOOT INNER TRIM BOARD <i>11</i>	1.0	PCS 145.40	145.40 X
5	REAR BOOT INNER TRIM BOARD CLIPS <i>11</i>	13.0	PCS 5.00	65.00 X
6	LAMP (REAR) (BOOT) <i>n/s car</i>	2.0	PCS 328.74	657.48 1PC
7	LAMP (L/H/R) <i>one</i>	1.0	PCS 462.02	462.02 ✓
8	LAMP (R/H/R) <i>one</i>	1.0	PCS 462.02	462.02 ✓
9	REAR BOOT GARNISH <i>one</i>	1.0	PCS 227.66	227.66 ✓
10	LAMP (NUMBER PLATE) <i>neu</i>	2.0	PCS 59.31	118.62 X
11	SWITCH (REAR BOOT) <i>11</i>	1.0	PCS 139.73	139.73 X
12	REAR BOOT ADJUSTER RUBBER <i>11</i>	2.0	PCS 18.88	37.76 X
13	REAR BOOT STOPPER BUSH <i>11</i>	2.0	PCS 15.51	31.02 X
14	REAR BOOT INNER LOCK <i>neu 305.10</i>	1.0	PCS 395.97	395.97 ✓
15	REAR BOOT LOCK STRIKER <i>11</i>	1.0	PCS 32.78	32.78 X
16	REAR BOOT ABSORBER <i>11</i>	2.0	PCS 240.24	480.48 X
17	REAR BOOT WEATHERSTRIP <i>neu 315.20</i>	1.0	PCS 399.32	399.32 ✓
18	WIPER MOTOR <i>neu 645.10</i>	1.0	PCS 928.79	928.79 ✓
19	WIPER ARM <i>11</i>	1.0	PCS 77.11	77.11 X
20	HANDLE (REAR BOOT) <i>11</i>	1.0	PCS 45.61	45.61 X
21	REAR BUMPER <i>DD/2</i>	1.0	PCS 396.00	396.00 ✓
22	BUMPER CLIP <i>neu</i>	6.0	PCS 6.00	36.00 ✓
23	BUMPER CAP <i>gross</i>	1.0	PCS 37.00	37.00 ✓
24	REAR BUMPER SPONGE <i>neu</i>	1.0	PCS 91.48	91.48 ✓
25	PROTECTOR BUMPER (SIDE) (L/H) <i>gross</i>	1.0	PCS 144.00	144.00 ✓
26	PROTECTOR BUMPER (SIDE) (R/H) <i>gross</i>	1.0	PCS 144.00	144.00 ✓
27	PROTECTOR BUMPER (CENTER) <i>gross</i>	1.0	PCS 205.00	205.00 ✓



ZERO GRAVITY

2 Kaki Bukit Avenue 2, #01-25 Kaki Bukit Autohub, Singapore 417921

Tel: +65 67412845 Fax No: +65 67412170

Email: zero_gravity@singnet.com.sg

Reg.No.: 52888887X

QUOTATION

No : QT-000266

CHINA TAIPING INSURANCE (SINGAPORE) PTE LTD

3 ANSON ROAD

#16-00 SPRINGLEAF TOWER

SINGAPORE 079909

Attention: Motor Claim Department

TEL : 63896111

FAX : 62221033

Your Ref. : GBJ9901P
 Vehicle No. : SLC5042M
 Make & Model : TOYOTA SIENTA
 Chasis No. : NSP1707018699
 Engine No. : 2NR8573572
 Accident Date : 04/12/2021
 Policy No. : 5109233726-02
 Date : 08/12/2021
 Page : 2 of 3

Thank you for your inquiry. We are pleased to submit our quote as follows:

Item	Description	Qty	U/ Price	Amount
			S\$	S\$
28	REAR BUMPER REFLECTOR (L/H) <i>CNE</i>	1.0	PCS 63.00	63.00 ✓
29	REAR BUMPER REFLECTOR (R/H) <i>11</i>	1.0	PCS 63.00	63.00 X
30	BUMPER SIDE RETAINER (L/H/R) <i>11</i>	1.0	PCS 88.00	88.00 X
31	BUMPER SIDE RETAINER (R/H/R) <i>11</i>	1.0	PCS 88.00	88.00 X
32	LAMP BRACKET (L/H/R) <i>CNE</i>	1.0	PCS 95.00	95.00 ✓
33	LAMP BRACKET (R/H/R) <i>CNE</i>	1.0	PCS 95.00	95.00 ✓
34	REAR END PANEL (INNER) <i>11</i>	1.0	PCS 680.00	680.00 X
35	REAR END PANEL (OUTER) <i>11</i>	1.0	PCS 418.00	418.00 ✓
36	REAR END PANEL GARNISH <i>11</i>	1.0	PCS 192.21	192.21 ✓
37	SENSOR (REAR BOOT) <i>SVC</i>	1.0	PCS 295.45	295.45 X
38	SPARE TYRE BOARD <i>11</i>	1.0	PCS 469.03	469.03 X
39	Discount 25 %			-2,415.71
40	SubTotal (L)			7,247.14
41	REAR END PANEL SEALANT <i>11</i>	1.0	BTL 50.00	50.00 ✓
42	SEALANT (WINDSCREEN) <i>11</i>	1.0	PCS 50.00	50.00 40
43	REVERSE SENSOR <i>11</i>	1.0	SET 280.00	280.00 200
44	REVERSE CAMERA <i>11</i>	1.0	SET 450.00	450.00 X
45	SubTotal (S)			830.00
46	PANEL BEAT & REPAIR REAR DAMAGE	1.0	X	1,000.00 680
47	TO PUTTY AND RE-SPRAY AFFECTED PORTION	1.0	X	900.00 800
48	TO PROVIDE UNDER TURFCODE	1.0	X	120.00 60
49	TO CHECK WIRING SYSTEM, FOCUS LIGHTINGS	1.0	X	50.00 20
50	TO CHECK WIRING SYSTEM & ENSURE FUNCTION OF COMPONENT	1.0	X	80.00
51	TO REMOVE AND REFIT REAR WINDSCREEN GLASS	1.0	X	150.00 120
52	TO REMOVE REVERSE SENSOR/CAMERA	1.0	X	150.00 50
53	TO TRANSFER REAR BOOT FITTING	1.0	X	120.00 60
54	TO REMOVE AND REFIT COMPONENTS / FACILITATE THE REPAIR	1.0	X	150.00 80



ZERO GRAVITY

2 Kaki Bukit Avenue 2, #01-25 Kaki Bukit Autohub, Singapore 417921
Tel: +65 67412845 Fax No: +65 67412170
Email: zero_gravity@singnet.com.sg
Reg.No.: 52888887X

QUOTATION

No : QT-000266

CHINA TAIPING INSURANCE (SINGAPORE) PTE LTD

3 ANSON ROAD

#16-00 SPRINGLEAF TOWER

SINGAPORE 079909

Attention: Motor Claim Department

TEL : 63896111

FAX : 62221033

Your Ref. : GBJ9901P
Vehicle No. : SLC5042M
Make & Model : TOYOTA SIENIA
Chasis No. : NSP1707018699
Engine No. : 2NR8573572
Accident Date : 04/12/2021
Policy No. : 5109233726-02
Date : 08/12/2021
Page : 3 of 3

Thank you for your inquiry. We are pleased to submit our quote as follows:

Item	Description	Qty	U/ Price S\$	Amount S\$
55	SubTotal (LABOUR)			2,720.00

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date:

P-5843.69
25-2
P-4282.76
S.N-290
L-1870
6542.76

SINGAPORE DOLLAR TEN THOUSAND SEVEN HUNDRED NINETY SEVEN AND CENTS
FOURTEEN ONLY

E. & O.E

Total	S\$	10,797.14
Discount	S\$	0.00
Net Total	S\$	10,797.14

Terms: C.O.D.

Customer's Signature/Co. Stamp

ZERO GRAVITY

Any claim for faulty workmanship is limited solely to the rectification free of cost of such work, no claim for loss consequential or otherwise being admissible. Any objections to the validity of these charges must be made seven (7) days from the date of this invoice otherwise it is assumed that this bill is accepted as correct.


> Back to OneMotoring

Enquire PARF/COE Rebate for Registered Vehicle

Vehicle Owner Particulars	
Owner ID Type:	Singapore NRIC
Owner ID:	249C
Vehicle Details	
Vehicle No.:	SLC5042M
Vehicle to be Exported:	No
Intended Deregistration Date:	08 Dec 2021
Vehicle Make:	TOYOTA
Vehicle Model:	SIENTA 1.5X CVT ABS D/AIRBAG 2WD 5DR
Primary Colour:	White
Manufacturing Year:	2015
Engine No.:	2NR8573572
Chassis No.:	NSP1707018699
Maximum Power Output:	80.0 kW (107 bhp)
Open Market Value:	\$19,152.00
Original Registration Date:	17 May 2016
First Registration Date:	17 May 2016
Transfer Count:	0
Actual ARF Paid:	\$9,152.00 4876
Intended PARF Rebate Details	
PARF Eligibility:	Yes
PARF Eligibility Expiry Date:	16 May 2026
PARF Rebate Amount:	\$6,406.00
Intended COE Rebate Details	
COE Expiry Date:	16 May 2026
COE Category:	A - Car up to 1600cc & 97kW (130bhp)
COE Period(Years):	10
QP Paid:	\$47,889.00
COE Rebate Amount:	\$21,253.00
Total Rebate Amount:	\$27,659.00

The information contained herein is correct as at 08 Dec 2021

OK




Post an Advertisement
Sell it yourself! Advertise it at just
\$68 until it's SOLD!

Post an Ad Advertiser Login Ways of Selling

01/2012 Land Rover Discovery 2.0A S14 HSE, \$246,888



One Owner, SUV, 7-Seater, Agent
Maintained, Twin Sunroof, High
Trade-In & Loan Avail.
SB Motoring Pte Ltd StarAd



Browse by Category

« Back (1 2) Next »

Sort by Date Posted 20 results/page

33 vehicles



Sienta

Advanced Search

Search

Make Model Price Depreciation Reg Date Eng Cap Mileage Veh Type Status

Search Selection

Sienta Any Any 2016 Any Any Any Available



Toyota Sienta 1.5A G \$54,000 \$10,860 /yr 24-Jun-2016 1,496 cc MPV Available

Elegant Silver MPV, One Owner Only, With 2 Power Sliding Doors, Low Maintenance Cost, Very Well Maintained, Easy Financing, Flexible Prime Motor & Leasing

Posted: 07-Dec-2021 Tags: 2016 Toyota Sienta, Toyota Sienta, Toyota, Sienta



Toyota Sienta 1.5A G \$53,800 \$10,130 /yr 05-Oct-2016 1,496 cc 72,000 km MPV Available

Flawless Well Taken Care Sienta G Model Still Looks Like New Car. Economical Yet Easy Maintenance. Ideal For Family Transportation. V. Viking Motor Pte Ltd

Posted: 07-Dec-2021 Tags: 2016 Toyota Sienta, Toyota Sienta, Toyota, Sienta



Toyota Sienta 1.5A X \$50,800 \$11,050 /yr 24-Mar-2016 1,496 cc 81,309 km MPV Available

A Perfect 7 Seaters Mini MPV With Power Sliding Door. Strictly Non PHV Car And It's Only 1 Owner Count. Brand New Paint Work Done... Imperium Car Motor Pte Ltd

Posted: 06-Dec-2021 Tags: 2016 Toyota Sienta, Toyota Sienta, Toyota, Sienta



Toyota Sienta 1.5A G \$53,300 \$10,140 /yr 21-Sep-2016 1,496 cc 70,000 km MPV Available

High Spec G Model, Family Friendly 7-Seater, Spacious And Comfortable, Superb Fuel Efficiency, Low Maintenance Cost, Well Maintained. Viking Motor Pte Ltd

Posted: 06-Dec-2021 Tags: 2016 Toyota Sienta, Toyota Sienta, Toyota, Sienta



Private hire drivers love these 7 cars

Thinking of becoming a private hire driver? We select seven of the best private hire cars for you to choose from and list out where to rent them. Read this article



Toyota Sienta 1.5A G \$50,888 \$9,900 /yr 11-Aug-2016 1,496 cc 61,258 km MPV Available

Higher Spec G Model Toyota Sienta 7 Seater With Dual Power Sliding Doors, Superb Condition. Additional 1 More Owner Due To Internal. PREMIUM AD

Posted: 05-Dec-2021 Tags: 2016 Toyota Sienta, Toyota Sienta, Toyota, Sienta



Toyota Sienta 1.5A X \$52,800 \$10,650 /yr 12-Jul-2016 1,496 cc 66,000 km MPV Available

Free Premium Warranty With Extra Wear & Tear Coverage For Your Added Assurance, Best Fuel Saving MPV With Easy Foldable Seats!... EDM Cars Pte Ltd PREMIUM AD

Posted: 05-Dec-2021 Tags: 2016 Toyota Sienta, Toyota Sienta, Toyota, Sienta

Toyota Sienta 1.5A G \$54,800 \$10,810 /yr 19-May-2016 1,496 cc 87,564 km MPV Available

Immediate Loan Approval! Highest Spec G Model With Dual Power Sliding Door! \$1000 Drive Away Available! 100% Major Accident Free. PREMIUM AD

Posted: 05-Dec-2021 Tags: 2016 Toyota Sienta, Toyota Sienta, Toyota, Sienta

Compare