



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Affiliated to Federation Internationale Des Experts En Automobile				
AXA INSURANCE PTE LTD 8 SHENTON WAY #24-01 AXA TOWERSINGAPORE 068811 ATTN:CYNTHIA			Ref: CC4/ASM21012433/Vpa3q2 Date: 15/12/2022 Code: ASM	
1. Policy Particulars :- THIRD PARTY CLAIM				
	Insured Veh.	SHA 217S	Veh. Inspected	GBB 2860L
	Policy No.	P2419140	Coverage (\$)	0.00
	Claim No.	S1M03NO7	Excess (\$)	0.00
	Assign From		Assign Date	08/12/2021
2. Vehicle Particulars & Condition				
	Make & Model	TOYOTA DYNA 100	c.c	2982
	Engine No.	HIDDEN	Year of Reg.	2008
	Chassis No.	JTFNT24Y50K400060	Colour	WHITE
	Odometer	230786 KM	Steering	IN ORDER
	Brakes	IN ORDER	Modification	SPORTS RIM
	General	GOOD		
3. Conditions of Tyres				
		Size	Make	Balance
	R/H Front Tyre	195 R15	FIRENZA	5 mm
	L/H Front Tyre	195 R15	FIRENZA	5 mm
	R/H Rear Tyre	155 R12C	FIRENZA	5 mm
	L/H Rear Tyre	155 R12C	FIRENZA	5 mm
4. Description of Damages				
	THE VEHICLE SUSTAINED DAMAGES AT THE REAR PORTION AND O/S BODY. DAMAGES SEE DETAILS.			
5. General Information				
	Accident Date	04/12/2021	Inspection Date	09/12/2021
	Survey held at	N-51 AUTOMOTIVE PL 2 KAKI BUKIT AVE 2 #01-17 KAKI BUKIT AUTOHUB SINGAPORE 417921		
5a. Remarks				
	A)THE INSPECTION WAS CONDUCTED ON A"WITHOUT PREJUDICE" BASIS. B)IN ACCORDANCE TO YOUR INSTRUCTIONS, WE HAVE NOT AUTHORISED REPAIRS.			
5b. Estimate Days of Repair				
	ESTIMATED NORMAL PERIOD FOR REPAIR:		5 Working Days	