

N-51 AUTOMOTIVE PTE LTD

Kaki Bukit AutoHub
2 Kaki Bukit Ave 2
#01-17 / #01-18 / Heavy Vehicle #01-08 / Spray Painting #02-27
Singapore 417921 Tel No. : +65 6842 0051 Fax No. : +65 6741 0510
E-Mail : sales@n51.com.sg
Company Reg. No. : 200616038C
GST Registration No. : 200616038C

TAN SOON MUI PTE LTD
8 WOODLANDS TERRACE
SINGAPORE 738433

Contact : 90683636, 86868988

TAX INVOICE

Repair Code : CLM17014

Date in : 06/12/2021

Vehicle Num. : GBB2860L

Model : TOYOTA DYNA 100 MANUAL 3SEATER

Chassis/Eng# : JTFNT24Y50K400060/1KD1883840

Parts and Labour Assessment

Description of part	Qty	Unit Price	Amount
FRONT RH DOOR	1 NE	1658.80	F 1,658.80 XN
FRONT RH END PILLAR EMBLEM 'TOYOTA D4D'	1 NE	47.90	AAC / 47.90 XN
REAR NUMBER PLATE BRACKET	1	291.40	BT / 291.40 107
REAR NUMBER PLATE LAMP L/R	2	69.60	CR / 139.20
REAR TAIL LAMP BRACKET L/R	2	93.00	BT / 186.00
REAR TAIL LAMP L/R	2	251.30	SCR / 502.60 432
Subtotal before discount			2,825.90
Percentage discount 25%			1132.18 648.92 706.48
Sub-total 1			2,119.43
FRONT RH DOOR COMPANY DETAIL STICKER	1 NE	60.00	30 60.00 XN
FRONT RH DOOR INNER TRIM BOARD CLIPS - SET	1 NE	50.00	20 50.00 XN
REAR CABIN FRONT ALUMINIUM PANEL	1 NE	1000.00	CA 1,000.00 XN
REAR CABIN FRONT ALUMINIUM PANEL REPAIR KIT	1 NE	180.00	120 180.00 XN
REAR END SUPPORT PANEL	1	800.00	rx 800.00
REAR NUMBER PLATE	1	25.00	NEC / 25.00
REAR NUMBER PLATE HOLDER	1	50.00	NEC 30 50.00
REAR SWING DOOR '6PAX' STICKER	1	25.00	NEC / 25.00
REAR SWING DOOR '70KM/H' STICKER	1	25.00	NEC / 25.00

*** This is a computer-generated document which requires no signature.***

Kaki Bukit AutoHub
2 Kaki Bukit Ave 2
#01-17 / #01-18 Heavy Vehicle #01-08 / Spray Painting #02-27
Singapore 417921 Tel No. : +65 6842 0051 Fax No. : +65 6741 0510
E-Mail : sales@n51.com.sg
Company Reg. No. : 200616038C
GST Registration No. : 200616038C

TAN SOON MUI PTE LTD
8 WOODLANDS TERRACE
SINGAPORE 738433

Contact : 90683636, 86868988

TAX INVOICE

Repair Code : CLM17014

Date in : 06/12/2021

Vehicle Num. : GBB2860L

Model : TOYOTA DYNA 100 MANUAL 3SEATER

Chassis/Eng# : JTFNT24Y50K400060/1KD1883840

REAR SWING DOOR 'AR' STICKER	1	NEC	60.00	25	60.00
REAR SWING DOOR 'T HOOK BRACKET' BRACKET L/R	2		80.00	SVC X	160.00
REAR SWING DOOR ALUMINIUM PANEL L/R	2 2	1400 1400	1800.00	DT	3,600.00
REAR SWING DOOR RH ALUMINIUM PILLAR PANEL	1	300	900.00	DT	900.00
REAR SWING DOOR RH OPENER BAR	1		450.00	SVC	450.00
REAR SWING DOOR RH OPENER BAR HOLDER BRACKET	1		100.00	SVC X	100.00
Subtotal before discount					7,485.00

Percentage discount 0%

Sub-total 2 ~~1586 6030~~ 7,485.00
Parts-total ~~21248 5670 72~~ 9,604.43

LABOUR

To remove, reinstall electrical wiring harness, check lighting, (to FR)

To transfer door glass, regulator gear, motor, railing, channel, trim board, mechanism lock and handle.

To re-spray painting on the change bodyparts, repair portion, and where consistent to the accident.

To provide labour, workmanship to change the above damaged bodyparts, repair, re-construct and re-align body structure, body alignments and damaged consistent to the accident.

To apply anti-rust chemical on repaired and replaced panel.

Labour Total 2,950.00

Parts & Labour Total ~~3232.48 6098 72~~ 12,554.43

Thru LKK Auto Hub
867 33764
10/12/21 1600
LIS slays wp

*** This is a computer-generated document which requires no signature.

page 2

LKK Auto Consultants hence notify

the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date: