

## RESTRICTED

3AMB / 34FMD  
71, Sembawang Rd  
Blk 615 #01-05  
Singapore 779121

Ref: 3AMB/34FMD/CSW KHATIB

Date: 06/8/2020

Tel: 6477 2026

Fax: 6477 2025

FINAL COST OF REPAIR

Vehicle No.	MID34081	Type of Repair	ACCIDENT
Vehicle Type	FORD EVREST,FFR,0.7 TONS	SR / SWD	-
Unit	KHATIB CMTL	MO No.	8202473990

S/N	Damaged Description	Remarks
1	NO DAMAGES TO REAR TOWING JAW	
	-----Last Entry-----	

S/N	Type of Repair Cost	Amount
1	LABOUR COST \$56.38/HR @ 1 HR	\$56.38
2	MATERIALS	NIL
3	GENERAL COST (TOWING)	NIL
4	ASSESSMENT FEE	NIL
	TOTAL REPAIR COST	\$56.38

Remarks:

*\*Above estimated costings*

SAF 1222 Ref No.: BB71 (1TPTBN)/D/KHN/040/20)

Prepared by:

ME3 AZMAN  
MAO CSW KHATIB  
3AMB/34FMD

RESTRICTED