

CHINA TAIPING

Vehicle number	SLX1033E
Make / Model	TOYOTA SIENTA HYBRID
Chassis number	NHP1707115189
Accident date	6/12/21
Reference	2112-12

Qty	Particulars	Unit Price - SGD \$
<u>PARTS REPLACEMENT - LIST ITEMS</u>		
1	BONNET LOCK	103.29 / Sew
1	BRACE PANEL	145.31 / BT DT
1	FRONT SUPPORT PANEL	1136.30 7844 891.6 dented
1	OIL COOLER	759.66 / BT
		2144.56
	Less 25%	536.14
		1608.42
		1608.42

PARTS REPLACEMENT - SPECIAL NETT ITEMS		
1	TAILGATE WINDSCREEN SOLAR FIRM	350.00 2 XNN
1 SET	REVERSE SENSOR	300.00 200 Cyt
1 SET	REAR BUMPER CLIP	30.00 70 N/C
1 SET	FENDER INNER TRIM BOARD CLIP	50.00 200 nec
1 SET	END PANEL TOP GARNISH CLIP	50.00 XNN
1 SET	TAILGATE INNER TRIM BOARD CLIP	50.00 200 nec
1	REAR NUMBER PLATE	80.00 240 BT
1	WINDSCREEN SEALANT	150.00 60
1 SET	FRONT BUMPER CLIP	30.00 70 N/C
1 SET	FRONT GRILLE CLIP	50.00 70 N/C
1	FRONT NUMBER PLATE	80.00 240
Subtotal		1220.00
Balance C/F		23912.85
LABOUR AND MISCELLANEOUS CHARGES		
1	CHECK WIRING AND LIGHTNING SYSTEM	150.00 100 30
2	RE-PROGRAMMING AFTER REPAIR	400.00 100
3	REMOVE AND REFIT TRIMS & GARNISHES	200.00 40
4	REMOVE AND REPLACE REVERSE SENSOR	200.00 70
5	REMOVE AND REFIT REAR WINDSCREEN	200.00 70 120
6	REMYE AND REFIT REAR SEAT TO FACILITATE REPAIR	400.00 70
7	REMOVE AND REPLACE HYBRID BATTERY	500.00 200 XNN
8	REMOVE AND REFIT TAILGATE ATTACHMENT	200.00 30
9	PANEL BEATING ON AFFECTED AREAS	2400.00 800 1000 1400
10	SPRAY PAINTING ON AFFECTED AREAS	2400.00 800 1000 1200
11	APPLY ANTI RUST ON AFFECTED AREAS	150.00 100 40
Subtotal		7200.00
Grand total		31112.85

Thuan @ Lkhauto.com

82235769

10/12/21 1030

L/S after repair photo

8 days wp

11000

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

D. E.

CHINA TAIPING

Vehicle number	SLX1033E ✓
Make / Model	TOYOTA SIENTA HYBRID
Chassis number	NHP1707115189
Accident date	6/12/21
Reference	2112-12

Qty	Particulars	Unit Price - SGD \$
PARTS REPLACEMENT - LIST ITEMS		
1	TAILGATE	1245.09 / PT
2	TAILGATE ABSORBER	533.50 X SVC
2	TAILGATE HINGE	212.74 X SVC
1	TAILGATE INNER TRIM	151.80 X SVC
1	TAILGATE OUTER GARNISH	228.69 / PT
1	TAILGATE INNER LAMP LH	209.99 X CRA
1	TAILGATE INNER LAMP RH	209.99 X CRA
1	TAILGATE EMBLEM - LOGO	74.25 / NAC
1	TAILGATE EMBLEM - HYBRID TECHNOLOGY	57.20 / NAC
1	TAILGATE LOCK	514.36 / Jan 387-9
1	TAILGATE STRIKER	28.38 X R
1	TAILGATE WEATHERSTRIP	409.53 X 360 / Cut
1	TAILGATE INNER BOARD HANDLE	35.70 / PT
2	REAR WINDSCREEN MOULDING	99.00 / NAC
1	REAR TAILLAMP LH	389.18 X CRA
1	REAR TAILLAMP RH	389.18 X CRA
1	REAR CORNER BUMPER	615.12 X SVC
1	REAR BUMPER	350.02 / PT
1	REAR BUMPER TOP GARNISH	209.00 / PT
2	REAR BUMPER RETAINER	155.10 X SVC
2	REAR BUMPER REFLECTOR	131.56 X SVC
2	REAR BUMPER REFLECTOR GARNISH	284.02 X SVC
1	REAR END PANEL	476.96 X BT
1	REAR END PANEL TOP GARNISH	162.25 X BT
1	SPARE TYRE TOP BOARD	307.89 X CRA X SVC
1	SPARE TYRE INNER BOARD	491.37 X CRA / Cut
1	FLOOR PANEL	768.57 X R
1	FLOOR PANEL UNDERTRAY	438.46 X R
1	REAR EXHAUST SILENCER	885.94 X R
2	REAR EXHAUST MOUNTING	108.02 X SVC
1	WIPER MOTOR	1309.55 X SVC
1	WIPER ARM	161.70 X SVC
1	HYBRID BATTERY	5027.70 X SVC
1	HYBRID BATTERY TRAY	379.20 X SVC
2	REAR FENDER INNER TRIM BOARD	1379.40 X Cut 1218
1	FRONT BUMPER	545.38 / PT
2	FRONT BUMPER RETAINER	105.82 X NAC
1	FRONT BUMPER REINFORCEMENT	394.13 X SVC
1	FRONT BUMPER SPONGE	108.20 X Cut
2	FRONT BUMPER SIDE GARNISH	242.00 X SVC
1	BONNET	742.40 X BT
2	BONNET HINGE	67.00 X SVC
1	RADIATOR	2577.20 X SVC
1	FAN HOUSING	339.40 X SVC
1	RADIATOR FAN MOTOR	655.70 X SVC
1	AIRCON CONDENSOR	1357.40 X SVC 1138 / BT
1	FRONT SUPPORT PANEL	88.00 X PT
1	FRONT SUPPORT PANEL TOP GARNISH	64.90 X Cut
2	FRONT HEADLAMP	3562.46 X Cut 1980
1	FRONT GRILLE	900.24 X Cut 546-25
1	FRONT GRILLE EMBLEM - LOGO	76.50 / PT
		30257.14
Less 25%		7564.29
		22692.85