

Trans-cab Auto Services Pte Ltd

No. 2 Ang Mo Kio Street 63 Singapore 569111

Tel No. : 6287 6666 Fax No. : 6257 1330

CO./GST Reg. No. 201019626G

SHD5358U**AAD2112-025***Not Authorized
Presumy B4 paint*

Vehicle No.:

Chassis No.:

Vehicle Make:

Vehicle Model:

Date of Accident :

Third Party Insurer :

Date of Registration:

07 DEC 2021**SHD5358U**

JTDKB3FU403078763

TOYOTA

PRIUS

03/12/2021

AIG.

11/01/2019

PART

- 1 COVER, REAR BUMPER
- 1 COVER, REAR BUMPER, LOWER
- 1 FILLER, REAR BUMPER EXTENSION, RH
- 1 GUARD, REAR BUMPER, CENTER
- 1 REINFORCEMENT SUB-ASSY, REAR BUMPER
- 1 FILLER, REAR BUMPER EXTENSION, RH
- 1 COVER, BACK DOOR TRIM
- 1 PANEL SUB-ASSY, BODY LOWER BACK
- 1 LENS AND BODY, REAR LAMP, RH
- 1 LENS & BODY, REAR COMBINATION LAMP, RH

LIST

\$	<i>Bu / cm</i>	442.60	✓
\$	<i>Sn</i>	15.40	X
\$	<i>Bu</i>	123.70	✓
\$	<i>nd / dir</i>	576.30	✓
\$	<i>R</i>	332.70	X
\$	<i>Sn</i>	123.70	X
\$	<i>Sn</i>	24.90	X
\$	<i>R</i>	650.30	X
\$	<i>Sn</i>	502.00	X
\$	<i>Bu</i>	451.80	✓

TOTAL \$ 3,243.40**25% \$ 810.85****\$ 2,432.55****Special Nett**

- 1SET PARKING AID
- 1 REAR BUMPER CLIP
- 1 REAR TAIL LAMP CLIP
- 1 END PANEL INNER TRIM CLIP
- 1 CLIP(FOR REAR DOOR TRIM BOARD)
- 2 WINDSCREEN SEALANT
- 1 WINDSCREEN MOULDING
- 1 WINDSCREEN INNER SPONGE SEAL

\$	<i>Sn</i>	700.00	X
\$	<i>nn</i>	65.00	<i>Sosun</i>
\$	<i>nn</i>	65.00	X
\$	<i>nn</i>	60.00	X
\$	<i>nn</i>	65.00	X
\$	<i>nn</i>	150.00	X
\$	<i>nn</i>	200.00	X
\$	<i>nn</i>	130.00	X

TOTAL \$ 735.00**TOTAL PARTS \$ 8,543.40****LABOUR**

AAD2112-025

Trans-cab Auto Services Pte Ltd

No. 2 Ang Mo Kio Street 63 Singapore 569111

Tel No. : 6287 6666 Fax No. : 6257 1330

CO./GST Reg. No. 201019626G

SHD5358U

To Rust-Proofing and apply undercoat Of The Affected Areas.	\$	<i>nn</i> 250.00	<i>X</i>
Putty And Spray Painting Of The Affected Portion.	\$	1,800.00	<i>500/</i>
To remove and refit interior fittings, trimings, garnish, fittings and other, to enable repair.	\$	<i>nn</i> 380.00	<i>X</i>
To Check Electrical Lighting Concerned.	\$	170.00	<i>20/</i>
Panel Beating, Knocking And Straightening The Necessary Portion, Remove And Renewal Of Parts, Adjust And Realign The Same	\$	3,000.00	<i>200/</i>
To check steering geometry and computer wheel alignment	\$	<i>nn</i> 220.00	<i>X</i>
To transfer of rear fender panel fittings, attachment and perform water seepage test.	\$	<i>nn</i> 170.00	<i>X</i>
TOTAL	\$	5,990.00	
Over All Total	\$	16,965.95	

(PART-BY-PART) Repair Days

20 Days

2 days

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date: