

SKM GAERAGE & TRADING LLP

10 Kaki Bukit Road 2 #03-31 First East Centre S (417868)

Tel: 9640 7853 Fax: 6443 0198

UEN No: T16LL0375F

China Taiping Insurance (S) Pte Ltd

Motor claims Department,

Vehicle No: SNB 1576Y

Model: Mercedes

Owner : Koh Jia Jun

LIK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Signature No: DMPCSNW0019886210

Accident Date: 24/11/2021

ESTIMATE REPAIR CLAIMS OF VEHICLE OF SNB1576Y

QTY	ITEM	COST PRICE
1	A/C Condenser / BT 1	\$ 920.00
1	Radiator /	\$ 744.70
2	A/C hose / ant	\$ 243.96
1	Radiator Hose X NN	\$ 154.08
1	Top water hose ?	\$ 166.93
1	Lower Water hose ?	\$ 141.24
1	Engine Under cover /	\$ 192.60
1	Bumper Under coer /	\$ 186.16
1	Noise center cover /	\$ 115.56
1	Anti Roll Bar /	\$ 308.16
1	LH Upper arm /	\$ 603.48
1	LH Lower Arm /	\$ 494.34
1	Front Absorber / BT	\$ 2,824.80
1	Steering rack /	\$ 6,163.20
1	Tie Rod end /	\$ 256.80
1	Rack End /	\$ 372.36
1	Steering cover /	\$ 102.72
1	Front Stabilizer link /	\$ 166.92
1	LH Front Trust arm /	\$ 346.68
1	LH Knuckle arm /	\$ 1,219.80
2	Front Disc rotor X NN BT	\$ 616.32
1	LH Front Wheel bearing / BT	\$ 513.60
2	Engine mountng ?	\$ 346.68
1	Gear mounting ?	\$ 70.62
1	Engine oil pan ?	\$ 231.12
1	Gearbox heat exchanger ?	\$ 256.80
1	Lower lip bumper front ?	\$ 179.76
2	Front Brake pad X NN	\$ 192.60
1	Front Absorber block valve X NN	\$ 513.60
	Absorber pressure pump ?	\$ 1,284.00
1	Seat belt RH / Act.	\$ 1,284.00
2	Exhaust Cathodic convertor / ant	\$ 4,879.20

1	Radiator fan	✓	
1	Gearbox auto pressure hose	?	\$ 1,284.00
3 & 4	RIMS	✓ BT	\$ 642.00
1	Main Floor LH	X	\$ 2,568.00
1	Main Floor LH substructure cover	✓	\$ 1,142.76
1	Main Floor RH	✓	\$ 398.04
1	Main Floor RH substructure cover	✓	\$ 1,142.76
1	Stiffener	✓	\$ 398.04
2	Integral carrier	✓	\$ 77.04
2	Auto Cooler hose (heat exchanger hose)	?	\$ 3,633.72
2	Lower Arm rear	✓ BT	\$ 359.52
2	Trust arm rear	✓	\$ 821.76
2	Upper Arm rear	?	\$ 590.64
2	Tyres Front	?	\$ 821.76
2	Tyres Rear	✓	\$ 770.00
1	Auto Cooler	✓ PH - m	\$ 800.00
			\$ 269.64

1 Frt sub-frame ✓ BT

\$ 41,812.47

Labour Cost

To provide labour charge \$ 2,000.00 / Kae .

Total \$ 43,812.47

8 Days.
part by part.

After repair photos. (New parts and old parts)

Guo Qiang - 82880282

Guo Qiang @ 1kkauto.com

Not Authorised.

Excess : TBA