

Our Job Ref No : 305496872

Date : 08/12/21

## ENGINEERING

ComfortDelGro Engineering Pte Ltd  
59 Loyang Drive Singapore 508969  
Fax: 6546 8156

## FINALIZATION FORM

To : LKK

**Fax :**

Attn : THEVAN

Vehicle Reg No. : SHD3245A

02/12/21

The survey and estimates of the repairs of the above-mentioned vehicle are as follows:-

Z The repair job shall bill to: NTUC GBF182C

2. The finalized amount shall be:

(a) Spare Parts after List discount

(b) Labour Charges

**Total for Part-By-Part Repair Cost**

(c.) Lumpsum Repair (if applicable)  
Total for Lumpsum repair cost after Less:  
**Final Lumpsum Repair cost**

\$1,050.00

3. Estimated normal period for repairs: 2 working days.

4. **We shall treat the above amount as Correct and Confirmed if there is no reply from you within 7 working days**

5. Thank you for your assistance.

We confirm the estimates and finalized amount

Signature : 

Name : CHIANG

Tel : 62148314

Fax : 65468156

Signature: \_\_\_\_\_

Name : Thevan

Date : 9/12/21

**For Official Use Only**

Item	Amount	Document Attached Yes or No	Confirm By (Signature)	Remarks
1. Rental Rate P/Day		YES		
2. Loss of Income Paid	-	N		
3. Survey Fees	-	-		
4. LTA Search Fee	\$7.49/\$2.00			
5. Medical Fees (on behalf of driver, if applicable)				
6. Overrun				

Remarks:

## COMFORTDELGRO ENGINEERING PTE LTD

## REPAIR ESTIMATE\*

VEHICLE NO SHD3245A

02/12/21

MAKE REG 13.09.2018

CHIANG/NTUC

MODEL IONIQ G2

Qty	Parts Description/ Labour	Type	Amount
1	REAR BUMPER		\$459.40
1	REAR BUMPER SIDE BRACKET RH		\$55.80
1	REAR BUMPER REINFORCEMENT		\$394.80
1	REAR BUMPER CENTRE MOULDING		\$451.25
2	REAR NUMBER PLATE LAMP	\$85.30	\$170.60
1	REAR SMART KEY SENSOR		\$45.00
1	REAR BUMPER TOW COVER		\$94.60
1	REAR BUMPER REFLECTOR RH		\$41.45
10	REAR BUMPER CLIPS	\$2.20	\$22.00
	<b>SUB TOTAL</b>		<b>\$1,734.90</b>
	<b>20.00%</b>		<b>\$346.98</b>
	<b>DISCOUNTED TOTAL</b>		<b>\$1,387.92</b>
1	REAR REVERSE SENSOR		\$180.00
1	REAR NUMBER PLATE W/HOLDER		\$55.00
1	REAR BUMPER MAT		\$50.00
	<b>Labour Charge</b>		
	Panel Beating		\$450.00
	Spray Painting Charge		\$300.00
	Check Lighting and Wiring		\$60.00
	Tuff Kote		\$90.00
	Remove/refix Reverse sensor		\$60.00
	<b>TOTAL LABOUR</b>		<b>\$960.00</b>
	<b>ESTIMATE TOTAL</b>		<b>\$2,627.42</b>

This is an initial estimate based on a visual inspection of the above vehicle. The final repair quantum will be prepared after the vehicle is surveyed by a motor Surveyor appointed by the insurance company.

Thevan Lkhauto.lom

82235769

6/12/21 1515

L/S after repair photo  
Zelays wp

**LKK Auto Consultants** hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date: