

Our Job Ref No : 305496783
 Date : 08/12/21

ENGINEERING
 ComfortDelGro Engineering Pte Ltd
 59 Loyang Drive Singapore 508969
 Fax: 6546 8156

FINALIZATION FORM

To : LKK
 Attn : THEVAN
 Vehicle Reg No. : SHC264U

Fax : _____
04/12/21


The survey and estimates of the repairs of the above-mentioned vehicle are as follows:-

1. The repair job shall bill to: NTUC SHC6914M
2. The finalized amount shall be:
 - (a) Spare Parts after List discount _____
 - (b) Labour Charges _____
 - Total for Part-By-Part Repair Cost** _____
 - (c) Lumpsum Repair (if applicable)
 Total for Lumpsum repair cost after Less: _____
Final Lumpsum Repair cost \$3,400.00
3. Estimated normal period for repairs: 3 working days.

4. **We shall treat the above amount as Correct and Confirmed if there is no reply from you within 7 working days**

5. Thank you for your assistance.

We confirm the estimates and finalized amount

Signature : 
 Name : CHIANG
 Tel : 62148314
 Fax : 65468156

Signature : 
 Name : Thevan
 Date : 9/12/21

For Official Use Only

Item	Amount	Document Attached Yes or No	Confirm By (Signature)	Remarks
1. Rental Rate P/Day		YES		
2. Loss of Income Paid	-	N		
3. Survey Fees	-	-		
4. LTA Search Fee	\$7.49/\$2.00			
5. Medical Fees (on behalf of driver, if applicable)				
6. Overrun				

Remarks:

REPAIR ESTIMATE*

VEHICLE NO SHC264U

DATE 04/12/21 10:30 AM

MAKE :24.09.2019

MODEL : HYUNDAI IONIQ G2

CHIANG/NTUC

Qty	Parts Description/ Labour	Type	Unit Price	Amount
1	FRONT DOOR PANEL LH			\$1,797.20
1	FRONT DOOR MOULDING LH			\$110.10
1	FRONT FENDER EMBLEM BLUE DRIVE			\$26.60
1	WHEEL RIM COVER RR LH			\$346.40
1	REAR DOOR MOULDING LH			\$1,789.90
1	REAR DOOR PANEL LH			\$125.30
	SUB TOTAL			\$4,195.50
	LESS 20%			\$839.10
	DISCOUNTED TOTAL			\$3,356.40
1	FRONT DOOR COMOFRT LOGO			\$75.00
1	REAR PETROL STICKER			\$20.00
1	FRONT FENDER ADVERTISEMENT LH			\$100.00
1	FRONT DOOR ADVERTISEMENT			\$100.00
1	REAR DOOR ADVERTISEMENT			\$100.00
1	REAR FENDER ADVERTISEMENT			\$100.00
1	REAR DOOR COMFORT APP STICKER			\$80.00
				\$557.50
	Labour Charge			
	Panel Beating			\$840.00
	Spray Painting Charge			\$1,000.00
	Remove/refix frt door part to new door			\$90.00
	Remove/refix rear door part to new door			\$90.00
	Remove/refix upholstery			\$90.00
	Check Wiring			\$60.00
	TOTAL LABOUR			\$2,170.00
	ESTIMATE TOTAL			\$6,083.90

This is an initial estimate based on a visual inspection of the above vehicle. The final repair quantum will be prepared after the vehicle is surveyed by a motor Surveyor appointed by the insurance company.

Thuvan@lkhauto.com
 82235769
 6/12/21 1600
 L/S after repair photo
 4 days w/p ✓

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer
 Signature:
 Date: