

Our Job Ref No : 305496785
Date : 08/12/21

ENGINEERING
Cambridge Engineering Pte Ltd
30 Layang Drive Singapore 608919
Fax 6548 8158

FINALIZATION FORM

To : LKK

Fax :

Attn : THEVAN

Vehicle Reg No. : SHD7226D

03/12/21

The survey and estimates of the repairs of the above-mentioned vehicle are as follows :

1. The repair job shall bill to : NTUC FBA8083D
2. The finalized amount shall be :
- (a) Spare Parts after List discount : _____
- (b) Labour Charges : _____
- Total for Part-By-Part Repair Cost** : _____
- (c) Lumpsum Repair (if applicable)
Total for Lumpsum repair cost after Less : _____
Final Lumpsum Repair cost : \$1,050.00

3. Estimated normal period for repairs : 2 working days.

4. **We shall treat the above amount as Correct and Confirmed if there is no reply from you within 7 working days**

5. Thank you for your assistance.

We confirm the estimates and finalized amount

Signature : 

Name : **CHIANG**

Tel : 62148314

Fax : 65468156

Signature : 

Name : Thevan

Date : 9/12/21

For Official Use Only

Item	Amount	Document Attached Yes or No	Confirm By (Signature)	Remarks
1. Rental Rate P/Day		YES		
2. Loss of Income Paid	-	N		
3. Survey Fees	-	-		
4. LTA Search Fee	\$7.49/\$2.00			
5. Medical Fees (on behalf of driver, if applicable)				
6. Overrun				

Remarks:

COMFORTDELGRO ENGINEERING PTE LTD

REPAIR ESTIMATE*

VEHICLE NO SHD7226D ✓
 MAKE REG 22.11.2018
 MODEL IONIQ G2

03/12/21

CHIANG/NTUC

Qty	Parts Description/ Labour	Type	Amount
1	REAR BUMPER		\$459.40
1	REAR BUMPER SIDE BRACKET RH		\$55.80
1	REAR BUMPER REINFORCEMENT		\$394.80
1	REAR BUMPER RH STAY BRACKET		\$138.10
1	REAR BUMPER CENTRE MOULDING		\$451.25
1	REAR BUMPER UNDER MOULDING		\$155.00
1	REAR SMART KEY SENSOR		\$45.00
1	REAR BUMPER TOW COVER		\$94.60
1	REAR BUMPER REFLECTOR RH		\$41.45
10	REAR BUMPER CLIPS		\$22.00
		\$2.20	
	SUB TOTAL		\$1,857.40
	20.00%		\$371.48
	DISCOUNTED TOTAL		\$1,485.92
1	REAR REVERSE SENSOR		\$180.00
1	REAR BUMPER MAT		\$50.00
			\$230.00
	Labour Charge		
	Panel Beating		\$600.00
	Spray Painting Charge		\$300.00
	Check Lighting and Wiring		\$60.00
	Tuff Kote		\$90.00
	Remove/refix Reverse sensor		\$60.00
	TOTAL LABOUR		\$1,110.00
	ESTIMATE TOTAL		\$2,825.92
This is an initial estimate based on a visual inspection of the above vehicle. The final repair quantum will be prepared after the vehicle is surveyed by a motor Surveyor appointed by the insurance company.			

Thuan@lthauto.com
 82235769
 6/12/21 1630
 L/S after repair photo
 2 days wp

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date: