


ASSIGNMENT

From: \_\_\_\_\_ Date: \_\_\_\_\_  
 Estimated Cost: \_\_\_\_\_  
 OD / TP / WS / TP RES / OD RES / EVA / INV / MV  
 To Inspect Vehicle No: \_\_\_\_\_  
 at Workshop m/s \_\_\_\_\_  
 of \_\_\_\_\_  
 Insured: **PC 9767G**  
 Policy No: \_\_\_\_\_  
 Claims No: **MT/1154804-001**  
 Sum Insured: \_\_\_\_\_ Excess: \_\_\_\_\_  
 (Client's Record)  
 Make of Vch: \_\_\_\_\_

Veh No: **SHA2358E** ✓ Yr Rogn: **28/9/18**  
 Type: M. Car / M. Cycle / Bus / Van / Lorry / **(T6X)** Prime Mover /  
 Truck / Trailer or \_\_\_\_\_  
 Make: **Hyundai Ioniq** c.c. **1580**  
 Colour: **blue** A/C: Insured / Std / Nil / NA  
 Sp. Reading: **394176** T/Radio: Insured / Std / Nil / NA  
 Eng/No: \_\_\_\_\_  
 C/No: **KMHC85/CUKH114713**  
 Gen. Cond: **Good** / Fair / Poor / Burnt  
 Steering: Insured / Jammed / Leaked / Burnt or \_\_\_\_\_  
 Brake: Insured / Jammed / Leaked / Burnt or \_\_\_\_\_  
 Modi: Nil / **(SIR)** / STD AIR/Im or \_\_\_\_\_  
 Tyre Size: F: **195/65R15**  
 R: **195/65R15**

(Policy Condition)  
 Remark: The veh had commenced its  
 repair at the time of inspection.



BS / DUN / EXNOVA / GY / FS / LIZA / MIC / OHTSU / PIR / SUMI /  
 TOYO / YOKO or **Westlake**  
 Front \_\_\_\_\_ Rear \_\_\_\_\_  
 R/Bal. **5** mm R/Bal. **5** mm  
 L/Bal. **5** mm L/Bal. **5** mm  
 D.O.A. **6/12/21** D.O.I. **6/12/21**  
 Survey held at **CPD OE**  
 Des. of Damages: Frt / **(Rear)** / O/S / N/S / U/C / Roof/Top or \_\_\_\_\_  
 The U/C / Chassis frame / Body Structure affected due to collision.

Date / Time	Action / Instruction
	<b>NO GIA provided</b>
15/12/21	Thevan confirmed LS \$1400 (Red 1022.69, 42%)

Date/Time, File Pass to?  : Prell, Report  
 : Final Report

Days Of Repair: **2**  
 Resurvey No. of Trip: **1**

Date/Time, File Return to?  
**16/12/21-typist**

Add Fee:  : Site Insp (\$ \_\_\_\_\_)  
 : Interview (\$ \_\_\_\_\_)  
 : Tech. Invs (\$ \_\_\_\_\_)  
 : Wheel and \_\_\_\_\_

Survey Fee:	_____
Transportation:	_____
_____ \$ + RS. _____ \$	_____
Planks	_____
Others	_____
TOTAL	_____

Request Form No: **TP**  
 Loss / Insured: **LS \$1400**

NTUC (Usum)

COMFORTDELGRO ENGINEERING PTE LTD

Date: 06.12.2021  
Time: 11:39:44  
Page: 1  
Juman!

REPAIR ESTIMATE

COMPANY : THIRD PARTY'S CLAIMS (CAS)  
CUSTOMER: 7010045  
ADDRESS : COMFORT TRANSPORTATION PTE LTD  
383 SIN MING DRIVE  
SINGAPORE SINGAPORE 575717  
65508755

JOB NO : 305496870  
REGN NO : SHA2358E ✓  
MILEAGE : 000000000  
MAKE : HYUNDAI  
MODEL : IONIQ(G2)  
DATE OF REGN : 28.09.2018  
DATE/TIME IN : 06.12.2021 10:05  
ACCIDENT DATE : 06.12.2021

JOB / PARTS DESCRIPTION QTY IND UNIT-PRICE DISC% AMOUNT


PART REQUISITION

0001	04-01-0104-2282-G	COVER-RR BUMPER#	1	459.40	20.00	367.52	/cut
0002	04-01-0104-2533-G	MOULDING ASSY-RR BUMPER C	1	451.25	20.00	361.00	/scr
0003	04-01-0104-2288-G	BEAM-RR BUMPER	1	394.80	20.00	315.84	?
0004	04-01-0101-0111-G	BUMPER COVER CLIP REAR	10 L	22.00	20.00	17.60	/n/c
0005	09-01-9999-0068-A	REVERSE SENSOR ASSY*	1 N	135.70	10.00	122.13	/cut
0006	09-01-0104-2133-G	ANTENNA ASSY-SMARTKEY	1	40.50	20.00	32.40	?
0007	04-01-0104-2370-G	LAMP ASSY-REAR FOG	1	201.50	20.00	161.20	Xscr
0008	28-01-0104-2029-A	VEHICLE NUMBER PLATE REAR	1 N	50.00	10.00	45.00	/scr

SUB-TOTAL : 1,422.69 ✓

JOB NATURE

0000	PB	PANEL BEATING	400.00	360
0001	SP	SPRAYPAINT CHARGE	300.00	250
0002	L	REMOVE/REFIX REVERSE SENSOR	50.00	20 ✓



COMPANY : THIRD PARTY'S CLAIMS (CAS)  
 CUSTOMER: 7010045  
 ADDRESS : COMFORT TRANSPORTATION PTE LTD  
 383 SIN MING DRIVE  
 SINGAPORE SINGAPORE 575717  
 65508755

JOB NO : 305496870  
 REGN NO : SHA2358E  
 MILEAGE : 0000000000  
 MAKE : HYUNDAI  
 MODEL : IONIQ(G2)  
 DATE OF REGN : 28.09.2018  
 DATE/TIME IN : 06.12.2021 10:0  
 ACCIDENT DATE : 06.12.2021

JOB / PARTS DESCRIPTION	QTY	IND	UNIT-PRICE	DISC%	AMOUNT
0003 20-05 RENEW ADVERTISEMENT STICKER-FENDR	200.00				<i>n/c</i>
0004 17-01 CHECK ALL LIGHTING	50.00				20
SUB-TOTAL :					1,000.00
TOTAL :					2,422.69

\_\_\_\_\_  
 MVA NAME & SIGNATURE  
 DATE :

\_\_\_\_\_  
 SURVEYOR NAME & SIGNATURE  
 DATE :

AUTHORISED : YES / NO

*Thuan@Lhhauto.com*  
*82235769*  
*6/12/21 11:530*  
*L/S after repair photo*  
*2 day swp*

**LKK Auto Consultants** hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed **and** is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date:

Date/Time: 06.12.2021 11:25

Page : 1

Job: ARC Repair TP(CLSO)1

**JOB CARD** Sales Order: 4148141


JG NO305496870

OWNER COMFORT TRANSPORTATION PTE LTD 7010045 383 SIN MING DRIVE Singapore SINGAPORE 575717 65508755	REGN NO. <b>SHA2358E</b>	MILEAGE
MAKE <b>HYUNDAI</b>	FUEL	E.....1/2.....F
MODEL <b>IONIQ(G2)</b>	DATE/TIME IN <b>06.12.2021 10:05</b>	TARGET DATE
YR OF MANU. <b>28.09.2018</b>	COMPLETION DATE/TIME	
CHASSIS CODE <b>KMHC851CVKU114713</b>		

JOB DESCRIPTION

Accident Date: 06.12.2021  
 Accurrence: 3P.06.12.2021

NO                      LABOR CODE                      DESCRIPTION



REMOVED & PASSED OUT BY: \_\_\_\_\_

SERVICE ADVISOR

CUSTOMER'S SIGNATURE

Check-in/Check-out Slip

Exit Pass

Vehicle No.: **SHA2358E**

Signature: **JU NTUC**

Vehicle No.:

**SHA2358E**

Service Advisor

Signature/Date

Name of Service Advisor

Date

Returned to Service Reception upon collection

To be kept by Security Guard