

Jess & Serene 2688
8A Duke's Road
Singapore 268888

File No : SH/2021/101/12/004/TP
Date : 13-December-2021

Estimated cost of repair for vehicle no : SMU7228A Ssangyong Tivoli

Accident involving vehicle no: SMU7228A & SLQ8234H on 04.12.2021 2020

Description	Quantity	Cost Price
LH front fender	1	\$ 660.00 DDV
LH front fender signal lamp	1	\$ 135.00 BRV
LH front door	1	\$ 1,257.73 1,800.00 DDV
LH front door chrome trim	1	\$ 110.00 BRV
LH front door outer handle	1	\$ 230.00 BRV
LH front door side mirror base	1	\$ 800.00 CUTV
LH front door side mirror cover	1	\$ 110.00 CUTV
LH rear door	1	\$ 1,300.00 1,850.00 DDV
LH rear door outer handle	1	\$ 230.00 BRV
LH tail lamp	1	\$ 460.00 BRV
		\$ 5,292.73 6,385.00
	Add 15%	\$ 793.91 957.00
		\$ 4,498.82 7,342.00

To remove damaged parts, to jack out LH rear fender inner panel, LH centre door pillar, to reshape and repair LH rear fender and inner panel, LH centre door pillar, to remove and refit LH front and rear door trim, lock, window, to replace damaged parts and adjust body panel alignment

\$ 700.00 750.00

To spray paint affected LH side and inner damaged portion inclusive of preparatory works and material

\$ 800.00 850.00

To disconnect wire harness to facilitate repairs and check for damage and reconnect wiring system and check for full functionality

\$ 25.00

To apply anti-corrosion Tuff-Kote

\$ 100.00

\$ 1,500.00 9,067.00

T/Party: India International Insurance Pte Ltd

Survey & Resurvey
13/12/2021 TQM in
1615 hrs

Lump sum repair
Repair days 7

97361577

LS 4800/2
TQM in
14/12/2021

Parts 4498.82
SN
Labour 1500.00
5998.82
@20% 1199.76
4799.06

Page 1 of 1

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer