

Our Job Ref No 305496878

Date : 08/12/21

ENGINEERING

ComfortDelGro Engineering Pte Ltd
59 Loyang Drive Singapore 508969
Fax: 6546 8156

FINALIZATION FORM

To : LKK

Fax :

Attn : THEVAN

: SHC1327R

SHA 06/12/21

The survey and estimates of the repairs of the above-mentioned vehicle are as follows:-

1. The repair job shall bill to: NTUC --- SMN423K

2. The finalized amount shall be:

(a) Spare Parts after List discount \$1,508.44

(b) Labour Charges \$620.00

Total for Part-By-Part Repair Cost \$2,128.44

(c.) Lumpsum Repair (if applicable)
Total for Lumpsum repair cost after Less: 20%
Final Lumpsum Repair cost

3. Estimated normal period for repairs: 2 working days

4. We shall treat the above amount as Correct and Confirmed if there is no reply from you within 7 working days

5. Thank you for your assistance.

We confirm the estimates and finalized amount

Signature : 

Name : JUMANI

Tel : 6214 8315

Fax : 65468156

Signature : 

Name : THEVAN

Date : 14/12/21

For Official Use Only

Item	Amount	Document Attached Yes or No	Confirm By (Signature)	Remarks
1. Rental Rate P/Day		YES		
2. Loss of Income Paid	-	N		
3. Survey Fees	-	-		
4. LTA Search Fee	7.49 / 2.00	YES		
5. Medical Fees (on behalf of driver, if applicable)				
6. Overrun				

Remarks:

COMFORTDELGRO ENGINEERING PTE LTD

REPAIR ESTIMATE

HTUC (LP/P)

Date: 06.12.2021

Time: 15:17:08

Page: 1

Jumani

COMPANY : THIRD PARTY'S CLAIMS (CAS)
 CUSTOMER: 7010045
 ADDRESS : COMFORT TRANSPORTATION PTE LTD
 383 SIN MING DRIVE
 SINGAPORE SINGAPORE 575717
 65508755

JOB NO : 305496878
 REGN NO : SHC1327R ✓
 MILEAGE : 0000000000
 MAKE : HYUNDAI
 MODEL : IONIQ(G3)
 DATE OF REGN : 18.03.2020
 DATE/TIME IN : 06.12.2021 10:30
 ACCIDENT DATE : 06.12.2021

JOB / PARTS DESCRIPTION

QTY IND UNIT-PRICE DISC% AMOUNT

PART REQUISITION

0001 04-01-0104-2282-G	COVER-RR BUMPER#	1	459.40	20.00	367.52	/cut
0002 04-01-0104-2533-G	MOULDING ASSY-RR BUMPER C	1	451.25	20.00	361.00	/cut
0003 04-01-0104-2288-G	BEAM-RR BUMPER	1	394.80	20.00	315.84	? / DT
0004 04-01-0104-1150-A	PROTECTOR MAT	1 N	50.00	2.00-	50.00	/NXC
0005 04-01-0101-0111-G	BUMPER COVER CLIP REAR	10 L	22.00	20.00	17.60	/NXC
0006 04-01-0104-2532-G	BRACKET ASSY-RR BUMPER SI	1	55.80	20.00	44.64	? / NXC
0007 04-01-0104-3919-G	STAY-RR BUMPER RH	1	138.10	20.00	110.48	? / DT
0008 09-01-9999-0068-A	REVERSE SENSOR ASSY*	1 N	180.00	10.00	162.00	/cut

SUB-TOTAL : 1,429.08 ✓

JOB NATURE

0000 PB	PANEL BEATING	400.00	360	350
0001 SP	SPRAYPAINT CHARGE	300.00	250	
0002 L	REMOVE/REFIX REVERSE SENSOR	50.00	20	

Thuvan@Lkhanto.com

82235769

6/12/21 1630

11/12/21 bfr paint photo

2days wp ✓

LKK Auto Consultants hence notify
 the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date:

SUPPLEMENTARY OF PARTS AND LABOUR COSTS			
DESCRIPTION	QTY	ESTIMATE	REMARKS
REAR BUMPER LOWER CENTRE MOULDING	1	\$155.00	Cut
CHECK ITEM STAY R			
REAR BUMPER BRACKET RH X STAY R	1	\$138.10	RH
REAR BUMPER BEAM	1	\$394.80	
LABOUR			
TOTAL:		\$687.90	JUMANI