



## LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

### TAX INVOICE

CHINA TAIPING INSURANCE (S) PTE LTD

INV No. AC2203973

3 ANSON ROAD #16-00  
SPRINGLEAF TOWER  
SINGAPORE 079909

INV Date 27/06/2022  
Reference CC6/CTI21012453/Kga3q2  
Code CTI

### PROFESSIONAL SERVICE FEE

Vehicle No. SJN 9439S  
Insured Veh. SMD 9673Z  
Claim No. SNM21D207139  
Policy No. DMPCSNA00243262101  
Accident Date 03/12/2021  
Inspection Date 09/12/2021

Description	Total
Third Party Express Settlement	400.00
<b>Subtotal</b>	<b>400.00</b>
<b>GST (7%)</b>	<b>28.00</b>
<b>Grand Total</b>	<b>428.00</b>

We shall be glad if you could forward the payment at your early convenience.

Cheque should be crossed and made payable to **'LKK Auto Consultants Pte Ltd'**

LKK Auto Consultants Pte Ltd

**LKM**



# LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Affiliated to Federation Internationale Des Experts En Automobile				
CHINA TAIPING INSURANCE (S) PTE LTD 3 ANSON ROAD #16-00 SPRINGLEAF TOWERSINGAPORE 079909			Ref: CC6/CTI21012453/Kga3q2	
			Date: 27/06/2022	
			Code: CTI	
<b>1. Policy Particulars :- THIRD PARTY CLAIM</b>				
Insured Veh.	SMD 9673Z	Veh. Inspected	SJN 9439S	
Policy No.	DMPCNA00243262101	Coverage (\$)	0.00	
Claim No.	SNM21D207139	Excess (\$)	0.00	
Assign From		Assign Date	09/12/2021	
<b>2. Vehicle Particulars &amp; Condition</b>				
Make & Model	HYUNDAI AVANTE (A)	c.c	1591	
Engine No.	HIDDEN	Year of Reg.	2009	
Chassis No.	KMHU41BR9U706907	Colour	METALLIC SILVER	
Odometer	367399 KM	Steering	IN ORDER	
Brakes	IN ORDER	Modification	SPORTS RIM	
General	GOOD			
<b>3. Conditions of Tyres</b>				
	Size	Make	Balance	
R/H Front Tyre	185/65 R15	CONTINENTAL	3 mm	
L/H Front Tyre	185/65 R15	CONTINENTAL	3 mm	
R/H Rear Tyre	185/65 R15	HABILEAD	4 mm	
L/H Rear Tyre	185/65 R15	HABILEAD	4 mm	
<b>4. Description of Damages</b>				
THE VEHICLE SUSTAINED DAMAGES AT THE N/S REAR PORTION.  DAMAGES SEE DETAILS.				
<b>5. General Information</b>				
Accident Date	03/12/2021	Inspection Date	09/12/2021	
Survey held at	NGS MOTORSPORT PTE LTD 10 ANG MO KIO INDUSTRIAL PARK 2A #02-01 AMK AUTOPOINT SINGAPORE 568047			
<b>5a. Remarks</b>				
A)THE INSPECTION WAS CONDUCTED ON A"WITHOUT PREJUDICE" BASIS. B)IN ACCORDANCE TO YOUR INSTRUCTIONS, WE HAVE NOT AUTHORISED REPAIRS.				
<b>5b. Estimate Days of Repair</b>				
ESTIMATED NORMAL PERIOD FOR REPAIR:			<b>3 Working Days</b>	



# LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Page No.:1 of 1

## ADJUSTMENT ON REPAIR COST FOR VEHICLE NO. SJN 9439S

Qty	Description of Parts	Condition	Estimate By Workshop (\$)	Our Adjusted (\$)
	<b><u>REPLACEMENT OF PARTS</u></b>			
1	REAR BUMPER	TO REPAIR SEE LABOUR	478.29	-
1	REAR SIDE RETAINER LH	SERVICEABLE	52.00	-
	LESS 20% DISCOUNT		-106.06	-
			424.23	-
	<b><u>SPECIAL NETT ITEMS</u></b>			
14	CLIPS ,FENDER LINING @\$5.00 (SN)	NOT NECESSARY	70.00	-
1	SPORT RIM (SN)	DENTED / SCRATCHED	580.00	280.00
			650.00	280.00
	<b><u>LABOUR</u></b>			
	TO REMOVE FRT DAMAGED PARTS WITH ALL NECESSARY COMPONENTS /ATTACHMENTS ,REPAIR /RESHAPE DENTED BODY PANEL REPLACE /REPOSITION DAMAGED ARTS ,REFIT ALIGN INTO REFIX ALL NECESSARY COMPONENTS/ATTACHMENT.INCLUSIVE OF THE REPAIR OF REAR BUMPER .		400.00	300.00
	SPRAY PAINTING -REAR BUMPER ,FENDER RH .		500.00	400.00
			900.00	700.00
	<b>GRAND TOTAL</b>		<b>1,974.23</b>	<b>980.00</b>
	<b>RECOMMENDED COST OF LUMP SUM REPAIRS (TO ITS PRE-ACCIDENT CONDITION)</b>			<b>800.00</b>

Report Ref No. CC6/CTI21012453/Kga3q2

KONG SENG CHEONG

Licensed Appraiser

**DISCLAIMER OF LIABILITY TO THIRD PARTIES:-** This Report is made solely for the use and benefit of the Client named on the front page of this Report.

No liability of responsibility whatsoever, in contract or tort, is accepted to any third party who may rely on the Report wholly or in part. Any third party acting or relying on this Report, in whole or in part, does so at his or her own risk.



## LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

### PHOTOGRAPHS FOR VEHICLE NO. SJN 9439S

### INSPECTION





## LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R





## **LKK Auto Consultants Pte Ltd**

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

