

ASS. REC. BY:

REF:

A/C / 21012459 / ke

C

Kenneth

ASSIGNMENT

From:

Date:

Estimated Cost:

OD / TP / WS / TP RES / OD RES / EVA / INV / MY

To Inspect Vehicle No:

at Workshop m/s

of

Insured:

Policy No.

Claims No.

Sum Insured:

Excess:

(Client's Record)

Make of Veh:

(Policy Condition)

Remark: The veh had commenced its
repair at the time of inspection.

N/S	O/S

Bal. or Market Value:

IDAC Accident Rpt:

Consistent? : Yes or No

GIA / PR Seen:

Consistent? : Yes or No

Est. Repairs:

084 days

Res.: Yes or No

Lum Sum:

20 %

3 Val.: Yes or No

CA / REV / REP. / 24 HRS

Date:

Person Contacted:

Vehicle: IN / OUT

Veh No:

SKR 4871B Yr Regn: 02, 15

Type: M.Car / M.Cycle / Bus / Van / Lorry / Taxi / Prime Mover /

Truck / Traller or

Make:

Mazda 5 c.c. 1998

Colour

M.D. Blue A/C: Insured / Std / NI / NA

Sp. Reading

189716 T/Radio: Insured / Std / NI / NA

Eng/No:

C/No:

Gen. Cond: Good Fair / Poor / Burnt

Steering: In order Jammed / Leaked / Burnt or

Brake: In order Jammed / Leaked / Burnt or

Mod: Nil / S/Rim / STD A/Rim or

Tyre Size:

F:

R:

BS / DUN / EXNOVA / GY / FS / LIZA / MIC / OHTSU / PIR / SUMI /

TOYO / YOKO or

Front

R/Bal.

L/Bal.

D.O.A.

Survey held at

Des. of Damages: Frt / Rear / O/S / N/S / U/C / Rooftop or

The U/C / Chassis frame / Body Structure affected due to collision.

Date / Time

Action / Instruction

13/12 11:20 @ 285ch Cdnw 31/12

Date/Time, File Pass to?

☐

: Prell. Report

1)

☐

: Final Report

Date/Time, File Return to?

2)

Days Of Repair:

Resurvey No. of Trip:

Survey Fee:

Transportation:

S - RS - SI

Fees

Others

TOTAL

Add Fee:

☐

: Site Insp (\$

☐

: Interview (\$

☐

: Tech Invs (\$

☐

: Weekend (\$

Report Format :

Lump Sum / I.B.I: (\$



方商昭噴漆 POON SIANG SEOW

Sin Ming Autocity, No. 160 Sin Ming Drive, #05-13, Singapore 575722.

Tel: 6453 7511 Fax: 6453 8046 Email: sitti1@singnet.com.sg Regn. No. 05396600K

Tang Chee Hoe

Apt Blk 310A

Ang Mo Kio Avenue 1

#23-387

Singapore 561310

*Not wither
11Lp @ 2850/h
Permy After Rainy
4 days*

Dear sir

Estimate cost of repair to vehicle no. SKR 4871B

To supply

1. Front door	<i>121</i>	1,205.00	—
2. Front door lock	<i>1</i>	468.00	X
3. Front door outer handle	<i>1</i>	141.00	X
4. Front door power motor and gear	<i>1</i>	580.00	X
5. Door vision one set	<i>1</i>	150.00	—
6. Front door black sticker x2	<i>1</i>	102.00	—
7. Front door outer moulding	<i>1</i>	134.00	X
8. Front door rubber	<i>1</i>	230.00	X
9. Rear door <i>1364.50</i>	<i>121</i>	1,405.00	—
10. Rear door lock	<i>1</i>	480.00	X
11. Rear door power motor and gear	<i>1</i>	589.00	X
12. Rear door rubber	<i>1</i>	289.00	X
13. Body sticker <i>208</i>	<i>1</i>	250.00	—

Labour charges

Rust proofing	120.00	<i>601</i>
Panel beating	1,200.00	<i>5001</i>
Spray painting	1,000.00	<i>5501</i>
total		

LKK Auto Consultants hence notify
the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and
is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date: