



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Affiliated to Federation Internationale Des Experts En Automobile				
BLUWEL AUTOMOTIVE SERVICE PTE LTD			Ref:	CS/TP21012460/Uqf3e2
BLK 1 KAKI BUKIT AVE 6			Date:	21/12/2021
#01-28/53/55/56 (MAIN OFFICE)SINGAPORE 417883				
ON BEHALF OF OW SHEE WING			Code:	TP149
1. Policy Particulars :- THIRD PARTY CLAIM				
	Insured Veh.	Veh. Inspected	SGF 9855B	
	Policy No.	Coverage (\$)	0.00	
	Claim No.	Excess (\$)	0.00	
	Assign From	Assign Date	09/12/2021	
2. Vehicle Particulars & Condition				
	Make & Model	TOYOTA HARRIER M GRADE (A)	c.c	1998
	Engine No.	HIDDEN	Year of Reg.	2018
	Chassis No.	JTEZB3GH20J004152	Colour	WHITE
	Odometer	74429 KM	Steering	IN ORDER
	Brakes	IN ORDER	Modification	SPORTS RIM
	General	GOOD		
3. Conditions of Tyres				
		Size	Make	Balance
	R/H Front Tyre	235/35 R18	BRIDGESTONE	6 mm
	L/H Front Tyre	235/35 R18	BRIDGESTONE	6 mm
	R/H Rear Tyre	235/35 R18	BRIDGESTONE	6 mm
	L/H Rear Tyre	235/35 R18	BRIDGESTONE	6 mm
4. Description of Damages				
	THE VEHICLE SUSTAINED DAMAGES AT THE REAR N/S PORTION.			
	DAMAGES SEE DETAILS.			
5. General Information				
	Accident Date	25/11/2021	Inspection Date	09/12/2021
	Survey held at	BLUWEL AUTOMOTIVE SERVICE PL BLK 1 KAKI BUKIT AVE 6 #01-28/53/55/56 (MAIN OFFICE) SINGAPORE 417883		
5a. Remarks				
	A)THE INSPECTION WAS CONDUCTED ON A"WITHOUT PREJUDICE" BASIS. B)IN ACCORDANCE TO YOUR INSTRUCTIONS, WE HAVE NOT AUTHORISED REPAIRS.			
5b. Estimate Days of Repair				
	ESTIMATED NORMAL PERIOD FOR REPAIR:		5 Working Days	