

Surveyor : STEVE LKK
 Claim : AIG OD
 DOA : 08.12.2021
 Emailed : 31.03.2022 9.30am
 Date Survey : 09.12.2021

VEHICLE NO : SJN 96 G
 MODEL : KIA STONIC 1.0 A
 WIP : 43742

Material	:	\$	<u>20,720.38</u>
Labour	:	\$	<u>10,940.00</u>
Sub-Total	:	\$	<u>31,660.38</u>
	:	\$	<u>-</u>
Less Excess	:	\$	<u>3,600.00</u>
Total	:	\$	<u>28,060.38</u>
GST 7%	:	\$	<u>1,964.23</u>
Grand Total	:	\$	<u>30,024.61</u>
Finalise By/Date	:	LOI /	<u>31/03/2022</u>

☒ REVERT BACK WITHIN 7 DAYS,
 OTHERWISE WILL PROCEED WITH INVOICING

☐ SURVEYOR'S REPORT REQUIRED

☐ REPAIR TOOK 0 WORKING DAYS + 0 Days (0) Weekends
 + 0 Days (0) Public Holiday
 TOTAL DAYS REPAIR TOOK = 0

☐ TP claim _____

☐ Claim GIA / LTA fee _____

☐ Claim Loss of ☐ Use / ☐ Rental

☐ Claim Medical Fee / Others _____

☐ Third Party Report - _____



CYCLE & CARRIAGE

CYCLE & CARRIAGE KIA PTE LTD
PANDAN GARDENS CUSTOMER SERVICE CENTRE
 209 Pandan Gardens Singapore 609339 Tel: 65684555 Fax: 65651240



Movement that inspires

PRO-FORMA INVOICE

Co Reg No : 199405410K

THIS IS NOT AN OFFICIAL TAX INVOICE

GST Reg No : MR-8500111-X

Invoice Name & Address	Owner Name & Vehicle Info
AIG Asia Pacific Insurance Pte. Ltd. MOTOR CLAIM DEPARTMENT 78 SHENTON WAY #09-16 AIG BUILDING SINGAPORE 079120 Contact No 64191000 13/12/2021	Cust No/Name LCV14671/SEAH BOON WEE Reg No/Reg Date SJN96G / 27/10/2021 Date In/Mileage 08/12/2021/ 1635 Chassis/Package KNAD6817VN6623814 Engine No G3LEMP207464 Make/Model KIA/STONIC 1.0 A PE E02R Colour/Trim MYW MOST YELLOW / WK SATURN BLACK

Account No	Terms	Date/Time Printed	CSE	Operator	WIP No			
LAX00000	Credit	31/03/2022/ 09:16	BLK	260 / AiTing	43742			
Description of Goods / Services					Qty	Unit Price	Disc%	Amount
E PNT88000 REPLACE DAMAGED PARTS, REPLACE FRONT BUMPER, LH FRONT FENDER, RH FRONT FENDER,FRONT SUPPORT PANEL, REPAIR ALL OTHER AFFECTED AREAS, ADJUST AND ALIGN BODY GAPS ALIGNMENT TO THE SAME								✓ 1480.00
E PNT98000 RESPRAY ON FRONT BUMPER, LH FRONT FENDER, LH FRONT DOOR, AND ALL OTHER AFFECTED ARES TO THE SAME								✓ 1050.00
E PNT88000 REPLACE RH FRONT DOOR, RH REAR DOOR, RH WING MIRROR, RH SIDE SILL, REPAIR RH FRONT A PILLAR, AND ALL OTHER AFFECTED AREAS, ADJUST AND ALIGN BODY GAPS ALIGNMENT TO THE SAME								✓ 1160.00
E PNT98000 RESPRAY ON RH FRONT DOOR, RH REAR DOOR, RH FRONT FENDER, RH FRONT A-PILLAR, RH WING MIRROR COVER, AND ALL OTHER AFFECTED AREAS TO THE SAME								✓ 1480.00
E PNT88000 REMOVE & INSTALL RADIATOR, A/COND CONDENSER TO FACILITATE REPAIR								✓ 120.00
E PNT88000 TTRANSFER RH FRONT DOOR ATTACHMENTS TO NEW PANEL								✓ 120.00
E PNT88000 TRANSFER RH REAR DOOR ATTACHMENTS TO NEW PANEL								✓ 120.00
E PNT88000 REPLACE FRONT WINDSCREEN GLASS AND CONDUCT WATER LEAK TEST								✓ 240.00
M SUNDRY APPLY FRONT WINDSCREEN GLASS SEALANT								✓ 80.00
A 33900099 REPLACE FRONT UNDERCARRIAGE PARTS								✓ 400.00
E PNT88000 REMOVE & REPLACE INTERCOOLER ASSY								✓ 200.00
B WHEELALIGNMENT To Conduct Computerize Full Wheel Alignment								✓ 120.00
M SUNDRY REPLACE LH FRONT TIRE, REPLACE TIRE VALVE, CONDUCT WHEEL BALANCING								✓ 30.00

This is not an official tax invoice.
 This is a computer generated document, no signature is required.

PRO-FORMA INVOICE

Co Reg No : 199405410K

THIS IS NOT AN OFFICIAL TAX INVOICE

GST Reg No : MR-8500111-X

Invoice Name & Address	Owner Name & Vehicle Info
AIG Asia Pacific Insurance Pte. Ltd. MOTOR CLAIM DEPARTMENT 78 SHENTON WAY #09-16 AIG BUILDING SINGAPORE 079120 Contact No 64191000 13/12/2021	Cust No/Name LCV14671/SEAH BOON WEE Reg No/Reg Date SJN96G / 27/10/2021 Date In/Mileage 08/12/2021/ 1635 Chassis/Package KNAD6817VN6623814 Engine No G3LEMP207464 Make/Model KIA/STONIC 1.0 A PE E02R Colour/Trim MYW MOST YELLOW / WK SATURN BLACK

Account No	Terms	Date/Time Printed	CSE	Operator	WIP No		
LAX00000	Credit	31/03/2022/ 09:16	BLK	260 / AiTing	43742		
Description of Goods / Services				Qty	Unit Price	Disc%	Amount
M SUNDRY							✓ 120.00
APPLY SEALANT ON AFFECTED AREAS							
M SUNDRY							✓ 80.00
PERFORM RUST PREVENTION ON AFFECTED AREAS							
A 52900099							✓ 200.00
REPLACE LH FRONT SEAT ASSY							
A 54900099							✓ 30.00
CHECK WIRING & CHASSIS ELECTRICAL SYSTEM							
A 10028901							✓ 120.00
CONDUCT DIAGNOSTIC CHECK USING HI-SCAN PRO TEST AND CLEAR TROUBLE CODE							
M SUNDRY							✓ 30.00
SUNDRIES							
E PNT88000							1200.00
REPAIR RH REAR FENDER, LH FRONT BODY CHASSIS, & FRONT FENDER INNER BODY						→ Supp	
E PNT88000							? 500.00
VEHICLE MOUNTED ONTO FLOOR BENCH TO FACILITATE REPAIR							
E PNT98000							700.00
RESPLY RH REAR FENDER, LH FRONT BODY CHASSIS, & FRONT FENDER INNER BODY						→ Supp.	
E PNT88000							✓ 400.00
REPLACE ROOF LINING							
E PNT88000							✓ 400.00
REPLACE AIR BAG MODULE & ALL SAFETY BELTS							
S TYRESALES2							✓ 260.00
SUPPLY TIRE YOKOHAMA AE51 185/65R15 (L/F)							
S SPECIALISTJOB							✓ 80.00
VACUUM & TOP UP A/COND GAS							
S SPECIALISTJOB							✓ 220.00
SUPPLY & REPLACE FRONT WINDSCREEN GLASS SOLAR FILM - RIKECOOL							
X EXC							-3600.00
EXCESS FOR INSURANCE CLAIM							
X LAMP ASSY-HEAD,LH					1.00	✓ 1845.00 20.00	1476.00

PRO-FORMA INVOICE

Co Reg No : 199405410K

THIS IS NOT AN OFFICIAL TAX INVOICE

GST Reg No : MR-8500111-X

Invoice Name & Address	Owner Name & Vehicle Info
AIG Asia Pacific Insurance Pte. Ltd. MOTOR CLAIM DEPARTMENT 78 SHENTON WAY #09-16 AIG BUILDING SINGAPORE 079120 Contact No 64191000 13/12/2021	Cust No/Name LCV14671/SEAH BOON WEE Reg No/Reg Date SJN96G / 27/10/2021 Date In/Mileage 08/12/2021/ 1635 Chassis/Package KNAD6817VN6623814 Engine No G3LEMP207464 Make/Model KIA/STONIC 1.0 A PE E02R Colour/Trim MYW MOST YELLOW / WK SATURN BLACK

Account No	Terms	Date/Time Printed	CSE	Operator	WIP No			
LAX00000	Credit	31/03/2022/ 09:16	BLK	260 / AiTing	43742			
Description of Goods / Services					Qty	Unit Price	Disc%	Amount
X	AIR GUIDE				1.00	✓ 52.00	20.00	41.60
X	RADIATOR ASSY				1.00	✓ 696.00	20.00	556.80
X	PANEL ASSY-UNDER COVER				1.00	✓ 65.00	20.00	52.00
X	COOLER ASSY-INTER				1.00	✓ 564.00	20.00	451.20
X	DUCT-EXTENSION				1.00	✓ 75.00	20.00	60.00
X	DUCT ASSY-AIR				1.00	✓ 78.00	20.00	62.40
X	SHAFT ASSY-DRIVE,LH				1.00	✓ 859.00	20.00	687.20
X	MODULE ASSY-AIR BAG CONTROL				1.00	✓ 687.00	20.00	549.60
X	CURTAIN AIR BAG MODULE,LH				1.00	✓ 1576.00	20.00	1260.80
X	STRUT ASSY-FR,LH				1.00	✓ 269.00	20.00	215.20
X	PAD-FRONT SPRING,LWR				1.00	✓ 14.00	20.00	11.20
X	PAD-FRONT SPRING,UPR				1.00	✓ 9.00	20.00	7.20
X	SEAT ASSY-SPRING,UPR				1.00	✓ 20.00	20.00	16.00
X	INSULATOR ASSY-STRUT,LH				1.00	✓ 37.00	20.00	29.60
X	LINK-STABILIZER				1.00	✓ 94.00	20.00	75.20
X	BAR ASSY-FR STABILIZER				1.00	✓ 198.00	20.00	158.40
X	KNUCKLE-FRONT AXLE,LH				1.00	✓ 340.00	20.00	272.00
X	HUB ASSY-FR WHEEL				1.00	✓ 145.00	20.00	116.00
X	BEARING-FRONT WHEEL HUB				1.00	✓ 131.00	20.00	104.80
X	CARRIER ASSY-FRONT END MODULE				1.00	✓ 556.00	20.00	444.80
X	BEAM COMPLETE-FR BUMPER				1.00	✓ 544.00	20.00	435.20
X	BRACKET ASSY-FENDER & BPR MTG,				1.00	✓ 16.00	20.00	12.80
X	BRACKET ASSY-CARRIER MTG,LH				1.00	✓ 27.00	20.00	21.60
X	ARM COMPLETE-FR LWR,LH				1.00	✓ 294.00	20.00	235.20
X	PANEL-FENDER,LH				1.00	✓ 401.00	20.00	320.80
X	PANEL ASSY-FRONT DOOR,RH				1.00	✓ 858.00	20.00	686.40
X	PANEL ASSY-REAR DOOR,RH				1.00	✓ 936.00	20.00	748.80
X	PANEL COMPL-FRONT DOOR TRIM,LH				1.00	✓ 421.00	20.00	336.80
X	HEADLINING ASSY				1.00	✓ 1193.00	20.00	954.40
X	BLACK TAPE-FR DR FRAME UPR,RH				1.00	✓ 13.00	20.00	10.40
X	TAPE-FR DR BLACK FRAME RR,RH				1.00	✓ 13.00	20.00	10.40
X	TAPE-RR DR BLACK FRAME FR,RH				1.00	✓ 13.00	20.00	10.40
X	BLACK TAPE-RR DR FRAME UPR,RH				1.00	✓ 7.00	20.00	5.60

PRO-FORMA INVOICE

Co Reg No : 199405410K

THIS IS NOT AN OFFICIAL TAX INVOICE

GST Reg No : MR-8500111-X

Invoice Name & Address	Owner Name & Vehicle Info
AIG Asia Pacific Insurance Pte. Ltd. MOTOR CLAIM DEPARTMENT 78 SHENTON WAY #09-16 AIG BUILDING SINGAPORE 079120 Contact No 64191000 13/12/2021	Cust No/Name LCV14671/SEAH BOON WEE Reg No/Reg Date SJN96G / 27/10/2021 Date In/Mileage 08/12/2021/ 1635 Chassis/Package KNAD6817VN6623814 Engine No G3LEMP207464 Make/Model KIA/STONIC 1.0 A PE E02R Colour/Trim MYW MOST YELLOW / WK SATURN BLACK

Account No	Terms	Date/Time Printed	CSE	Operator	WIP No
LAX00000	Credit	31/03/2022/ 09:16	BLK	260 / AiTing	43742
Description of Goods / Services		Qty	Unit Price	Disc%	Amount
X GARNISH-QTR SIDE RH		1.00	✓ 50.00	20.00	40.00
X GARNISH ASSY-RR DR SIDE,RH		1.00	✓ 92.00	20.00	73.60
X GARNISH ASSY-FR DR SIDE RH		1.00	✓ 82.00	20.00	65.60
X GARNISH ASSY-FNDR SIDE,RH		1.00	✓ 45.00	20.00	36.00
X MOULDING ASSY-SIDE SILL,RH		1.00	✓ 248.00	20.00	198.40
X MOULDING ASSY-SIDE SILL,LH		1.00	✓ 248.00	20.00	198.40
X GARNISH ASSY-FNDR SIDE,LH		1.00	✓ 45.00	20.00	36.00
X MIRROR ASSY-OUTSIDE RR VIEW,RH		1.00	✓ 585.00	20.00	468.00
X GLASS-WINDSHIELD		1.00	✓ 851.00	20.00	680.80
X MOULDING-WINDSHIELD GLASS		1.00	✓ 52.00	20.00	41.60
X PAD-WINDSHIELD GLASS		12.00	✓ 2.00	20.00	19.20
X STOPPER-RR WINDOW GLASS		2.00	✓ 4.00	20.00	6.40
X S/BELT ASSY-RR,RH		1.00	✓ 266.00	20.00	212.80
X S/BELT ASSY-RR,LH		1.00	✓ 266.00	20.00	212.80
X S/BELT ASSY-FR RH		1.00	✓ 323.00	20.00	258.40
X S/BELT ASSY-FR LH		1.00	✓ 323.00	20.00	258.40
X BACK ASSY-FR SEAT,LH		1.00	✓ 1374.00	20.00	1099.20
X GUARD ASSY-FRONT WHEEL,LH		1.00	✓ 56.00	20.00	44.80
X COVER-FR BUMPER UPR		1.00	✓ 476.00	20.00	380.80
X COVER-FR BUMPER,LWR		1.00	✓ 367.00	20.00	293.60
X SKID PLATE-FR BUMPER		1.00	✓ 55.00	20.00	44.00
X LIP-FR BUMPER		1.00	✓ 42.00	20.00	33.60
X GRILLE-FRONT BUMPER		1.00	✓ 247.00	20.00	197.60
X AIR DUCT-FR BUMPER,LH		1.00	✓ 38.00	20.00	30.40
X COVER-BLANKING FR FOG LH		1.00	✓ 28.00	20.00	22.40
X ABSORBER-FRONT BUMPER ENERGY		1.00	✓ 98.00	20.00	78.40
X STIFFNER-FR BPR LWR		1.00	✓ 123.00	20.00	98.40
X BRACKET-FR BUMPER SIDE,LH		1.00	✓ 13.00	20.00	10.40
X WHEEL ASSY-ALUMINIUM	→ Supp.	3.00	✓ 659.00	20.00	1581.60
X BRACKET, IU ADHESIVE		1.00	✓ 26.00	00.00	26.00
X COVER-RR BUMPER LWR		1.00	385.00	20.00	308.00
X BLOWER ASSY		1.00	643.00	20.00	514.40
X CONDENSER ASSY-COOLER	} Supp.	1.00	648.00	20.00	518.40

PRO-FORMA INVOICE

Co Reg No : 199405410K

THIS IS NOT AN OFFICIAL TAX INVOICE

GST Reg No : MR-8500111-X

Invoice Name & Address	Owner Name & Vehicle Info
AIG Asia Pacific Insurance Pte. Ltd. MOTOR CLAIM DEPARTMENT 78 SHENTON WAY #09-16 AIG BUILDING SINGAPORE 079120 Contact No 64191000 13/12/2021	Cust No/Name LCV14671/SEAH BOON WEE Reg No/Reg Date SJN96G / 27/10/2021 Date In/Mileage 08/12/2021/ 1635 Chassis/Package KNAD6817VN6623814 Engine No G3LEMP207464 Make/Model KIA/STONIC 1.0 A PE E02R Colour/Trim MYW MOST YELLOW / WK SATURN BLACK

Account No	Terms	Date/Time Printed	CSE	Operator	WIP No
LAX00000	Credit	31/03/2022/ 09:16	BLK	260 / AiTing	43742
Description of Goods / Services		Qty	Unit Price	Disc%	Amount
X CLIP		10.00	1.00	20.00	8.00
X PANEL-FENDER,RH	} Supp.	1.00	430.00	20.00	344.00
X TAPE-RR DR FRAME BLACK RR,RH		1.00	6.00	20.00	4.80
X GARNISH ASSY-FRT DR SIDE,LH		1.00	82.00	20.00	65.60
X GARNISH ASSY-RR DR SIDE LH	} Supp.	1.00	92.00	20.00	73.60
X GARNISH-QTR SIDE.LH		1.00	50.00	20.00	40.00
X BOLT		1.00	6.00	20.00	4.80
X ANTIFREEZER		1.00	108.98	20.00	87.18
X INSULATOR-RADIATOR MTG,LWR		2.00	8.00	20.00	12.80
X TCU		1.00	1303.00	20.00	1042.40
X FUSE-SLOW BLOW 40A		1.00	5.00	20.00	4.00
X CROSSMEMBER COMPL		1.00	635.00	20.00	508.00
Z TEXT					
AIG OD CLAIM					
DOA : 08.12.21					
SURVEYOR STEVE-LKK 09.12.21					
REPAIR 25 DAYS					
Guarantee Your Warranty, Maintain with Cycle & Carriage!					

Parts	20,720.38	Nett	28,060.38
Labour	10,040.00	7% GST on	1964.23
Standard Menu	0.00		
Specialist Job	560.00	Total Payable	30,024.61
Diagnostics Job	0.00		
Sundry/Others	-3,260.00		
Total(w/o GST)	28,060.38		

This is not an official tax invoice.
 This is a computer generated document, no signature is required.


INSURANCE CO.: AIG

Supplementary Parts For Registration No.: SJN 96 G

	<u>Materials</u>	<u>Cost (\$)</u>
1	Wheel assy-Aluminium (x2) <i>CUT</i>	1,318.00 ✓
2	Cover-RR bumper Lwr <i>CUT</i>	385.00 ✓
3	Blower assy <i>BR</i>	643.00 ✓
4	Condenser assy-Cooler <i>DD</i>	648.00 ✓
5	Clips (x10) <i>NEC</i>	10.00 ✓
6	Panel-fender, RH <i>DD</i>	430.00 ✓
7	Tape-RR dr frame black RR, RH <i>NEC</i>	6.00 ✓
8	Garnish assy-RR dr side LH <i>CUT</i>	92.00 ✓
9	Garnish-Qtr side, LH <i>CUT</i>	50.00 ✓
10	Bolt <i>NEC</i>	6.00 ✓
11	Antifreezer <i>NEC</i>	108.98 ✓
12	Insulator-radiator mtg, Lwr (x2) <i>NEC</i>	16.00 ✓
13	TCU <i>(fault Code) - Shorted</i>	1,303.00 ✓
14	Fuse-Slow blow 40A <i>NEC</i>	5.00 ✓
Total Materials		5,020.98
Less 20% discount		1,004.20
Total after discount		4,016.78

	<u>Labour</u>	<u>Cost (\$)</u>
1	Repair RH rear fender, LH front body chassis, & front fender inner body	1,200.00 ✓
2	Respray RH rear fender, LH front body chassis, & front fender inner body	700.00 ✓
Total labour		1,900.00
Total amount		5,916.78
7% GST		414.17
Grand total		<u>\$ 6,330.96</u>

Thank You.
Yours faithfully



LOI ATTING
SENIOR OFFICER - ADMIN
KIA SERVICE CENTRE
DID : 6568 4556 / 6568 4501
FAX : 6567 5258 / 6565 1240

CAR NO: SJN 9664WIP: 43742 (ADDITIONAL PARTS CHANGE)

S/NO	PARTS NAME	? / SUPP	CSA SIGN	PHOTO TAKEN	REMARKS
1	Aircon Condenser Assy bt	? / SUPP			
2	Radiator Fan Assy CA	? / SUPP			
3	Inter Cooler Hose Lower	? / SUPP			
4	Inter Cooler Cover (Airguard)	? / SUPP	CA		
5	Clip Front Bumper X10 nec	? / SUPP			
6	Coolant Radiator Nc	? / SUPP			
7	Panel Fender RH FH bt	? / SUPP			
8	Radiator lower Mounting X2	? / SUPP	MIS		Missing
9	Black Tape RR Door Rear nec	? / SUPP			
10	Garnish Assy Front door side LH SC	? / SUPP			
11	Garnish Assy RR door side LH SC	? / SUPP			
12	Garnish Assy Gtr Side LH SC	? / SUPP			
13	Stabilizer bar, fwd	? / SUPP			
14		? / SUPP			
15	Repair RR fender RH	? / SUPP			
16	Repair Front LH Body Chassis + Front	? / SUPP			
17	Fender Inner Body	? / SUPP			
18	Floor Bench Pulling Repair	? / SUPP			
19	Manifing RR RH fender	? / SUPP			
20	Painting Vnt LH Body chassis + FR fender	? / SUPP			

DATE	TAKEN BY

PHOTO BEFORE PAINT

PHOTO AFTER PAINT

PHOTO OF MOUNT TO CELLETE BENCH

REMOVE AND INSTALL ENGINE

REMOVE AND INSTALL DASHBAORD

REMOVE & INSTALL FUEL TANK

PHOTO UNDERCARRIAGE PARTS

MODEL: StonicSURVEYOR: Steve - Luk

Work Order: R001646
License: sjn 96 g
Technician: kfsan 810119
Mileage: 1641
Date: 1.1.11 0:30

Kia : Stonic : 2021- (YB CUV) : Rest of World

Front : Left

Actual	Before	Specified Range
-0°21'	-0°21'	-0°54' 0°06'
3°57'*	3°57'*	4°02' 5°02'
0°08'	0°08'	-0°02' 0°11'
10°45'*	10°45'*	12°30' 13°30'
10°24'*	10°24'*	11°36' 13°36'

Camber
Caster
Toe
SAI
Included Angle
Turning Angle Diff.

Front : Right

Actual	Before	Specified Range
-0°42'	-0°42'	-0°54' 0°06'
4°22'	4°22'	4°02' 5°02'
0°07'	0°08'	-0°02' 0°11'
9°03'*	9°03'*	12°30' 13°30'
8°21'*	8°21'*	11°36' 13°36'

Front

Cross Camber
Cross Caster
Cross SAI
Total Toe
Cross Turn Diff.

Actual	Before	Specified Range
0°21'	0°20'	
-0°25'	-0°25'	
1°42'	1°42'	
0°15'	0°15'	-0°03' 0°21'

Rear : Left

Actual	Before	Specified Range
-1°13'	-1°12'	-2°00' -1°00'
-0°01'	0°00'	-0°02' 0°16'

Camber
Toe

Rear : Right

Actual	Before	Specified Range
-1°42'	-1°42'	-2°00' -1°00'
0°17'*	0°17'*	-0°02' 0°16'

Rear

Cross Camber
Total Toe
Thrust Angle

Actual	Before	Specified Range
0°30'	0°30'	
0°17'	0°17'	-0°05' 0°31'
-0°09'	-0°09'	

* This value is not within specification. Tire wear, handling and safety problems may result.

HOME
 Online
STONIC(YB CU../2022/G 1.0 T-G..)
VCI

Fault Code Searching

Rescan

Erase All DTC

Go to DTC

Save

11/11

System	Status	Result
ENGINE	No Current DTC	Good
AT	No Current DTC	Good
ABSESP	No Current DTC	Good
AIRBAG	No Current DTC	Good
AIRCON	No Current DTC	Good
EPS	No Current DTC	Good

System	DTC	Description	State
No Current DTC			

S/W Ver.	M-E-K-01-00-0266	VCI Ver.	02.63
ECU Ver.	M-E-K-01-00-0205	OS Ver.	Android 10