

Co Reg No : 199405410K

ESTIMATE

GST Reg No : MR-8500111-X

Invoice Name & Address	Owner Name & Vehicle Info														
AIG Asia Pacific Insurance Pte. Ltd. MOTOR CLAIM DEPARTMENT 78 SHENTON WAY #09-16 AIG BUILDING SINGAPORE 079120 Contact No 64191000	<table> <tr> <td>Cust No/Name</td><td>/SEAH BOON WEE</td></tr> <tr> <td>Reg No/Reg Date</td><td>SJN96G / 27/10/202</td></tr> <tr> <td>Date In/Mileage</td><td>08/12/2021/ 0</td></tr> <tr> <td>Chassis No</td><td>KNAD6817VN6623814</td></tr> <tr> <td>Engine No</td><td>G3LEMP207464</td></tr> <tr> <td>Make/Model</td><td>KIA/STONIC 1.0 A PE E02R</td></tr> <tr> <td>Colour/Trim</td><td>MYW MOST YELLOW / WK SATURN BLACK</td></tr> </table>	Cust No/Name	/SEAH BOON WEE	Reg No/Reg Date	SJN96G / 27/10/202	Date In/Mileage	08/12/2021/ 0	Chassis No	KNAD6817VN6623814	Engine No	G3LEMP207464	Make/Model	KIA/STONIC 1.0 A PE E02R	Colour/Trim	MYW MOST YELLOW / WK SATURN BLACK
Cust No/Name	/SEAH BOON WEE														
Reg No/Reg Date	SJN96G / 27/10/202														
Date In/Mileage	08/12/2021/ 0														
Chassis No	KNAD6817VN6623814														
Engine No	G3LEMP207464														
Make/Model	KIA/STONIC 1.0 A PE E02R														
Colour/Trim	MYW MOST YELLOW / WK SATURN BLACK														

Account No	Terms	Date/Time Printed	CSE	Operator	WIP No
LAX00000	Credit	08/12/2021/ 21:20	BLK	282 / Kevin Leong	43742
Description of Goods / Services					
	Qty	Unit Price	Disc%	Amount	
E PNT88000 REPLACE FRT BUMPER, FRT LH FENDER, SUPPORT, LH SIDE SILL, FRT LH WHEEL HOUSING & AFFECTED AREA REPAIR ON FRT LH BODY CHASSIS & FRT LH FENDER INNER				3200.00	
E PNT98000 PAINT WORK ON FRT BUMPER, FRT LH FENDER, FRT LH DOOR, FRT LH FENDER INNER, FRT LH WHEEL HOUSING & FRT LH BODY CHASSIS				2100.00	
E PNT88000 REPLACE FRT RH DOOR, REAR RH DOOR, RH WING MIRROR, RH SIDE SILL & AFFECTED AREA REPAIR ON FRT RH A-PILLAR & FRT RH FENDER				1680.00	
E PNT98000 PAINT WORK ON FRT RH DOOR, REAR RH DOOR, FRT RH FENDER, FRT RH A-PILLAR & RH WING MIRROR COVER				1750.00	
E PNT88000 REMOVE & INSTALL RADIATOR, CONDENSER FOR FACILITATE REPAIR				120.00	
M SUNDRY TO TOP UP AIRCON GAS				80.00	
E PNT88000 TO TRANSFER FRT RH DOOR ATTACHMENTS TO NEW PANEL				120.00	
E PNT88000 TO TRANSFER REAR RH DOOR ATTACHMENTS TO NEW PANEL				120.00	
E PNT88000 REPLACE FRT WINDSCREEN GLASS				240.00	
M SUNDRY TO APPLY WINDSCREEN SEALANT				80.00	
A 21900099 REPLACE CLUTCH ACTUATOR MOTOR				400.00	
A 33900099 REPLACE FRT UNDERCARRIAGE				400.00	
A 52900099 REPLACE ROOF LINING				400.00	
A 52900099				400.00	

Confirm & accepted by

Authorized signatory and company stamp

Validity of this estimate is 14 days from date of quote. This is a computer generated document, no signature is required. Estimated costs quoted are excluding GST. We would mention that the above estimate is based on our initial inspection and does not include any additional parts or labour which may be required after repair work has commenced. Occasionally worn or damaged parts are discovered after work has started and needed for repairs or replacement. However, should this occur, we would advise you. Please be informed that a deposit of 50% of the above estimate is payable before commencement of the work. Payment for this may be made in cash, credit card or cheque. You must also agree to pay full amount for renewal of the windscreen in the event of inadvertent breakage in the course of renewing the rubber seal or other repair requiring the removal of the windscreen.



CYCLE & CARRIAGE

CYCLE & CARRIAGE KIA PTE LTD
PANDAN GARDENS CUSTOMER SERVICE CENTRE

209 Pandan Gardens Singapore 609339 Tel: 65684555 Fax: 65651240



Movement that inspires

Co Reg No : 199405410K

ESTIMATE

GST Reg No : MR-8500111-X

Invoice Name & Address	Owner Name & Vehicle Info	
AIG Asia Pacific Insurance Pte. Ltd. MOTOR CLAIM DEPARTMENT 78 SHENTON WAY #09-16 AIG BUILDING SINGAPORE 079120 Contact No 64191000	Cust No/Name	/SEAH BOON WEE
	Reg No/Reg Date	SJN96G / 27/10/202
	Date In/Mileage	08/12/2021/ 0
	Chassis No	KNAD6817VN6623814
	Engine No	G3LEMP207464
	Make/Model	KIA/STONIC 1.0 A PE E02R
	Colour/Trim	MYW MOST YELLOW / WK SATURN BLACK

Account No	Terms	Date/Time Printed	CSE	Operator	WIP No		
LAX00000	Credit	08/12/2021/ 21:20	BLK	282 / Kevin Leong	43742		
Description of Goods / Services				Qty	Unit Price	Disc%	Amount
REPLACE AIRBAG MODULE & ALL SAFETY BELTS							
E PNT88000							200.00
REPLACE INTERCOOLER ASSY							
B WHEELALIGNMENT							120.00
To Conduct Computerize Full Wheel Alignment							
M SUNDRY							30.00
TO TRANSFER FRT LH RIM INCLUDING BALANCING							
M SUNDRY							120.00
TO APPLY SEALANT ON AFFECTED AREA							
M SUNDRY							120.00
PERFORM RUST PREVENTION							
E PNT88000							500.00
TO MOUNT ON FLOOR BENCH							
A 52900099							400.00
REPLACE FRT LH SEAT ASSY							
A 54900099							30.00
CHECK WIRING & CHASSIS ELECTRICAL SYSTEM							
A 10028901							120.00
TO CARRY OUT DIAGNOSTIC CHECK ON ELECTRONIC CONTROL SYSTEM							
M SUNDRY							780.00
TO SUPPLY 3 PCS TYRE							
M SUNDRY							50.00
SUNDRIES							
M SUNDRY							220.00
TO SUPPLY FRT WINDSCREEN GLASS SOLAR FILM							
M SUNDRY							
CLUTCH ACTUATOR ASSY							
M LAMP ASSY-HEAD,LH				1.00	1845.00	20.00	1476.00
M AIR GUIDE				1.00	52.00	20.00	41.60
M RADIATOR ASSY				1.00	696.00	20.00	556.80
M PANEL ASSY-UNDER COVER				1.00	65.00	20.00	52.00
M COOLER ASSY-INTER				1.00	564.00	20.00	451.20
M HOSE&PIPE ASSY-I/C INLET				1.00	368.00	20.00	294.40

Confirm & accepted by

Authorized signatory and company stamp

Validity of this estimate is 14 days from date of quote. This is a computer generated document, no signature is required. Estimated costs quoted are excluding GST. We would mention that the above estimate is based on our initial inspection and does not include any additional parts or labour which may be required after repair work has commenced. Occasionally worn or damaged parts are discovered after work has started and needed for repairs or replacement. However, should this occur, we would advise you. Please be informed that a deposit of 50% of the above estimate is payable before commencement of the work. Payment for this may be made in cash, credit card or cheque. You must also agree to pay full amount for renewal of the windscreen in the event of inadvertent breakage in the course of renewing the rubber seal or other repair requiring the removal of the windscreen.



CYCLE & CARRIAGE

CYCLE & CARRIAGE KIA PTE LTD

PANDAN GARDENS CUSTOMER SERVICE CENTRE

209 Pandan Gardens Singapore 609339 Tel: 65684555 Fax: 65651240



Movement that inspires

Co Reg No : 199405410K

ESTIMATE

GST Reg No : MR-8500111-X

Invoice Name & Address	Owner Name & Vehicle Info	
AIG Asia Pacific Insurance Pte. Ltd. MOTOR CLAIM DEPARTMENT 78 SHENTON WAY #09-16 AIG BUILDING SINGAPORE 079120 Contact No 64191000	Cust No/Name	/SEAH BOON WEE
	Reg No/Reg Date	SJN96G / 27/10/202
	Date In/Mileage	08/12/2021/ 0
	Chassis No	KNAD6817VN6623814
	Engine No	G3LEMP207464
	Make/Model	KIA/STONIC 1.0 A PE E02R
	Colour/Trim	MYW MOST YELLOW / WK SATURN BLACK

Account No	Terms	Date/Time Printed	CSE	Operator	WIP No
LAX00000	Credit	08/12/2021/ 21:20	BLK	282 / Kevin Leong	43742
Description of Goods / Services		Qty	Unit Price	Disc%	Amount
M DUCT-EXTENSION		1.00	75.00	20.00	60.00
M CLEANER ASSY-AIR		1.00	150.00	20.00	120.00
M DUCT ASSY-AIR		1.00	78.00	20.00	62.40
M SHIELD ASSY-HEAT		1.00	10.00	20.00	8.00
M SHIELD-AIR INTAKE		1.00	12.00	20.00	9.60
M SHAFT ASSY-DRIVE,LH		1.00	859.00	20.00	687.20
M MODULE ASSY-AIR BAG CONTROL		1.00	687.00	20.00	549.60
M CURTAIN AIR BAG MODULE,LH		1.00	1576.00	20.00	1260.80
M STRUT ASSY-FR,LH		1.00	269.00	20.00	215.20
M PAD-FRONT SPRING,LWR		1.00	14.00	20.00	11.20
M PAD-FRONT SPRING,UPR		1.00	9.00	20.00	7.20
M SEAT ASSY-SPRING,UPR		1.00	20.00	20.00	16.00
M INSULATOR ASSY-STRUT,LH		1.00	37.00	20.00	29.60
M COVER-INSULATOR DUST		1.00	30.00	20.00	24.00
M LINK-STABILIZER		1.00	94.00	20.00	75.20
M BAR ASSY-FR STABILIZER		1.00	198.00	20.00	158.40
M KNUCKLE-FRONT AXLE,LH		1.00	340.00	20.00	272.00
M HUB ASSY-FR WHEEL		1.00	145.00	20.00	116.00
M BEARING-FRONT WHEEL HUB		1.00	131.00	20.00	104.80
M GEAR ASSY-STEERING		1.00	923.00	20.00	738.40
M CARRIER ASSY-FRONT END MODULE		1.00	556.00	20.00	444.80
M BEAM COMPLETE-FR BUMPER		1.00	544.00	20.00	435.20
M REINF-FENDER APRON UPR,LH		1.00	62.00	20.00	49.60
M BRACKET ASSY-FENDER & BPR MTG,		1.00	16.00	20.00	12.80
M PANEL ASSY-FNDR APRON,LH		1.00	263.00	20.00	210.40
M BRACKET ASSY-CARRIER MTG,LH		1.00	27.00	20.00	21.60
M CROSSMEMBER COMPL		1.00	635.00	20.00	508.00
M ARM COMPLETE-FR LWR,LH		1.00	294.00	20.00	235.20
M PANEL-FENDER,LH		1.00	401.00	20.00	320.80
M INSULATOR-FENDER LH		1.00	27.00	20.00	21.60
M PANEL ASSY-FRONT DOOR,RH		1.00	858.00	20.00	686.40
M PANEL ASSY-REAR DOOR,LH		1.00	768.00	20.00	614.40
M PANEL COMPL-FRONT DOOR TRIM,LH		1.00	421.00	20.00	336.80

Confirm & accepted by

Authorized signatory and company stamp

Validity of this estimate is 14 days from date of quote. This is a computer generated document, no signature is required. Estimated costs quoted are excluding GST. We would mention that the above estimate is based on our initial inspection and does not include any additional parts or labour which may be required after repair work has commenced. Occasionally worn or damaged parts are discovered after work has started and needed for repairs or replacement. However, should this occur, we would advise you. Please be informed that a deposit of 50% of the above estimate is payable before commencement of the work. Payment for this may be made in cash, credit card or cheque. You must also agree to pay full amount for renewal of the windscreen in the event of inadvertent breakage in the course of renewing the rubber seal or other repair requiring the removal of the windscreen.



CYCLE & CARRIAGE

CYCLE & CARRIAGE KIA PTE LTD
PANDAN GARDENS CUSTOMER SERVICE CENTRE

209 Pandan Gardens Singapore 609339 Tel: 65684555 Fax: 65651240



Co Reg No : 199405410K

ESTIMATE

GST Reg No : MR-8500111-X

Invoice Name & Address	Owner Name & Vehicle Info	
AIG Asia Pacific Insurance Pte. Ltd. MOTOR CLAIM DEPARTMENT 78 SHENTON WAY #09-16 AIG BUILDING SINGAPORE 079120 Contact No 64191000	Cust No/Name	/SEAH BOON WEE
	Reg No/Reg Date	SJN96G / 27/10/202
	Date In/Mileage	08/12/2021/ 0
	Chassis No	KNAD6817VN6623814
	Engine No	G3LEMP207464
	Make/Model	KIA/STONIC 1.0 A PE E02R
	Colour/Trim	MYW MOST YELLOW / WK SATURN BLACK

Account No	Terms	Date/Time Printed	CSE	Operator	WIP No
LAX00000	Credit	08/12/2021/ 21:20	BLK	282 / Kevin Leong	43742
Description of Goods / Services		Qty	Unit Price	Disc%	Amount
M HEADLINING ASSY		1.00	1193.00	20.00	954.40
M W/STRIP ASSY-FR DR BELT O/S RH		1.00	43.00	20.00	34.40
M W/STRIP ASSY-FR DR SIDE RH		1.00	90.00	20.00	72.00
M W/STRIP-FR DR BELT I/S RH		1.00	28.00	20.00	22.40
M W/STRIP ASSY-RR DR BELT O/S RH		1.00	51.00	20.00	40.80
M W/STRIP ASSY-RR DR SIDE RH		1.00	130.00	20.00	104.00
M W/STRIP-RR DR BELT I/S RH		1.00	21.00	20.00	16.80
M BLACK TAPE-FR DR FRAME UPR,RH		1.00	13.00	20.00	10.40
M TAPE-FR DR BLACK FRAME RR,RH		1.00	13.00	20.00	10.40
M TAPE-RR DR BLACK FRAME FR,RH		1.00	13.00	20.00	10.40
M BLACK TAPE-RR DR FRAME UPR,RH		1.00	7.00	20.00	5.60
M GARNISH-QTR SIDE RH		1.00	50.00	20.00	40.00
M GARNISH ASSY-RR DR SIDE,RH		1.00	92.00	20.00	73.60
M GARNISH ASSY-FR DR SIDE RH		1.00	82.00	20.00	65.60
M GARNISH ASSY-FNDR SIDE,RH		1.00	45.00	20.00	36.00
M MOULDING ASSY-SIDE SILL,RH		1.00	248.00	20.00	198.40
M MOULDING ASSY-SIDE SILL,LH		1.00	248.00	20.00	198.40
M GARNISH ASSY-FNDR SIDE,LH		1.00	45.00	20.00	36.00
M GARNISH ASSY-FRT DR SIDE,LH		1.00	82.00	20.00	65.60
M MIRROR ASSY-OUTSIDE RR VIEW,RH		1.00	585.00	20.00	468.00
M COVER ASSY-FR DR QDRNT INR,RH		1.00	38.00	20.00	30.40
M COVER ASSY-FR DR QDRNT INR,LH		1.00	38.00	20.00	30.40
M GLASS-WINDSHIELD		1.00	851.00	20.00	680.80
M MOULDING-WINDSHIELD GLASS		1.00	52.00	20.00	41.60
M GARNISH ASSY-DELTA RH		1.00	33.00	20.00	26.40
M COVER ASSY-COWL TOP,LH		1.00	10.00	20.00	8.00
M PAD-WINDSHIELD GLASS		12.00	2.00	20.00	19.20
P STOPPER-RR WINDOW GLASS		2.00	4.00	20.00	6.40
M BASE-IINSIDE REAR VIEW MIRROR		1.00	27.00	20.00	21.60
M SENSOR-AUTO DEFOG		1.00	253.00	20.00	202.40
M S/BELT ASSY-RR,RH		1.00	266.00	20.00	212.80
M S/BELT ASSY-RR,LH		1.00	266.00	20.00	212.80
M BUCKLE ASSY-RR S/BELT,RH		1.00	101.00	20.00	80.80

Confirm & accepted by

Authorized signatory and company stamp

Validity of this estimate is 14 days from date of quote. This is a computer generated document, no signature is required. Estimated costs quoted are excluding GST. We would mention that the above estimate is based on our initial inspection and does not include any additional parts or labour which may be required after repair work has commenced. Occasionally worn or damaged parts are discovered after work has started and needed for repairs or replacement. However, should this occur, we would advise you. Please be informed that a deposit of 50% of the above estimate is payable before commencement of the work. Payment for this may be made in cash, credit card or cheque. You must also agree to pay full amount for renewal of the windscreen in the event of inadvertent breakage in the course of renewing the rubber seal or other repair requiring the removal of the windscreen.



CYCLE & CARRIAGE

CYCLE & CARRIAGE KIA PTE LTD

PANDAN GARDENS CUSTOMER SERVICE CENTRE

209 Pandan Gardens Singapore 609339 Tel: 65684555 Fax: 65651240



Movement that inspires

Co Reg No : 199405410K

ESTIMATE

GST Reg No : MR-8500111-X

Invoice Name & Address	Owner Name & Vehicle Info	
AIG Asia Pacific Insurance Pte. Ltd. MOTOR CLAIM DEPARTMENT 78 SHENTON WAY #09-16 AIG BUILDING SINGAPORE 079120 Contact No 64191000	Cust No/Name	/SEAH BOON WEE
	Reg No/Reg Date	SJN96G / 27/10/202
	Date In/Mileage	08/12/2021/ 0
	Chassis No	KNAD6817VN6623814
	Engine No	G3LEMP207464
	Make/Model	KIA/STONIC 1.0 A PE E02R
	Colour/Trim	MYW MOST YELLOW / WK SATURN BLACK

Account No	Terms	Date/Time Printed	CSE	Operator	WIP No
LAX00000	Credit	08/12/2021/ 21:20	BLK	282 / Kevin Leong	43742
Description of Goods / Services					
	Qty	Unit Price	Disc%	Amount	
M BUCKLE ASSY-RR S/BELT,LH	1.00	101.00	20.00	80.80	
M S/BELT ASSY-FR RH	1.00	323.00	20.00	258.40	
M S/BELT ASSY-FR LH	1.00	323.00	20.00	258.40	
M BUCKLE ASSY-FR S/BELT,RH	1.00	151.00	20.00	120.80	
M BUCKLE ASSY-FR S/BELT,LH	1.00	151.00	20.00	120.80	
M ADJUSTER ASSY-HEIGHT	1.00	37.00	20.00	29.60	
M BACK ASSY-FR SEAT,LH	1.00	1374.00	20.00	1099.20	
M SHIELD COVER-FR SEAT OTR,LH	1.00	40.00	20.00	32.00	
M GUARD ASSY-FRONT WHEEL,LH	1.00	56.00	20.00	44.80	
M COVER-WHEEL SPEED SENSOR,LH	1.00	13.00	20.00	10.40	
M COVER-FR BUMPER UPR	1.00	476.00	20.00	380.80	
M COVER-FR BUMPER,LWR	1.00	367.00	20.00	293.60	
M SKID PLATE-FR BUMPER	1.00	55.00	20.00	44.00	
M LIP-FR BUMPER	1.00	42.00	20.00	33.60	
M GRILLE-FRONT BUMPER	1.00	247.00	20.00	197.60	
M GRILLE ASSY-RADIATOR	1.00	324.00	20.00	259.20	
M AIR DUCT-FR BUMPER,LH	1.00	38.00	20.00	30.40	
M COVER-BLANKING FR FOG LH	1.00	28.00	20.00	22.40	
M MOULDING-FRONT BUMPER A/INTAKE	1.00	61.00	20.00	48.80	
M ABSORBER-FRONT BUMPER ENERGY	1.00	98.00	20.00	78.40	
M STIFFNER-FR BPR LWR	1.00	123.00	20.00	98.40	
M BRACKET-FR BUMPER SIDE,LH	1.00	13.00	20.00	10.40	
M STRIP-FR BUMPER	1.00	27.00	20.00	21.60	
M WHEEL ASSY-ALUMINIUM	1.00	659.00	20.00	527.20	
M BRACKET, IU ADHESIVE	1.00	26.00	00.00	26.00	

Confirm & accepted by

Nett 33,239.60
7% GST on 33239.60 2326.77

Total Payable 35,566.37

Authorized signatory and company stamp

Validity of this estimate is 14 days from date of quote. This is a computer generated document, no signature is required. Estimated costs quoted are excluding GST. We would mention that the above estimate is based on our initial inspection and does not include any additional parts or labour which may be required after repair work has commenced. Occasionally worn or damaged parts are discovered after work has started and needed for repairs or replacement. However, should this occur, we would advise you. Please be informed that a deposit of 50% of the above estimate is payable before commencement of the work. Payment for this may be made in cash, credit card or cheque. You must also agree to pay full amount for renewal of the windscreen in the event of inadvertent breakage in the course of renewing the rubber seal or other repair requiring the removal of the windscreen.