

AH LIM MOTOR COMPANY

No. 10 Ang Mo Kio Ind. Park 2A #01-09 AMK Autopoint Singapore 568047
 TEL: 6483 1244 (4 lines) FAX: 6483 6170 Email: ahlmmc@singnet.com.sg
 GST:M9-0009639-E RCB NO:06470300B

SURVEYOR COPY

M/S : SOMPO INSURANCE SINGAPORE PTE LTD
 50 RAFFLES PLACE
 #03-03 SINGAPORE LAND TOWER
 SINGAPORE 048623
TEL: 64616555
ATTN: Motor Claim Department

Estimate No: MC1902336
Date: 08 Dec 2021
Policy No: D21MTPV01011458
Veh Reg No: SJD5877P
Make/Model: SUBARU IMPREZA 5D
 2.5 WRX-S AWD 5MT

Your Ref No: -
Claim Type: Own Damage
Accident Date: 06/12/2021

Estimate Repair Cost to Vehicle No : SJD5877P

Description	U/Price	Quantity	Cost <u>S\$</u>	Amount <u>S\$</u>
SPARE PARTS				
1 FRONT BONNET		1 PC	380.00	
2 FRONT BONNET RUBBER FRONT CENTER		1 PC	25.00	
3 FRONT BONNET RUBBER CENTRE INNER		1 PC	15.00	
4 FRONT BONNET STOPPER LH & RH		2 PC	6.00	
5 FRONT BONNET HINGE LH & RH		2 PC	50.00	
6 HEADLAMP LH & RH WITH LOWER BEAM		2 PC	2,400.00	
7 RADIATOR GRILLE		1 PC	230.00	
8 RADIATOR GRILLE EMBLEM		1 PC	45.00	
9 RADIATOR GRILLE CLIPS		4 PC	6.00	
10 FRONT BUMPER		1 PC	250.00	
11 FRONT BUMPER TOW COVER		1 PC	10.00	
12 FRONT BUMPER LOWER GRILLE		1 PC	40.00	
13 FRONT BUMPER SIDE RETAINER RH		1 PC	10.00	
14 FRONT BUMPER SIDE RETAINER LH -CHECK PRICE		1 PC	0.0000	
15 FRONT BUMPER CLIPS		11 PC	16.50	
16 FRONT BUMPER LOWER BRACKET -CHECK PRICE		1 PC	0.0000	
17 FRONT BUMPER SPONGE		1 PC	65.00	
18 FRONT BUMPER REINFORCEMENT		1 PC	140.00	
19 FRONT BUMPER UNDERCOVER -CHECK PRICE		1 PC	0.0000	
20 FRONT FENDER LH & RH		2 PC	260.00	
21 FRONT FENDER COWLING LH & RH		2 PC	160.00	
22 FRONT FENDER COWLING CLIPS		20 PC	400.00	
23 FOG LAMP WITH BRACKET LH & RH		2 PC	260.00	
24 WASHER TANK		1 PC	60.00	
25 RADIATOR SUPPORT PANEL ASSEMBLY		1 PC	250.00	
26 RADIATOR SUPPORT PANEL LOWER FRAME		1 PC	65.00	
			5,143.50	
	Add 10%		514.35	5,657.85
 Special Nett				
27 COOLANT		1 PC	30.00	
28 NUMBER PLATE		1 PC	35.00	
29 FRONT BUMPER SPOILER -CHECK PRICE		1 PC	0.0000	

65.00

LABOUR

AH LIM MOTOR COMPANY

No. 10 Ang Mo Kio Ind. Park 2A #01-09 AMK Autopoint Singapore 568047
TEL: 6483 1244 (4 lines) FAX: 6483 6170 Email: ahlimmc@singnet.com.sg
GST:M9-0009639-E RCB NO:06470300B

M/S : SOMPO INSURANCE SINGAPORE PTE LTD
50 RAFFLES PLACE
#03-03 SINGAPORE LAND TOWER
SINGAPORE 048623
TEL: 64616555
ATTN: Motor Claim Department

Estimate No: MC1902336
Date: 08 Dec 2021
Policy No: D21MTPV01011458
Veh Reg No: SJD5877P
Make/Model: SUBARU IMPREZA 5D
2.5 WRX-S AWD 5MT

Your Ref No: -
Claim Type: Own Damage
Accident Date: 06/12/2021

Estimate Repair Cost to Vehicle No : SJD5877P

Description	U/Price	Quantity	Cost S\$	Amount S\$
30 TO DISCONNECT AND CHECK ELECTRICAL WIRING, WIRE SOCKETS AND ETC. TO REMOVE AND REINSTALL DAMAGED ELECTRICAL UNITS, TEST AND RECTIFY FOR PROPER FUNCTIONING.		1 PC	40.00	
31 TO REMOVE AND REPLACE A/C CONDENSER AND PIPES, RADIATOR AND HOSES, VACUUM A/C SYSTEM AS WELL AS REFILL A/C GAS.		1 PC	100.00	
32 TO DISMANTLE ALL DAMAGED PARTS. TO CUT & WELD RADIATOR SUPPORT PANEL. TO KNOCK & REPAIR FRONT WHEELHOUSE PANEL LH & RH, INNER PANELS AND AFFECTED AREAS. TO REFIT LISTED PARTS BACK SAME.		1 PC	800.00	
33 TO SPRAY BONNET, FRONT BUMPER, FRONT FENDER LH & RH, FRONT WHEELHOUSE PANEL LH & RH		1 PC	800.00	
				1,740.00

Repair Amount S\$ 7,462.85
Add GST @ 7% 522.40
Total Amount payable S\$ 7,985.25

TOTAL: SINGAPORE DOLLAR SEVEN THOUSAND NINE HUNDRED EIGHTY FIVE AND CENTS TWENTY FIVE ONLY

Please arrange this vehicle to be surveyed soonest possible.

Thank You

For AH LIM MOTOR COMPANY


AUTHORISED SIGNATURE