

**LKK Auto Consultants Pte Ltd** (Co.Reg.No:199607198R)51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park  
Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com;assignments@lkkauto.com

**VEHICLE DAMAGE INSPECTION REPORT****Our File No:** CS/CTI21012469/KVY3N2  
**Date:** 29/12/2021REFERENCE

Handling Insurer:	China Taiping Insurance (Singapore) Pte. Ltd.	Policy No:	DMPCSNW00103942100
<b>Claimant Vehicle No :</b>	SLJ3938E	<b>Insured Vehicle No :</b>	SMA6375U
Date of Loss:	07/12/2021	Nature of Claim:	TP
		Claim No:	SNM21D207130/C02/TOHHS

DESCRIPTION & IDENTIFICATION OF VEHICLE

Reg No:	<b>SLJ3938E</b>	Engine No:	10JBHD3050129
Make & Model:	CITROEN C4 PICASSO, 1.6 D BLUEHDI EAT6 (A)	Chassis No:	VF73DBHZTGJ642795
Reg. Date:	09/12/2016 (Man. Year: 2016)	Odometer:	0 km
Colour:	White		
Engine Capacity:	1560 cc		
Market Value/New Car Price:	N/A		
Sum Insured (S\$):	<b>Market Value/New Car Price</b>		

CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition:		Steering (Serviceable):	Yes	Footbrake (Serviceable):	Yes
Handbrake (Serviceable):	Yes	Engine Modification:	No	Pre-accident Condition:	

CONDITION OF TYRES

Front Tyre Size:	205/60R16	Rear Tyre Size:	205/60R16
Front Left Side:	Michelin 9 mm	Rear Left Side:	Michelin 9 mm
Front Right Side:	Michelin 9 mm	Rear Right Side:	Michelin 9 mm

*The above values represent the remaining tyre treads depth*

<b>COST OF CLAIMS</b>	<b>Repairer's</b>	<b>Adjuster's</b>	<b>Difference</b>	<b>Diff %</b>
Parts	8,795.05	5,074.38	3,720.67	42.30
Miscellaneous Items	0.00	0.00	0.00	
Labour	2,300.00	930.00	1,370.00	59.57
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
<b>Calculated Gross Total (S\$)</b>	<b>11,095.05</b>	<b>6,004.38</b>	<b>5,090.67</b>	<b>45.88</b>
<b>Approved Total (Overridden) (S\$)</b>		<b>4,650.00</b>		

**Nett Amount (S\$)**

**11,095.05**

**4,650.00**

**6,445.05**

**58.09**

---

INSPECTION

Date of Assignment: 09/12/2021

Date Inspected: 10/12/2021

Estimated Period of Repair: 5.0 days

Inspected At:

Poon Siang Seow (HQ)  
160 Sin Ming Drive, #05-13 Sin Ming AutoCity  
Singapore 575722

---

**Adjuster:** KENNETH KONG

**Manager:** VERON CHEN

*NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.*

## REPAIR DETAILS

### Reference

<b>Part Source:</b> MRM-SG	Version: 1.0 (Last Synchronised: 29 Dec 2021)
<b>Parts:</b> 144	CITROEN C4 PICASSO 1.6 D BLUEHDI EAT6 (A) (Catalogue:Merimen Singapore 1.0)
<b>Labour:</b> Repairer's	(Price-denominated Standard List)
<b>Print Code:</b> (Unsubmitted, no print-code for SLJ3938E)	
<b>Validity:</b>	These estimates are valid only if they contain the print code (above) on all estimate pages, running page numbers with the END OF ESTIMATES marker on the last estimate page
<b>Further Info:</b>	Items/values not in reference catalogue are prefixed with an asterisk *.

### Recommended Parts

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
1	1		*TAIL GATE	Cracked	2,879.50 F	*2,450.00 FL
2	1		*TAIL GATE LOCK	Repair	179.35 F	*- FL
3	1		*TAIL GATE LOGO	Not Necessary	68.00 F	*- FL
4	1		*TAIL GATE BADGE CITROEN	Not Necessary	58.00 F	*- FL
5	1		*TAIL GATE BADGE PICASSO	Not Necessary	65.00 F	*- FL
6	1		*TAIL GATE BADGE C4 BLUEHDI	Not Necessary	85.00 F	*- FL
7	1		*TAIL GATE BADGE	Necessary	50.00 F	*50.00 FL
8	1		*TAIL GATE LOWER GARISH COVER	Serviceable	730.95 F	*- FL
9	1		*TAIL GATE RUBBER	Serviceable	196.80 F	*- FL
10	2		*TAIL GATE DAMPER	Serviceable	439.50 F	*- FL
11	1		*REAR PANEL	Bent	886.80 F	*886.80 FL
12	1		*REAR PANEL TOP GARISH	Serviceable	254.75 F	*- FL
13	1		*REAR BUMPER	Buckled	1,329.00 F	*1,329.00 FL
14	1		*REAR BUMPER REINFORCEMENT	Bent	568.00 F	*568.00 FL
15	2		*REAR BUMPER REFLECTOR	Serviceable	120.00 F	*- FL
16	1		*REAR BUMPER SENSOR	Serviceable	350.00 F	*- FL
17	2		*REAR BUMPER RETAINER	Serviceable	180.00 F	*- FL
18	1		*REAR BUMPER LOWER COVER	Buckled/Distorted	354.40 F	*354.40 FL

F=Franchise part. L=ListItemDisc.

<b>Sub Total (\$)</b>	<b>8,795.05</b>	<b>5,638.20</b>
<b>- List Item Discount on L Items 0.00/10.00% (\$)</b>	0.00	563.82
<b>Total Parts (\$)</b>	<b>8,795.05</b>	<b>5,074.38</b>

Report was unsubmitted during this print-out.

## Recommended Miscellaneous Items

There are no new miscellaneous items selected.

## Recommended Labour

No	Particulars	Lab.Type	Repairer's	Amount
<b>Labour Items</b>				
1	RUST PROOFING	New	100.00	30.00
2	PANEL BEATING	New	1,200.00	400.00
3	SPRAY PAINTING	New	1,000.00	500.00
			<b>Gross Labour Cost (\$\$)</b>	<b>2,300.00</b>
				<b>930.00</b>

Report was unsubmitted during this print-out.

< END OF ESTIMATES >