

ASS. REC. BY: Tan JH

REF: CS / AIG21012470 / Tivf3

ASSIGNMENT

From: _____ Date: _____

Estimated Cost: _____

OD / WS / TP RES / OD RES / EVA / INV / MV

To Inspect Vehicle No: _____

at Workshop m/s _____

of _____

Insured: _____

Policy No. 1900129790

Claims No. 1762579462SG

Sum Insured: _____ Excess: 300

(Client's Record)

Make of Veh: _____

(Policy Condition)

Remark: The veh had commenced its repair at the time of inspection.

N/S	O/S

Bal. or Market Value: 48000

IDAC Accident Rpt: _____ Consistent? : Yes or No

GIA / PR Seen: _____ Consistent? : Yes or No

Est. Repairs: _____ days Res.: Yes or No

Lum Sum: _____ % 3 Val.: Yes or No

CA / REV / REP. / 24 HRS

Vehicle: IN / OUT

Date: _____ Person Contacted: _____

Veh No: FBN588Z Yr Regn: 2018, Jhy.

Type: M.Car / M.Cycle / Bus / Van / Lorry / Taxi / Prime Mover /

Truck / Trailer or

Make: Yamaha Super T152.0 150.

Colour: Black / 6.0 A/C: Insured / Std / NI / NA

Sp. Reading _____ T/Radio: Insured / Std / NI / NA

Eng/No: _____

C/No: MY 346074250-111919

Gen. Cond: Good / Fair / Poor / Burnt

Steering: Inorder / Jammed / Leaked / Burnt or

Brake: Inorder / Jammed / Leaked / Burnt or

Mod: Nil / S/Rim / STD A/Rim or

Tyre Size: F: 70/80R17

R: 100/70R12

BS / DUN / EXNOVA / GY / FS / LIZA / MIC / OHTSU / PIR / SUMI /

TOYO / YOKO or

maxxis

Front

Rear

R/Bal. 5 mm R/Bal. 5 mm

L/Bal. _____ mm L/Bal. _____ mm

D.O.A. 3/12/21

D.O.I. 9/12/21 @ 5pm

Survey held at Bike Roadshop

Des. of Damages: Front / Rear / O/S / N/S / U/C / Rooftop or

Front, fender, N/S

The U/C / Chassis frame / Body Structure affected due to collision.

Date / Time Action / Instruction Battery weak

6/1/22 LS \$3650 confirmed (Red 2355, 39%)

Date/Time, File Pass to?

☐ : Prel. Report

1)

☐ : Final Report

Date/Time, File Return to?

2) 6/1/22-typist

Days Of Repair: 3

Resurvey No. of Trip: 1

Survey Fee:

Transportation:

S + RS \$

Photos

Others

TOTAL

Add Fee:

☐ : Site Insp (\$

☐ : Interview (\$

☐ : Tech. Invs (\$

☐ : Weekend (\$

Rep. Format: Merimen

Lump Sum / L.S. (\$3650)

BIKE PRODUCTION PTE LTD
 610, Serangoon Road S(218216)
 Tel: 63922555, 62995177 Fax: 62975400
ROC/ GST Reg No.: 200007407G

Date: 9 Dec 2021

ASSESSMENT FOR REPAIR: YAMAHA SNIPER T150 - FBN588Z

Chassis No.:

Engine No.:


<u>Qty</u>	<u>Description</u>	<u>Estimate</u>
1 pc	Front disk	\$115.00 ?
1 pc	Front wheel axle	\$75.00 ?
1 pc	Right fork assembly	\$380.00 <i>bt</i>
1 pc	Left fork assembly	\$380.00 <i>bt</i>
1 pc	Front headlamp lower cover	\$105.00 <i>cr</i>
1 pc	Headlamp lower assy	\$250.00 <i>cr</i>
1 pc	Front mudguard	\$85.00 <i>cr</i>
2 pcs	Steering stem bearing @ \$45.00	\$90.00 <i>cr</i>
1 pc	Steering stem bracket assembly	\$195.00 <i>bt</i>
1 pc	Handle bar	\$125.00 ?
1 pc	Right fairing	\$105.00 <i>cr</i>
1 pc	Left fairing	\$105.00 <i>cr</i>
2 pcs	Fairing stickers @ \$55.00	\$110.00 <i>cr</i>
1 pc	Right front signal	\$65.00 <i>cr</i>
1 pc	Brake pedal assy	\$75.00 X
1 pc	Right balancer	\$45.00 <i>bt</i>
1 pc	Front footrest holder assembly	\$145.00 X
1 pc	Left clutch lever	\$45.00 <i>bt</i>
1 pc	Left balancer	\$45.00 <i>bt</i>
1 pc	Left engine cover	\$195.00 <i>dd</i>
1 pc	Left engine cover gasket	\$45.00 <i>cr</i>
1 pc	Gear pedal assy	\$145.00 <i>bt</i>
1 pc	Center basket	\$30.00 X
1 pc	Left rear side cover	\$105.00 <i>bt</i>
1 pc	Left rear side cover sticker	\$45.00 <i>cr</i>
1 pc	Left front foot rest	\$55.00 <i>dd</i>
1 pc	Left rear footrest	\$45.00 <i>dd</i>
1 pc	Mainstand	\$125.00 <i>bt</i>
1 pc	Left rear signal	\$55.00 <i>bt</i>
1 pc	Meter assy	\$245.00 X
1 pc	Center H cover	\$75.00 <i>cr</i>
1 pc	Exhaust long cover	\$95.00 X
	Less discount 10%	\$3,800.00
		\$380.00
		\$3,420.00
	<u>Special nett items</u>	
1 pc	Engine oil	\$35.00 <i>cr</i>
1 pc	Front sport rim assy	\$350.00 ?
1)	Towing charges	\$100.00 ? <i>by receipt</i>
2)	Dismantle, replace, realign and adjust above damaged parts	\$700.00 <i>300</i>

- | | | |
|----|--|-----------------------|
| 4) | To knock, straighten chassis & body balancing | 200? plus
\$380.00 |
| 5) | To remove/refit, replace (if damage) check and straighten front fork tubes | \$180.00 120? plus |
| 6) | To remove/refit and balance front sport rim | \$90.00 30. |
| 7) | Spray painting | \$300.00 200 |

Total Estimate

\$5,555.00

Note: The above estimate is subjected to the prevailing GST of 7%


For Bike Production Pte Ltd

Tanpin 97495749

Not Authorise, Revert

Ex: to be advise 9/12/21 esp

3 days

Tanpin @ Ikharu town

4/5, Resurvey after repair

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date: