

**BIKE PRODUCTION PTE LTD**  
610, Serangoon Road S(218216)  
Tel: 63922555, 62995177 Fax: 62975400  
**ROC/ GST Reg No.: 200007407G**

Date: 9 Dec 2021

**ASSESSMENT FOR REPAIR: YAMAHA SNIPER T150 - FBN588Z**

Chassis No.:

Engine No.:

<b><u>Qty</u></b>	<b><u>Description</u></b>	<b><u>Estimate</u></b>
1 pc	Front disk	\$115.00
1 pc	Front wheel axle	\$75.00
1 pc	Right fork assembly	\$380.00
1 pc	Left fork assembly	\$380.00
1 pc	Front headlamp lower cover	\$105.00
1 pc	Headlamp lower assy	\$250.00
1 pc	Front mudguard	\$85.00
2 pcs	Steering stem bearing @ \$45.00	\$90.00
1 pc	Steering stem bracket assembly	\$195.00
1 pc	Handle bar	\$125.00
1 pc	Right fairing	\$105.00
1 pc	Left fairing	\$105.00
2 pcs	Fairing stickers @ \$55.00	\$110.00
1 pc	Right front signal	\$65.00
1 pc	Brake pedal assy	\$75.00
1 pc	Right balancer	\$45.00
1 pc	Front footrest holder assembly	\$145.00
1 pc	Left clutch lever	\$45.00
1 pc	Left balancer	\$45.00
1 pc	Left engine cover	\$195.00
1 pc	Left engine cover gasket	\$45.00
1 pc	Gear pedal assy	\$145.00
1 pc	Center basket	\$30.00
1 pc	Left rear side cover	\$105.00
1 pc	Left rear side cover sticker	\$45.00
1 pc	Left front foot rest	\$55.00
1 pc	Left rear footrest	\$45.00
1 pc	Mainstand	\$125.00
1 pc	Left rear signal	\$55.00
1 pc	Meter assy	\$245.00
1 pc	Center H cover	\$75.00
1 pc	Exhaust long cover	\$95.00
		<hr/>
		\$3,800.00
	Less discount 10%	\$380.00
		<hr/>
		\$3,420.00
	<b><u>Special nett items</u></b>	
1 pc	Engine oil	\$35.00
1 pc	Front sport rim assy	\$350.00

1)	Towing charges	\$100.00
2)	Dismantle, replace, realign and adjust above damaged parts	\$700.00

4)	To knock, straighten chassis & body balancing	\$380.00
5)	To remove/refit, replace (if damage) check and straighten front fork tubes	\$180.00
6)	To remove/refit and balance front sport rim	\$90.00
7)	Spray painting	\$300.00
<b>Total Estimate</b>		<u><u>\$5,555.00</u></u>

**Note: The above estimate is subjected to the prevailing GST of 7%**

---

For Bike Production Pte Ltd